

ABU DHABI AVIATION ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES
WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L NO.	

NOMENCLATURE							PART NO.		204-012-101-153GFM		SERIAL NO.		ADA-01007							
MANUFACTURER							CARD No10					RETIREMENT TIME (If Applicable)			OVERHAUL INTERVAL			2400 HOURS		
INSTALLATION DATA										REMOVAL DATA										
DATE		INSTALLED ON ACFT/EQUIP		BY	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS		DATE	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS		REASON FOR REMOVAL								
		TYPE	ACFT/EQUIP			SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H									
15-Mar-15		212	A6-BAC	ADA	15228:35	18862:24	1840:00	05 APR 2018	15713:40	19347:29	2325:05	DUE OVERHAUL								
22 JAN 19		212	AG-BBV	ADA	19590:45	19347:29	0:00	22 JAN 21	19621:10	19377:54	30:25	TT STRAP REPLACEMENT								
						19377:54	751 0:00													

TECHNICAL DIRECTIVES				
TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DATE	JOB No.
FAA AD 2014-12-04 Para 3 & 4	11-Mar-15	M/R grip Ultrasonic inspection c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-02-116 Rev A	11-Mar-15	M/R grip Ultrasonic inspection c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-02-59 & FAA AD 90-26-11	11-Mar-15	Drag Brace MPI c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-02-117	11-Mar-15	1200 hour of Hub pins c/out.	11-Mar-15	ADA -OH18406-R
TB-212-99-170	11-Mar-15	Previously complied with.	11-Mar-15	ADA -OH18406-R
ASB 212-94-94	11-Mar-15	1200 hour inspection of M/R yoke carried out.	11-Mar-15	ADA -OH18406-R
ASB 212-94-92 Rev A	11-Mar-15	M/R grip conditional inspection c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-10-142 Rev B	11-Mar-15	Inboard strap fitting MPI c/with.	11-Mar-15	ADA -OH18406-R
ASB 212-12-144	11-Mar-15	M/R Grip inspection and rework C/out.	11-Mar-15	ADA -OH18406-R
FAA AD 2013-03-16	11-Mar-15	Inboard strap fitting MPI c/with.		
FAA AD 2014-12-04 PARA 4	03 APR 17	M/R GRIP ULTRASONIC INSP. C/OUT.	03 APR 17	BAC-000228

CARD NO. **U/PARA 3**

PERMANENT F

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (SPECIFY)	TSN	REPAIR STATION	REMARKS AND MAJOR PART REPLACED	W/O #
11-Mar-15	REPAIR	18862:24	ADA OH18406R	1200 hour/24 month inspection c/out IAW BHT-212-CR&O Rev.9-- TT Straps LPFS-27985/27602 replaced by LPFS-33723/33745. Drag Brace A-599/A-603 replaced by A-350/A1-07403.	OH18406-R
20 MAR 15 18 MAY 16	INSP INSP	18862:24 18998:10	BAC-000044/0016 BAC-000169/79	6 MTH INSP. C/OUT. 6 MTH INSP. C/OUT.	MOOH FAASA
03 APR 17	REPLACE	19113:24	BAC-000228	TT STRAPS LPFS 33745 & LPFS 33723 REPLACED BY S/N: LPFS 36061 & LPFS 36063	FAASA
10 APR 17 27 SEP 17	INSP INSP	19113:24 19265:24	BAC-000228 BAC-000233	6 MTH INSP C/OUT. 6 MTH INSP. C/OUT	FAASA. MO75
03 OCT 18	O/H	19347.29	OH 21464-0	Overhauled IAW BHT 212 CR&O R10. M/R Strap Pins S/N DIFS17958, DIFS17971, DIFS18004, DIFS18089 replaced by S/N DIFS20711, DIFS20969, DIFS20900, DIFS20552. Bushings S/N BT10363, BT10437, BT10438, BT10505 replaced by S/N DI22279, DI22182, DI21833, DI22185. TT Strap S/N LPFS36061, LPFS36063 replaced by S/N LPFS36305, LPFS36307. Pitch Horn S/N MWFS632, MWFS809 replaced by S/N REFS3542, REFS3526.	OH-06
				ASB 212-02-116 Rev A, FAA AD 2014-12-04, ASB 212-90-59 (FAA AD 90-26-11), TB 212-99-170, ASB 212-10-142 Rev B Part 1 and Part 2, FAA AD 2013-03-16 Complied With. ASB 212-94-94, ASB 212-94-92 Rev. A, ASB 212-15-152 Previously Complied With.	
22 JAN 19	INSP.	19347.29	BBV-000211/0110	6 MTH INSP. C/OUT.	M-011
10 JUN 2021	INSP	19377:54	OH 23439-R	1200 HR / 24 MTH INSP C/O IAW BHT-212-CR&O, REV.13. TT STRAPS S/N LPFS 36305 & LPFS 36307 REPLACED BY S/N LPFS 38633 & LPFS 38616.	ADA TRM OH 06.

ABU DHABI AVIATION

ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES
WHEN THE ITEM IS INSTALLED. THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

CARD NO. 9

P/L No. GRN No.

NOMENCLATURE MAIN ROTOR HUB ASSY

PART NO. 204-012-101-~~029~~¹⁵³ GFM

SERIAL NO. ADA-01007

MANUFACTURER

RETIREMENT TIME (If Applicable)

OVERHAUL INTERVAL 2400 HRS.

INSTALLATION DATA

REMOVAL DATA

DATE	INSTALLED ON AIRCRAFT		BY	HRS / LDS TOTAL ACFT./EQUIP	COMP. HOURS / LDGS		DATE	TOTAL ACFT./EQUIP HRS / LDGS	COMP. HOURS / LDGS		REASON FOR REMOVAL
	TYPE	REG. NO.			SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
31 JAN 05	212	EP-NAG	ADA	15254.50	16378.67	1391.00	30 Oct 05	15850.67	16974.83	1987.17	Grip NDT insp & buffe
02 Nov 05	212	A6-BBC	ADA	30149.92	16974.83	1987.17	18 FEB 06	30197.50	17022.42	2034.75	A/C UNDERGOING MAJOR INSP
29 Mar 06	212	A6-BBC	ADA	30200.67	17022.42	0.00	24 Jun 07	30720.42	17542.17	519.75	TT straps due retire
10 Jul 07	212	A6-BBC	ADA	30720.42	17542.17	519.75	21 Mar 08	31212.25	18034.00	1011.58	Sub-Assy RT.
23 May 08	212	A6-BBL	ADA	24326.17	18034.00	1011.58	30 Jun 09	24833.17	18541.00	1518.58	TT Strap due RT
29 AUG 2009	212	A6-BBC	ADA	31759.83	18541.00	1518.58	12 Apr 11	31930.00	18701.17	1678.75	ASB 212-10-142 Rev A comp
27 Jul 11	212	A6-BBS	ADA	24362.67	18701.17	1678.75	31 Jul 11	24364.58	18703.08	1680.67	vibration.
15.4.12	212 RAC	P2-HFV	Helifix	15224.0	18703.08	1680.67	19/09/12	15224.0	18860.78	1839.45	Removed for ops
19/09/12	212 BRW	P2-HFP	Helifix	18028.9	18860.78	1839.45	22/01/13	18030.0	18861.88	1839.47	Removed for ops
18 JAN 13	212 RAC	P2-HFV	Helifix	15224.0	18861.98	1839.59	11 FEB 14	15224.25	18862.24	1839.78	1840.51

TECHNICAL DIRECTIVES

TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DONE BY
ASB 212-02-116 Rev. A	17022.42	ASB 212-02-116 Rev.A complied with. (Ultrasonic insp. of MYR Grips).	OH-10697-O OH-12
ASB 212-02-117	17022.42	ASB 212-02-117 complied with. (1200 Hrs Special Insp. for Pin)	
FAA AD2003-01-04 Pt C	17542.17	Ultrasonic inspection of grips complied with.	WS OH 11995R
	18034.00	AD 2003-01-04 (ASB 212-02-116 Rev.A), AD 90-26-11 (ASB 212-90-59), AD 79-20-05, ASB 212-02-117, ASB 212-94-94, ASB 212-94-92 Rev.A and TB 212-99-170 PCW.	WS OH 12818R
	18701.17	FAA AD 2003-01-04 (ASB 212-02-116 REV.A), FAA AD 90-26-11 (ASB 212-90-59), ASB 212-02-117, ASB 212-94-94, ASB 212-94-92 Rev.A., ASB 212-10-142 Rev.B (FASAAD 2010-0246R1, FAA AD 2011-08-01) Complied With. TB 212-99-170 Previously complied with.	WS OH 15643-R

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (Specify)	TSN	REPAIR STATION	REMARKS AND MAJOR PART REPLACED	SIGNATURE AUTHORISATION
15JAN05	REPAIR	16378.67	ADA WS OH-9441-R	REPAIRED C/O IAW BHT-212-CR&O. M/R GRIP ULTRASONIC INSP. C/OUT. PITCH HORN S/N REFS-2201, REFS-2214 REPLACED BY S/N MWS-809, MWS-632. INB. STRAP FITTING S/N A-5709, A-5715 REPLACED BY S/N A-7841, A-7816. FISHINGS S/N DI-21016, DI-21262, DI-21852, DI-21936 REPLACED BY S/N BT-10363, BT-10438, BT-10505, BT-10437.	OH 04 / OH
03FEB05 03AUG05 31Oct05	INSP. INSP. Insp	16378.67 16776.58 16974.83	ADA WS 600/2NAG05 ADA WS03085NAG01 ADA OH 10352R	6 MONTHLY INSPECTION CARRIED OUT. 6 MONTHLY INSPECTION CARRIED OUT. Grip NDT inspection and ADB 212-02-116 Rev A carried out.	6330802 5880317 M 004
01Nov05 05DEC05 28Mar06	Insp. INSP Overhaul	16974.83 16996.83 17022.42	WS 26105BC01 WS 03125BC01 WS OH-10697-O	6Mth insp. c/out. 6 month inspection carried out. Overhauled iaw BHT-212-CR&O Revision No. 5.	M 004. M 021 OH 12
06May06	Insp.	17024.17	WS 06056BC46	TT Strap S/N LPFS-18033, LPFS-18034 replaced by S/N LPFS-19559, LPFS-20186. Strap Pin S/N DIFS-14804, DIFS-14884, DIFS-14934, DIFS-14965 replaced by S/N DIFS-17958, DIFS-17971, DIFS-18004, DIFS-18089.	M 025
29Oct06 27Jun07	insp. Repair	17210.33 17542.17	WS 18104BC98 WS CH 11995R	6 monthly inspection carried out. TT straps S/N LPFS-19559/LPFS-20186 replaced by LPFS-20624/20610. Ultrasonic current insp c/out on M/R grips.	M 012 OH -01
10Jul07 08Feb08 13Apr08	Insp. Insp Insp.	17542.17 17979.33 18034.00	WS 28057BC03 WS 080208BC26 WS OH-12818R	6 Mth insp. c/out. 6 mth inspection c/out. 1200 Hrs/24 Mths Inspection carried out IAW BHT 212 MM Ch. 5 Rev 8 & 212 CR&O Rev 6. Outboard Fittings A-15657, A-16020 replaced by A-17700, A-17749. AD 2003-01-04 (ASB 212-02-116 Rev A); AD 90-26-11 (ASB 212-90-59); ASB 212-94-94; ASB 212-94-92 Rev. A; ASB 212-02-117; AD 79-20-05 complied with and TB 212-99-170 previously complied with.	M 011 M 022 OH 11
20Jul08 21Jan09	Inspect Insp.	18153.17 18446.08	WS 010708BL23 WS 190109BL69	6 month inspection c/out. 6 Mth insp. c/out.	M 027 M 022
20Jul09	Insp	18541.00	WS OH 14258R	1200hr/24mth insp C/out iaw BHT 212-MM Chap 5 Rev 9 and 212 CR&O Rev. 7. TT strap LPFS-20610/20624 replaced by LPFS-22970/22781. Inbd fittings S/N A-7841/7816 replaced by A-3960/8995.	OH 11
23Aug09 23Feb10 29Aug10	Insp. Insp. Insp.	18541.00 18610.33 18621.50	WS 070309BC29 WS 270210BC96 WS 280810BC50	6 mth insp. c/out. 6 mth insp. c/out. 6 mth insp. c-out.	M 047 M 010 M 048
27Jul11 27Jul11	Insp Insp	18701.17 18701.17	WS OH-15643-R WS 270711BS29	1200hr/24Mth insp c/out IAW BHT-212-CR&O Rev.9 & ASB 212-10-142 Rev.B C/with TT Strap S/N LPFS-22781, LPFS-22970 replaced by S/N LPFS-27985, LPFS-27602. 6 Mth insp c/out.	OH 11 M 083

COMPONENT NAME M/R HUB ASSY.
PART NUMBER 204-012-101-029G
SERIAL NUMBER ADA-01007
PAGE 9A OF

HISTORICAL SERVICE RECORD - CONTINUATION SHEET

[illegible]

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	TOTAL TIME (HRS)	REMOVAL DATA	
		DATE Assy HRS	ACCUMULATED TIME ON ASSEMBLY OR PART		DATE Assy HRS		ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: STRAP PIN ASSY	DIFS-5102	11277.17	568.58	-	2400	18973.42	4264.83	TIMEX
	DIFS-5306	11277.17	568.58	-	2400			
NO.: 204-012-104-005	DIFS-5346	11277.17	568.58	-	2400			
	DIFS-5380	11277.17	568.58	-	2400			
NAME: OUTBOARD FITTING	A-437	11277.17	655.33	-	3600	11775.75	3552.58	HI TIME
NO.: 204-012-103-005	A-448	11277.17	655.33	-	3600	11775.75	3552.58	HI TIME
NAME: PITCH HORN	RE-4378	11277.17	1886.83	-	3000	12381.58	2991.25	TIMEX
NO.: 204-011-120-005	RE-4447	11277.17	1886.83	-	3000	12381.58	2991.25	TIMEX
NAME: T/T STRAPS	LKFS-3806	11277.17	648.33	-	1200/2 Years	11775.75	1146.92	HI TIME
NO.: 204-310-101-101	LKFS-3832	11277.17	648.33	-	1200/2 Years	11775.75	1146.92	HI TIME
NAME: pitch horn	REFS-1093	15.11.97	2792.67	403.67	3000	13472.25	2994.17	TIMEX
NO.: 204-011-120-005	REFS-1121	13270.75			3000	13472.25	2994.17	TIMEX
NAME: PITCH HORN	TKFS-29	13472.25	2381.50	-	3000	14081.17	2990.42	TIMEX
NO.: 204-011-120-005	TKFS-214	030198	2381.50	-	3000	14081.17	2990.42	TIMEX
NAME: PITCH HORN	REFS-2201	191198	570.75	-	3000	16378.67	2868.25	TIMEX
NO.: 204-011-120-005	REFS-2214	14081.17	570.75	-	3000	16378.67	2868.25	TIMEX
NAME: T/T STRAPS	LPFS-9869	14143.50	NIL	-	1200/2 years	14371.08	227.58	Cal Timex
NO.: 204-310-101-101	LPFS_9877	14143.50	NIL	-	1200/2 years	14371.08	227.58	Cal Timex
NAME: I/B FITTINGS	A-5709	14143.50	NIL	-	2400	16378.67	2235.17	HIGH TIME
NO.: 2120010-103-007	A-5715	14143.50	NIL	-	2400	16378.67	2235.17	HIGH TIME
NAME: M/R GRIP ASSY	* LL-0198	14143.50	15151.67	0.0	1200/2 years	14370.58	15378.75	227.08
204-011-121-009G *								
204-011-121-121G	A-5347	14370.58	3019.25	651.50		14370.58	3019.25	651.50

COMPONENT NAME MAIN ROTOR HUB
PART NUMBER 204-012-101-294
SERIAL NUMBER ADA - 01007
PAGE 7A+8A OF

HISTORICAL SERVICE RECORD - CONTINUATION SHEET

[illegible]

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	TOTAL Assembly TIME (HRS)	REMOVAL DATA	
		DATE AIRCRAFT HRS	ACCUMULATED TIME ON ASSEMBLY OR PART		DATE AIRCRAFT HRS		ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: DRAG BRACE.	A.599 ✓	10103:40	NK	00:00	RETURN TO ASSEMBLY LOG			
NO.: 204-011-140-005	A.603 ✓	10103:40	NK	00:00	CARDS FOR O/H DETAILS			
NAME: MR GRIP.	511-36078	9419:15	NK	00:00		11043.92	NK	1624.67
NO.: 204-011-121-009.								
NAME: BUSHING.	BT-591 ✓	10103:40	NEW	00:00		12973.42	2869.75	TIME
NO.: 204-011-135-105	BT-413 ✓	10103:40	NEW	00:00				
NAME: BUSHING	BT-59 ✓	10103:40	NEW	00:00				
NO.: 204-011-135-105	BT-82. ✓	10103:40	NEW	00:00				
NAME: PITCH HORN ASSY	CH-163	11043.92	2536.00	0.0	3000	11277.17	2905.08	-
NO.: 204-011-120-005	REFS-135	11043.92	2671.83	-	3000	11277.17	2769.25	-
NAME: INBOARD FITTING	A-3503	11043.92	2080.33	-	2400	11277.17	2313.58	-
NO.: 212-010-103-007	A-3507	11043.92	2080.33	-	2400	11277.17	2313.58	-
NAME: STRAP PIN ASSY	VT-11779	11043.92	2080.33	-	2400	11277.17	2313.58	-
	VT-12464	11043.92	2080.33	-	2400	11277.17	2313.58	-
NO.: 204-012-104-005	VT-12471	11043.92	2080.33	-	2400	11277.17	2313.58	-
	VT-12499	11043.92	2080.33	-	2400	11277.17	2313.58	-
NAME: T.T. STRAP ASSY	BNFS-46420	11043.92	884.42	-	1200/2 Yrs	11277.17	1117.67	-
NO.: 204-012-122-005	BNFS-46565	11043.92	884.42	-	1200/2 Yrs	11277.17	1117.67	-
NAME: M/R GRIP ASSY	LL-0860	11043.92	NK	0.0		11775.75	-	731.83
NO.: 204-011-121-009 RRG	5278-9	11043.92	13863.67	0.0		11775.75	-	731.83
NAME: I/B FITTING	A-2950	11277.17	1745.42	-	2400	11775.50	2244.00	NI TIME
212-010-103-007	A-3608	11277.17	1745.42	-	2400	11775.50	2244.00	NI TIME

REFER TO INDIVIDUAL LOG CARDS FOR SUBASSEMBLIES
COMPONENT NAME **MAIN ROTOR HUB ASSY**

PART NUMBER **204-012-101-029GFM**

SERIAL NUMBER **ADA-01007**

PAGE **8** OF

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

INSTALLATION DATA						A / C HOURS SCH. FOR ☒ O / H ☐ RETIRE X HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A / C NO.	BY (ACTIVITY)	INSTALLED AT A / C HRS.	COMP. HRS.			DATE	REMOVED AT A / C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O / H				SINCE NEW	SINCE O / H	
16-11-00	A6-BBS	ADA	17351.92	14311.00	167.50		2400 1200	131200	17411.50	14370.58	227.08
290301	A6-BBK	ADA	22100.08	14370.58	227.08		280301	22100.58	14371.08	227.58	I/T Str x Cal.
090401	A6-BBY	ADA	14252.50	14371.08	227.58		20Aug02	14869.08	14987.67	844.17	Trunnion Timex
28Mar03	A6-BBA	ADA	24343.67	14987.67	0.0		14Nov03	24562.17	15206.17	218.50	RTS BAB
14Nov03	A6-BAB	ADA	15949.75	15206.17	218.50		03Mar04	16523.33	15779.75	792.08	Ops Rec
10Apr04	A6-BBS	ADA	20140.75	15779.75	792.08		05 AUG.04	20420.67	16059.67	1072.00	1200HR/24 INSP.
08 AUG.04	A6-BBS	ADA	20420.67	16059.67	1072.00		31DEC04	20739.67	16378.67	1391.00	IB STRAP & TNG PL-TTN

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
	14371.08	Replaced I/T Straps. Drag Braces & Yoke 1200 Hr/24 Mth Insp C/O IAW		
		ASB 212-90-59 & ASB 212-94-94.	ADA WS OH 6231R	29Mar01
AD 2003-01-04		(M/R GRIP) COMPLIED WITH.	TS 212/014	190103
	14987.67	Overhauled iaw Bell 212 CR & O manual/Form ADA/OH/212/01 REV 1 Nov 02		
		Tech. Dir. c/o : ASB 212-02-116, ASB 212-02-117 and AD 2003-01-04.	OH 006	23FEB03
ADA WS 600/3AB03	15206.17	6 Monthly Inspection Carried Out. ASB 212-02-116 Rev A Complied With.	M 085 & M 004	15Nov03
WS OH 8935-R	16059.67	6 MONTH INSP. C/O. - ASB 212-02-116 REVA C/O. - TT STRAP SNOS. LPFS-15376 & LPFS15590	OH 12 & OH 04	07 AUG.04
		REPLACED BY SNOS.:LPFS 18031 & LPFS 18033/ STRAP PIN SNOS. DIFS-14934,DIFS-14965,DIFS-14804, DIFS-14884 .(1200 HR. INSP. C/O.) - DRAGBRACES SN. A-599 & A-603 NDT C/O._ GRIP ASSY SN.*		
		A-6014 & A-6015 1200 HR INSP. C/O. - ASB212-02-117 C/W.		
		1200 hr./24 mths. insp. carried out		

[illegible]

COMPONENT NAME MR HUB ASSY
 PART NUMBER 204-012-101-029G FM
 SERIAL NUMBER ADA-01007
 PAGE 7 OF

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

	T.T. STRAPS (CAL.)

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A / C NO.	BY (ACTIVITY)	INSTALLED AT A / C HRS.	COMP. HRS.			DATE	REMOVED AT A / C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O / H				SINCE NEW	SINCE O / H	
12-2-96	A6- BBK	ADA	20768.08	11775.75	0.0		3.7.96	20872.00	11879.67	103.92	INSP & EVALUATION
11.9.96	A6- BBL	ADA	17488.83	11879.67	103.92		31.7.97	18582.58	12973.42	1197.67	TT STRAPS
30.8.97	A6- BBU	ADA	10468.75	12973.42	1197.67		13.4.98	11332.17	13836.83	2061.08	7MAY98
240998	A6- BBC	ADA	26635.25	13836.83	2061.08		081298	26941.92	14143.50	2367.75	Overhaul
060599	A6- BBW	ADA	11345.42	14143.50	0.0		27Mar2000	11427.25	14225.33	81.83	10MAY99
1MAY00	A6- BBA	ADA	23967.75	14225.33	81.83		10Aug2000	24053.23	14312.39	168.89	TRUNION EXCEEDS RIN PER AD 2000-15-52
1MAY00	A6- BBA	ADA	23967.75	14225.33	81.83		10AUG00	24053.42	14311.00	167.50	AD/ASB

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		Overhauled iaw BHT CR&O manual. TSN 11775.75, TSO 0.0	ADA OH-224	110ct95
ASB 212-94-94	EQ 192A	MR Hub pitch change bearings - inner race replacement. (E-10-192 "B")	ADA OH-224	110ct95
W/S OH 285		Conditional inspection of M/R Hub Assy carried out IAW BHT 212 CR & O Manual chapter 62-20. (Overtorque above 112%) Sub Assy Items MPI & FPI Carried out. TSN 11879.67 TSO 103.92	ADA	080996
W/S 300/4BL97		600 Hr/6 Mth inspection carried out. TSN 12338.17	ADA	180197
W/S 2701BL02		Pitch Horns Replaced @ 12381.58 Assy TT see over for details	ADA	270197
WS OH-4021R		Midlife insp/replacement carried out. TSN 12973.42, TSO 1197.67	ADA	280897
W/S 0301BU02		Pitch Horns Replaced @ 13472.25 Assy TT. see cont sheet 2 for details	ADA	030198
W/S 300/9BU98		600 Hr inspection carried out. TSN 13576.17	ADA	300198
W/S 953		600 HR INSPECTION CARRIED OUT. TSN: 13836.83 TSO: 2061.08	ADA	290498

COMPONENT NAME	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	REMOVAL DATA		
		DATE	ACCUMULATED TIME ON ASSEMBLY OR PART			DATE	ACCUMULATED TIME ON ASSEMBLY OR PART	
PART NUMBER		COMPONENT HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	COMPONENT HOURS	ASSEMBLY HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: Trunnion	A-84		NEW	NEW				
NO.: 204-011-105-001		4625.17						
NAME: Yoke Assy	A-1156M		NEW	NEW				
NO.: 212-011-102-105		11775.75						
NAME: TT strap	BNFS-48188	11775.75	NEW	NEW	—	12973.42	1197.67	TIMEX
NO.: 204-012-122-005	BNFS-48192	11775.75	NEW	NEW	—	12973.42	1197.67	TIMEX
NAME: OB Fitting	A-13695	11775.75	NEW	NEW		23.2.03	3212.92	HI TIME
NO.: 204-012-103-005	A-13717	11775.75	NEW	NEW		14987.67		
NAME: IB Fitting	A-4110	11775.75	NEW	NEW		14143.50	2367.75	TIMEX
NO.: 212-010-103-007	A-4114	11775.75	NEW	NEW		14143.50	2367.75	TIMEX
NAME: Grip Assy	A-5347	11775.75	NEW	NEW		14143.50	2367.75	At O/H
NO.: 204-011-121-121G	A-5357	11775.75	NEW	NEW		14370.58	2594.83	227.08 RTS
NAME: Pillow Block	307770400493A	11775.75	NK	0.0				
NO.: 204-011-108-113	307770400493B	11775.75	NK	0.0				
NAME: PITCH HORN	REFS-798	12381.58	2080.83	—	3000 Hrs	15.11.97	2970.00	TIMEX
NO.: 204-011-120-005	REFS-844	12381.58	2080.83	—	3000 Hrs	13270.75		
NAME: Bushing	DI-21016	28 Aug 97	New	New		15JAN05	3405.25	HIGH TIME
NO.: 204-011-135-105	DI-21262	12973.42				16378.67		
NAME: TT strap	LPFS-8383	12973.42	New	New		14143.50	1170.08	TIMEX
NO.: 204-910-101-101	LPFS-8439	12973.42	New	New		14143.50	1170.08	TIMEX
NAME: PIN	DIFS-10358	28 Aug 97	New	New		23.2.03	2016.33	HI TIME
NO.: 204-012-104-005	DIFS-8797	12973.42				14987.67		

COMPONENT NAME MAIN ROTOR HUB ASY
 PART NUMBER 204-012-101-29G
 SERIAL NUMBER ADA-01007
 PAGE 6 OF

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

Overhaul (2400)	
NOTICE: WHEN RETURNING ANY LIMITED	
LIFE COMPONENT TO BHT FOR ANY	
16-04-95	T.T. Straps (Date)
THE COMPONENT	T.T. Straps (hours)

INSTALLATION DATA						A/C HOURS SCH. FOR ☒ O/H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.			DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
3-11-92	30777 (BC)	ADA	23326:40	9419:15	00:00	2400	25-3-92	24011:05	10103:40	684:25	Yoke Tires.
13-05-93	31227 (AB)	ADA	7287:55	10103:40	684:25		220594	8228.17	11043.92	1624.67	Op. Req.
12-6-94	30822 (BL)	ADA	14342.5	11043.92	1624.67		280794	14575.75	11277.17	1857.92	O/B Strap Fittings Time
201094	A6-BAB	ADA	8605.00	11277.17	1857.92		30-4-95	9103.58	11775.75	2356.50	T.T. STRAPS & DUE OVAL
				CONT'D ON PAGE NO. 7							

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
ASB 212-92-80		Pillow Block Inspection	ADA	5-4-93.
AD 93-05-01				
ADA WS 6764		Yoke, T.T. Straps, Drag Brackets Replaced Hub Inspected, No Assembly	ADA.	5-4-93
		BALANCED T.T. 10103:40 TSO 684:25		
ADA WS OH622		Rebond pillow block buffer pads. TSN 10241:05, TSO 821:50.	ADA/043	090793
ADA w/s OH1463		DISASSEMBLED, INSPECTED. GRIPS, PITCH HORNS, T.T. STRAPS, PINS (x4),	ADA/021	4-06-94
		I/B FITTINGS & BLADE BOLTS ALL REPLACED. RE-ASSEMBLED. @ 11043.92 HUB T.T.		
ASB 212-94-91		MAIN BLADE BOLTS RECALL - N/A BY S/N	WS 1406BL02	140694
EQ-159		Improved Inspectability-Detection of Cracks being masked by Sealant/		
		Paint. W/S OH 1656 TSN 11277.17	ADA	110894
W/S OH 1656		T/T Straps, O/B & I/B Fittings Strap Pins & Pitch Horns Replaced		
		TSN 11277.17 TSO 1857.92	ADA	110894

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL DATE COMPONENT HOURS	REMOVAL DATA		
		DATE COMPONENT HOURS	ACCUMULATED TIME ON ASSEMBLY OR PART			DATE AIRCRAFT HOURS	ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: 212-011-102-105 YOKE	A142 ✓	10103:40	00:00	—	11775.75	11775.75	1672.08	WARRANTY WORN SANDERS
NO.: 204-011-102-125	A. 256	8765:15	NEW	—		10103:40	2400:30	INCLUDING FACTOR
NAME: TRUNNION	A. 84 ✓							
NO.: 204-011-105-1		4625:10	NEW	—	XFER TO CARD NO. 7			
NAME: PITCH HORN	REFS. 860	8336:55	NEW	—		11043.92	2707.00	
NO.: 204-011-120-5	REFS. 650	8336:55	NEW	—		11043.92	2707.00	
NAME: TT STRAPS	BNFS. 46065	9419:15	NEW	—		10103:40	684:25	
NO.: 204-012-122-005	BNFS. 46182	9419:15	NEW	—		10103:40	684:25	
NAME: INBD FITTING	A. 3970	9419:15	NEW	—		11043.92	1624.67	
NO.: 212-010-103-7	A. 3951	9419:15	NEW	—		11043.92	1624.67	
NAME: 1/B SNAP PIN	EA. 1063	9419:15	NEW	—		11043.92	1624.67	
NO.: 204-012-104-005	EA. 5	9419:15	NEW	—		11043.92	1624.67	
NAME: 0/B SNAP PIN	EA. 1895	9419:15	NEW	—		11043.92	1624.67	
NO.: 204-012-104-005	EA. 614	9419:15	NEW	—		11043.92	1624.67	
NAME: DRAG BRACE	A1. 01836	9419:15	NK.	00:00		10103:40	NK	684:25
NO.: 204-011-140-005	A1. 09932	9419:15	NK	00:00		10103:40	NK	684:25
NAME: 0/B FITTING	A. 11209	7679:10	NEW	—		11277.17	3598.00	—
NO.: 204-012-103-005	A. 11814	7679:10	NEW	—		11277.17	3598.00	
NAME: TT STRAPS	BNFS-46179	10103:40	NEW	—		11043.92	940.25	—
204-012-122-005	BNFS-46184	10103:40	NEW	—		11043.92	940.25	—

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

[illegible]

HISTORICAL SERVICE RECORD

COMPONENT NAME MAIN ROTOR HUB ASSY.
PART NUMBER 204-012-101-29G
SERIAL NUMBER ADA-01007
PAGE 4 OF

6169-00	Overhaul (2400)
REASON IT IS MANDATORY THAT THIS SERVICE	
18-10-93	T.T. Straps (Date)
	T.T. Straps (hours)

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
200690	31189 (BV)	ADA	5293:55	7023:50	00:00	230790	5293:55	7023:50	0:0	RTS
230790	30794 (BH)	ADA	18047:15	7023:50	0:0	5.12.90	18702:35	7679:10	655:20	Yoke Time/TSN
080191	31180 (BT)	ADA	12061:45	7679:10	655:20	3.10.91	13145:25	8762:50	1739:00	Yoke High Time
181091	30773 (BA)	ADA	15600:45	8762:50	1739:00	031191	15603:10	8765:15	1741:25	Vibration
17.12.91	30783 (BE)	ADA	15693:25	8765:15	1741:25	290392	16135:25	9207:15	2183:25	RTS
070592	31189 (BV)	ADA	5952:25	9207:15	2183:25	21/6/92	6164:25	9419:15	2395:25	DUE OVERHAUL

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		Overhauled in accordance with Bell Component Repair and Overhaul Manual	D.A.A.S.	15 May 90
		T.T. 7023:50, T.S.O. 00:00 (Job No. 211938-2101)		
		T.B. 212-78-11, T.B. 212-86-94, AD 79-20-05, ASB 212-80-17, ASB 212-81-23,		
		ASB 212-87-43'A', ASB 212-87-44, ASB 212-87-48, ASB 212-89-55'A',		
		ASB 212-90-59, ADHM/212/85/36 compiled with.		
ADA WS NO. 911285		Yoke S/N EN-83047-6 REPLACED BY A-100. TT STRAPS LFWS 3005/3035	ADA	16.10.91
		REPLACED BY LFWS 3775/2852. ASB 212-90-59 CARRIED OUT. DNG BULBETS		
		AI-07624/07942 REPLACED BY AI-01836/09932		
ADA WS NO. Q.A. 91/29/9/10/91		T.T. STRAP PINS VERIFICATION ASB 212-91-68 SATISFIED	ADA	9.10.91
W/S NO: 911489		ASSY. DISASSEMBLED, Yoke S/N A-100 REPLACED BY S/N A-256 (TSN "NEW") ALONG	ADA	11.11.91
		WITH BEARINGS. HUB T.T. 8765:15, T.S.O. 1741:25 ASSY. REASSEMBLED.		
ADA WS No. 920444		MRH disassy/reassy (pillow block removal to repl seals & buffers. TSN 9207:15	ADA/EBP	06.0.92

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: Outbrd Strap Pin								
NO: 204-012-104-5	VT-8991 (R)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Outbrd Strap Pin								
NO: 204-012-104-5	VT-8983 (W)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Yoke								
NO: 204-011-102-125	EM-82812-5	4625:10	00:00	-	7679:10	3619:15	(Lifts inc)	3600
NAME: Pitch Horn								
NO: 204-011-120-5	RE-4133	5349.00	0.0	-	8336:55	2987:55	-	3000
NAME: Pitch Horn	REFS 860	8336:55	0:00	-				3000
NO: 204-011-120-5	RE-4346	5349.00	0.0	-	8336:55	2987:55	-	3000
NAME: Trunnion	REFS 650	8336:55	0:00	-				3000
NO: 204-011-105-1	A.84	4625.10	0.0	-				15000
NAME: TT Strap								
NO: 204-012-122-5	26560	5824.25	0.0	-	6604:50	780:25	(Cal tx)	1200 / 2 Yrs
NAME: TT Strap								
NO: 204-012-122-5	26562	5824.25	0.0	-	6604:50	780:25	(Cal tx)	1200 / 2 Yrs
NAME: TT STRAP	LKFS0842	6604:50	NEW	NEW	7679:10	1074:20	-	1200hr/2yrs
NO: 204-310-101-101	LKFS1167	6604:50	NEW	NEW	7679:10	1074:20	-	1200hr/2yrs
NAME: Inboard Strap Fitting	A-2800	7023:50	00:00	-	9419:15	2395:25		2400
NO: 212-010-103-7	A-2854	7023:50	00:00	-	9419:15	2395:25		2400
NAME: Inboard Strap Pin	EA-690	7023:50	00:00	-	9419:15	2395:25		2400
NO: 204-012-104-5	EA-960	7023:50	00:00	-	9419:15	2395:25		2400
NAME: Outboard Strap Pin	EA-1036	7023:50	00:00	-	9419:15	2395:25		2400
NO: 204-012-104-5	EA-1102	7023:50	00:00	-	9419:15	2395:25		2400
NAME: FITTING OUTBOARD	A-437	4625:10	00:00	-	7679:10	3054:00	(RTS)	2400 3600
NO: 204-012-103-5	A-448	4625:10	00:00	-	7679:10	3054:00	(RTS)	2400 3600
NAME: DRAG BRACE	A1-09390	NK	NK	NK	7679:10	NK		COND
NO: 204-011-140-5	A1-09405	NK	NK	NK	"	NK		COND

A Subsidiary of Textron Inc

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
BELOW IS RETURNED TO BHT. FOR ANY
REASON IT IS MANDATORY THAT THIS SERVICE
RECORD ACCOMPANY THE COMPONENT

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

[illegible]

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: PITCH HORN								
NO: 204-011-120-5	RE-2977	2358:30	00:00	-	5349.00	2990.30	(Timex)	3000
NAME: Yoke Assy.								
NO: 204-011-102-125	EM-82748-2	3475.05	0.0	-	4625:10	1150:05	-	3600
NAME: Outboard Fitting								
NO: 204-012-103-5	A1-28349	3475.05	2327.55	0.0	4625:10	3478:00	-	3600
NAME: Outboard Fitting								
NO: 204-012-103-5	A1-29574	3475.05	2327.55	0.0	4625:10	3478:00	-	3600
NAME: Retention Strap								
NO: 204-012-122-5	23447	3475.05	0.0	-	4625:10	1150:05	-	1200/2 Years
NAME: Retention Strap								
NO: 204-012-122-5	23454	3475.05	0.0	-	4625:10	1150:05	-	1200/2 Years.
NAME: T.T. Strap								
NO: 204-012-122-5	27244 (R)	4625:10	00:00	-	5824.25	1199.15	-	
NAME: T.T. Strap								
NO: 204-012-122-5	27254 (W)	4625:10	00:00	-	5824.25	1199.15	-	2400
NAME: Inboard Fitting								
NO: 212-010-103-7	A1475 (R)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Inboard Fitting								
NO: 212-010-103-7	A1486 (W)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Outboard Fitting								
NO: 204-012-103-5	A437 (R)	4625:10	00:00	-	X REFER TO CARD NO. 2		-	
NAME: Outboard Fitting								
NO: 204-012-103-5	A448 (W)	4625:10	00:00	-			-	
NAME: Inbrd Strap Pin								
NO: 204-012-104-5	VT-8888 (R)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Inbrd Strap Pin	VT-9046							
NO: 204-012-104-5	VT-8983 (W)	4625:10	00:00	-	7023:50	2398:40	-	2400

PAGE 2 OF



NOTICE: WHEN COMPONENT IDENTIFIED
BELOW IS RETURNED TO BHC. FOR ANY
REASON IT IS MANDATORY THAT THIS SERVICE
RECORD ACCOMPANY THE COMPONENT

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DATE _____

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: RETENTION STRAP								
NO: 204-012-122-5	11583	47.55	0.0	-	1172.05	1124.10	-	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	11684	47.55	0.0	-	1172.05	1124.10	-	1200/2 Years
NAME: TRUNNION								
NO: 204-011-105-1	A1-10634	47.55	0.0	-	4625.10	3577.15		
NAME: RETENTION STRAP								
NO: 204-012-122-005	20731	1172.05	0.0	-	2358:30	1186:25	-	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-005	20752	1172.05	0.0	-	2358:30	1186:25	-	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	21064	2358:30	00:00	-	3475.05	1116.35 (Timex)		1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	21075	2358:30	00:00	-	3475.05	1116.35 (Timex)		1200/2 Years
NAME: INBOARD STRAP FITTING								
NO: 212-010-103-7	A-244	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: INBOARD STRAP FITTING								
NO: 212-010-103-7	A1-05294	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: INBOARD STRAP PIN								
NO: 204-012-104-5	DI-2589	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: INBOARD STRAP PIN								
NO: 204-012-104-5	PB-7793	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: OUTBOARD STRAP PIN								
NO: 204-012-104-5	PB-6881	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: OUTBOARD STRAP PIN								
NO: 204-012-104-5	DI-3786	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: PITCH HORN								
NO: 204-011-120-5	RE-2378	2358:30	00:00	-	5349.00	2990.30 (Timex)		3000

HISTORICAL SERVICE RECORD

COMPONENT NAME M/R HUB ASSEMBLY
 PART NUMBER 204-012-101-29 G
 SERIAL NUMBER ADA-01007
 PAGE 1 OF

NOTICE: WHEN COMPONENT IDENTIFIED
 BELOW IS RETURNED TO BHT. FOR ANY
 REASON IT IS MANDATORY THAT THIS SERVICE
 RECORD ACCOMPANY THE COMPONENT

SERIAL NUMBER

PAGE 1 OF

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
2-21-80	32123	BHT	0.0	0.0	0.0	30/1/82	47.55	47.55	-	Tension/Torsion Straps Time Ex.-Cal.
2.5.82	30651	ADH	3272.20	47.55	-	15.6.83	4174.45	950.20	-	With U/S Blade
3.7.83	30783	ADH	5782.45	950.20	-	14.10.83	6004.30	1172.05	-	Grip Seals Leaking
23.10.83	30777	ADH	9862.05	1172.05	-	23.7.84	11048.30	2358.30	-	Retention Straps Timex & Overhaul
19.9.84	30777	ADH	11341.30	2358:30	00:00	20.9.84	11342.20	2359.20	0.50	Unable to track
21.9.84	30776	ADH	12422.05	2359.20	0.50	21.6.85	13537.50	3475.05	1116.35	Yoke + others Time-
14.7.85	32123	ADH	5260.10	3475.05	1116.35	18.11.85	5748.50	3963.45	1605.15	Lateral Vibration.
18.11.85	30903	ADH	10552.15	3963.45	1605.15	6.4.86	11133.45	4545.15	2186.45	To Service 30822
6.4.86	30822	ADH	6645.45	4545.15	2186.45	1.5.86	6725.40	4625.10	2266.40	Due Overhaul.
25.10.86	30779	ADH	12312.55	4625:10	00:00	10.8.87	13512.10	5824.25	1199.15	T/T Straps Timex

UNION DIRECTIVES AND HISTORY OF OVERHAUL

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
W/S No.89/82		Static Balance check carried out after trunnion change. TT 47.55	ADH	2.22.82
		Overhauled in accordance with Bell Component Repair and Overhaul Manual	Fas Orient	28 Aug 84
		T.T. 2358:30 , T.S.O. 00:00 (Job No. S68078).	(Pte.) Ltd.	
		T.B. 212-78-11, T.B. 212-81-56'A', ASB 212-80-17, ASB 212-81-23 and F.A.A.	Singapore.	
		A.D. 79-20-05 Amendment 39-3662 complied with.		
		NOTE : Assembly serviced with Aeroshell Grease 22C.		
W/S 265/85		ASB.212-85-37 "A" Complied with. Grip S/Ns. GD.9456-11/GD.9449-3 TT 29	ADH	13.2.85
		Overhauled in accordance with Bell Component Repair and Overhaul Manual	Fas Orient	3 Oct '86
		T.T. - 4625:10, T.S.O. - 00:00 (Job No. 210046-2101).	(Pte) Ltd.,	
		T.B. 212-78-11, ASB 212-80-17, ASB 212-85-37'A', ADHM/212/85/36, OSN 212-85-13	Singapore Fas	
		and T.B. 212-86-94 complied with.		
		Hub Assembly serviced with Aeroshell Grease 22C.		

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: INBD STRAP FITTING								
NO: 212-010-103-7	A1-05973	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: INBD STRAP FITTING								
NO: 212-010-103-7	A1-05926	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: OUTBD STRAP FITTING								
NO: 204-012-103-5	A1-27855	0.0	0.0	0.0	3475.05	3475.05	(Timex)	3600
NAME: OUTBD STRAP FITTING								
NO: 204-012-103-5	A1-29004	0.0	0.0	0.0	3475.05	3475.05	(Timex)	3600
NAME: RETENTION STRAP								
NO: 204-012-122-5	2452	0.0	0.0	0.0	47.55	47.55	Time Ex Calendar	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	2558	0.0	0.0	0.0	47.55	47.55	Time Ex Calendar	1200/2 Years
NAME: STRAP PIN								
NO: 204-012-104-5	VT2171	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	VT1970	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	VT2118	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	VT1130	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: PITCH HORN								
NO: 204-011-120-5	RE1329	0.0	0.0	0.0	2358:30	2358:30	-	3000
NAME: PITCH HORN								
NO: 204-011-120-5	RE0720	0.0	0.0	0.0	2358:30	2358:30	-	3000
NAME: YOKE								
NO: 204-011-102-125	GD 9020-5	0.0	0.0	0.0	3475.05	3475.05	(Timex)	3600
NAME: Trunnion								
NO: 204-011-105-1	A1-09691	0.0	0.0	0.0	47.55	47.55	Eccentric	