ABU DHABI AVIATION
ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES

WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L NO.	GRN

CARD 10

NOMENCLATURE	M/R HUB ASSEMBLY	PART NO.	204-012-101-153GFM	SERIAL NO.	ADA-01237
MANUFACTURER	BHT	RETIREMENT TIME (If Applicable)		OVERHAUL INTERVAL	2400 Hour

INSTALLATION DATA

DATE	INSTALLED ON AIRCRAFT		BY	TOTAL HRS/LDS	COMP. HOURS/LDGS	
	S/N	REG. NO.		ACFT/EQUIP	SINCE NEW	SINCE O/H
					18295:38	0:00

REMOVAL DATA

DATE	TOTAL HRS/LDS	COMP. HOURS/LDGS		REASON FOR REMOV/
	ACFT/EQUIP	SINCE NEW	SINCE O/H	

TECHNICAL DIRECTIVES

TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DATE	WORKSHEET/GRN
ASB 212-02-116 Rev A	10-Dec-20	M/R Grips 204-011-121-009 and -121, Ultrasonic Inspection of - C/WITH.	10-Dec-20	OH22843-O
FAA AD 2014-12-04	10-Dec-20	M/R Grips 204-011-121-009 and -121, Inspection of - C/WITH.	10-Dec-20	OH22843-O
FAA AD 90-26-11	10-Dec-20	Drag Brace Assy 204-011-140-003, -005, Magnetic Particle Inspection - C/WITH.	10-Dec-20	OH22843-O
TB 212-99-170	10-Dec-20	Improved Pitch Horn to Main Rotor Grip Attachment Hardware - C/WITH.	10-Dec-20	OH22843-O
ASB 212-94-94	10-Dec-20	1200 Hr Yoke Inspection - C/WITH.	10-Dec-20	OH22843-O
ASB 212-94-92 Rev A	10-Dec-20	Overhaul and Conditional Insp Requirements, M/R Grip - C/WITH.	10-Dec-20	OH22843-O

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (SPECIFY)	TSN	REPAIR STATION & WORK ORDER	REMARKS AND MAJOR PART REPLACED	DONE BY/GRN
10-Dec-20	O/H	18295:38	OH22843-O	Overhaul carried out IAW BHT-212-CR&O REV 12. Inboard Fittings S/N's: A-8983, A-9108 replaced by S/N's: A-9156, A-8994. Strap Pins S/N's: DIFS-20054, DIFS-20291, DIFS-20241, DIFS-20056 replaced by S/N's: DIFS-20814, DIFS-20685, DIFS-20899, DIFS-20956. Pillow Block Bushings S/N's: BT-8330, BT-8292, BT-8291, BT-8179 replaced by S/N's: DI-22073, DI-21975, DI-22250, DI-21883. Pillow Blocks S/N's: 30794060693A, 30794060693B replaced by S/N: TI-4, TI-44. TT Straps S/N's: LPFS35465, LPFS35469 replaced by S/N's: LPFS38503, LPFS38507. Blade Bolts S/N's: FWFS-252, FWFS-291 replaced by S/N's: FWFS808, FWFS341.	OH 11
04-Jan-21	REPLACED	18295:38	OH23346-R	Blade Bolt S/N: FWFS341 replaced by FWFS861 iaw BHT-212-CR&O REV. 12.	OH 06

DESCRIPTION: M/R HUB ASSY
PART NUMBER: 204-012-101-029 GFM
SERIAL NUMBER: ADA-01237
9 OF

Helifix Engineering Ltd
Portion 1536, Jacksons Parade,
Jacksons International Airport,
Port Moresby 121, NCD, PNG

NOTICE: When returning any limited life components to BHTC/BHTI for any reason, it is mandatory that a valid historical service record accompany the component.

2400 HR O/H 1200 HR INSP

HISTORICAL SERVICE RECORD.

INSTALLATION DATA						OH✓ INSP RETIRE.	REMOVAL DATA					
DATE	INSTALLED ON A/C #	BY ACTIVITY	INSTALLED AT A/C Hrs A/C RIN	COMPONENT HOURS/RIN SINCE NEW COMP HRS RIN	SINCE OH COMP HRS	Due OFF @ A/C TTIS Other	DATE	REMOVED AT A/C Hrs A/C RIN	COMPONENT HOURS/RIN SINCE NEW COMP HRS RIN	SINCE OH COMP HRS RIN	REASON
09-Nov-13	P2-HFT	HELIFIX	19,035.10	17,354.80	1,457.90	19,977.20		19165:06	17484:48	1587:54	DUE O/H.
14 APR 18	N21225	BDS	16977:10	17484:48	1587:54		3 Mar 20	17788:00	~~2398:45~~ 18295:38	2398:45	DUE O/H. STRAP PINS Retention straps R

CONTINUE TO ~~NEXT PAGE~~ 10

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL.

DIRECTIVE # IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
	17,354.80	TT-STRAPS S/N: LPFS-28005 & LPFS-27424, Replaced by TT-Straps S/N: LPFS-31911 & LPFS-31873, OUTBRD Fittings S/N: A-14554 & A-14556, Replaced by S/N: CQ-73 & CQ-	Helifix J/N-HFT-22513	9/11/20
		1200 HR INSP C/O IAW B212 MM& CO&R PARA 5-41 On Pins S/N: DIFS-20054,DIFS-20056,DIFS-20241,DIFS-20291, 24 MTHS INSP C/O IAW B212 MM & CR&O on Drag Brace S/N		
		A1-11786 & A1-11033, Replaced by S/N: A-3904 & A-3884.		
	17484.48	1200 HRS/24 MTH INSP. C/OUT IAW BHT-212-CR&O REV. 10. TT STRAP S/N LPFS-31873, LPFS-31911		
		REPLACED BY S/N LPFS-35465, LPFS-35469, BLADE BOLT S/N DIFS-4170, DIFS-4336 REPLACED		
		BY S/N FWFS-291, FWFS-252, ASB 212-02-116 REV A, FAA AD 2014-12-04, ASB 212-90-5G	OH19740-R	14 AUG 2
		(AD 90-26-11), ASB 212-02-117, ASB 212-94-94, ASB 212-94-92 REV A, FAA AD 92-23-01		
		(ASB 212-90-62 REV A), ASB 212-10-142 REV B Part 1 & Part 2, ASB 212-12-144, FAA AD 2013-03-16,		
		ASB 212-15-152 COMPLIED WITH, TB 212-99-170 PREVIOUSLY C/W ITH.		

COMPONENT NAME M/R HUB ASSY
PART NUMBER 204-012-101-029 GFM
SERIAL NUMBER ADA-01237
PAGE 8 OF

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

INSTALLATION DATA						A / C HOURS SCH. FOR ☑ O / H ☐ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A / C NO.	BY (ACTIVITY)	INSTALLED AT A / C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	HRS. / DATE	DATE	REMOVED AT A / C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	REASON FOR REMOVA
21Jan06	A6-BBE	ADA	24144.50	15804.50	1970.25	2400HR OHL 1200HR INSP	25JAN07	24236.92	15896.92	2062.67	HIGH TIME
~~06MAR07~~	~~A6-BBE~~	~~ADA~~	~~24236.92~~	15896.42	0.00	2400HR OHL 1200H/24M IN	14Feb08	24369.58	16029.58	132.67	Ops Req.
22 FEB 2008	A6-BBA	ADA	25802.25	16029.58	132.67	" "	25Feb09	25846.83	16074.17	177.25	TT Strap timex 12-0
19JUN09	A6-BBO	ADA	21673.42	16074.17	177.25	-do- -do-	22/04/11	22311.9	160712.65	815.73	INBOARD ASB 212- & AD 2011-0
8/4/12	P2-HFT	HELIFIX	18393.0	~~16712.7~~ 16071~~3.7~~	815.7	19977.2	09/11/13	19035.1	17354.8	1457.9	OUTBRD F & TT-STRAP
09/11/13	P2-HFT	HELIFIX	19035.1	17354.8	1457.9	19977.2	— CONT	CARD 9.			

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
	15804.50	6 Mth insp. c/out.	WS 26115BP01	29Nov05
ASB 212-02-116RevA	15804.50	600Hr insp. c/out IAW BHT 212 MM & CR&O. Ultrasonic insp. c/out IAW ASB.	WS CH 10472-R	08Dec05
	15804.50	6 month inspection c/out.	WS 23125BE01	21Jan06
	15806.75	6 Mth insp. c/out.	WS 06056BE16	06May06
	15896.42	Overhauled iaw BHT 212 CR&O, Rev.6 AD 2003-01-04(ASB 212-02-116 R.A), AD 90--26-11(ASB 212-90-59), AD 79-20-05, ASB 212-02-117, ASB 212-94-94, ASB 212-94-92 R.A and TB 212-99-170 complied with. TT Straps S/N LPFS-18093/LPFS-18096 replaced by S/N LPFS-20872/LPFS-20840. IB strap fittings S/N A-5932/A-5975 replaced by S/N A-8983/A-9108 Strap pins S/N DIFS-10365/DIFS-11346/DIFS-11492/DIFS-9444 replaced by S/N DIFS-20054, DIFS-20056, DIFS-20241 and DIFS-20291.	WS CH 11649-O	23FEB07
	15956.08	6 Mth insp. c/out.	WS 24057BE76	25May07
	16029.58	6Mth Insp. c/out. ASB 212-02-116 Rev.A (AD2003-01-04 PT C) c/out	WS 230907BA21	14Feb08

REFER TO INDIVIDUAL LOG CARDS FOR SUBCOMPONENTS

COMPONENT NAME M/R HUB ASSY
PART NUMBER 204-012-101-029 GFM
SERIAL NUMBER ADA-01237
PAGE 7 OF

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A / C NO.	BY (ACTIVITY)	INSTALLED AT A / C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	HRS. / DATE	DATE	REMOVED AT A / C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	REASON FOR REMOVAL
4JUN03	A6-BBW	ADA	13820.17	14830.75	996.50		12Aug03	14072.25	15082.83	1248.58	RTS BBQ
12AUG03	A6-BBQ	ADA	17356.42	15082.83	1248.58		18JAN05	17836.67	15563.08	1728.83	DUE INSP
10Feb05	A6-BBP	ADA	13525.17	15563.08	1728.83		26Nov05	13766.58	15804.50	1970.25	Ops req
			CLOSED - CONT. CARD 8								

15400.33

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
~~ASB 212-02-116REV A~~ ASB 212-02-117 AD 2003-01-04	14830.75	1200 HRS/24 MTHS INSPECTION C/O.TT STRAPS, Pillow Block Bushins, Blade Bolts replaced.	ADA WS OH 7466R	19MAr03
TB 212-99-170	14830.75	New Bolt P/N NAS 6606H27.	-do-	-do-
	14830.75	Drag brace S/N A1-11252 and A1-10835 removed for BBW.	W/s 300/8BW03	05-04-03
WS OH 7618R	14830.75	Drag Braces SND AI-11786 and AI-11033 Installed.	OH 03	06May03
ASB 212-02-116RevA	15082.83	Ultrasonic inspection of Grip Tangs C/out.	WS 12083BW01	12Aug03
	15279.75	6 monthly inspection carried out.	WS 600/2BQ04	24Feb04
W/S. 08054BQ01	15400.33	6 MONTH INSPECTION CARRIED OUT.	SM - 01	09 MAY 04
ASB212-02-117 ASB212-02-116REV A	15563.08	1200HRS/24MTH INSP. C/OUT. TT STRAP S/N LPFS-16437,LPFS-16441 REPL. BY S/N LPFS-18096,LPFS-18093.	WS OH9465-R	24JAN05
	15563.08	6 monthly inspection c/out.	WS 10MBP04	20Feb05
WS 21055BP01	15723.58	6 Monthly Inspection Carried Out.	M 021	22May05
	15726.83	6 Mth insp. c/out.	WS 24065BP02	24Jun05

317-8

COMPONENT NAME M/R Hub Assy

PART NUMBER 204-012-101-029GRM

SERIAL NUMBER ADA-01237

PAGE 6 OF

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

INSTALLATION DATA

DATE	INSTALLED ON A / C NO.	BY (ACTIVITY)	INSTALLED AT A / C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H
200599	A6-BBL	ADA	19654.67	13834.25	0.0
2503001	A6-BBL	ADA	19808.83	13988.42	154.17
120402	A6-BAC	ADA	9618.83	14074.33	240.08
250702	A6-BBS	ADA	18729.00	14636.58	802.33
20/08/2	A6-BBY	ADA	14869.08	14636.58	802.33
24Jan03	A6-BBK	ADA	23350.17	14815.92	981.67
27JAn03	A6-BBY	ADA	15054.00	14819.58	985.33

A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE HRS. / DATE

REMOVAL DATA

DATE	REMOVED AT A / C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	REASON FOR REMOVAL
040301	19808.83	13988.42	154.17	T/T Strap Tx - Calen
230302	19894.75	14074.33	240.08	RTS
250702	10181.08	14636.58	802.33	RTS
270702	18729.00	14636.58	802.33	RTS
24Jan03	15048.42	14815.92	981.67	RTS BBK
27Jan03	23353.83	14819.58	985.33	RTS BBY
16Feb03	15065.17	14830.75	996.50	TT Strap

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
		Overhaul inspection c/out. For replaced sub-components refer to		
		ADA WS # OH 420. TSN: 13834.25	ADA WS #OH420	190599
		6 Monthly Inspection Carried Out. TSN 13894.17	ADA WS 300/13BL00	10050
WS OH 6176R		T/T Straps Replaced. S/Ns Off LPFS-9806/LPFS-9868 S/NS ON LPFS-11666/LPFS-11677		
		M/R Grip Assys Replaced. S/Ns Off ESI-00377/GD-94537 S/Ns On A-6062/A-6063		
	TSN 13988.42	Drag Brace Inspection C/O. Imp roved Inspectability C/O IAW EIQ.159	ADA	140301
WS 300/14BL01		6 Monthly Inspection Carried Out. TSN 13988.42	ADA	250301
WS 19082BY01	14636.58	6 Monthly Inspection Carried out	ADA M 005	20/08/02
AD 2003-01-04		(M/R GRIP) COMPLIED WITH.	TS 212/014	190103
	14819.58	6 Monthly Inspection Carried out.	ADA WS 27013BK01	27JAN03

COMPONENT NAME / PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	REMOVAL DATA		
			ACCUMULATED TIME ON ASSEMBLY OR PART			DATE	ACCUMULATED TIME ON ASSEMBLY OR PART	
		DATE / COMPONENT HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	DATE / COMPONENT HOURS	ASSEMBLY HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: DRAG BRACE	A1-10835	10561.75	NK	0.0	1200	REFER TO ITEM LOG CARDS FOR INSP O/H ETC. ©		
NO.: 204-011-140-005	A1-11252	10561.75	NK	0.0	1200			
NAME: YOKE ASSY		180795						
NO.: 212-011-102-105	A-1145M	11446.17	NEW	NEW	10,000			
NAME: TRUNNION ASSY		180795			RIN 300,000			
NO.: 204-011-105-001	AFS-1860	11446.17	NEW	NEW	15,000			
NAME: BUSHING	BT-4441 BT-4547	180795	NEW	NEW	3600	08MAr03	All 4 @ 3384.58	-
NO.: 204-001-135-105	BT-3685 BT-4558	11446.17			3600	14830.75		
NAME: PILLOW BLOCK	NSN-1	180795	NK	0.0	2400			
NO.: 204-011-108-113FM	NSN-2	1146.17	NK	0.0	2400			
NAME: PITCH HORN	REFS-2625	13558.17	NIL	-	3000			
NO.: 204-011-120-005	REFS-2285	13834.25	NIL	-	3000			
NAME: RETENTION STRAP	LPFS-9806	190599	NIL	-	1200/2 years	13988.42	154.17/23	MTHS
NO.: 204-310-101-101	LPFS-9868	13834.25	NIL	-	1200/2 years	13988.42	154.17/23	MTHS
NAME: FITTING - O/B	A-14554	190599	NIL	-	3600	17354.8	3520.55	JOB#
NO.: 204-012-103-005	A-14556	13834.25	NIL	-	3600	17354.8	3520.55	HFT-2251
NAME: FITTING - I/B	A-5932	190599	NIL	-	2400			
NO.: 212-010-103-007	A-5975	13834.25	NIL	-	2400			
NAME: STRAP PIN	DIFS-9444 DIFS-10365	190599	NIL	-	2400			
NO.: 204-012-104-005	DIFS-11346 DIFS-11492	13834.25			2400			
NAME: M/R GRIP ASSY	ESI-00377	190599	NK	0.0	1200	REFER TO ITEM LOG CARDS	BOTH REM @ 13988.42	154.1
NO.: 204-011-121-009	GD-9453/7	13834.25	NK	0.0	1200	FOR INSP, O/H ETC ©	Assy TSN	154.1

COMPONENT NAME M/R HUB ASSY
PART NUMBER 204-012-101-029GFM
SERIAL NUMBER ADA-01237
PAGE 6A OF

HISTORICAL SERVICE RECORD - CONTINUATION SHEET

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (Specify)	TSN	REPAIR STATION	REMARKS AND MAJOR PART REPLACED		
10May08	Insp.	16030.58	ADA	6 mth insp. c/out.	WS 100508BA35	M 040
25Feb09	Insp.	16074.17	ADA	6 mth insp. c/out.	WS 091208BA21	M 030
09Mar09	Insp	16074.17	ADA	1200 Hrs/24 Mths Inspection carried out IAW BHT 212 CR&O Rev 7. TT Straps LPFS-20840, LPFS-20872 replaced by LPFS-22854, LPFS-22562. FAA AD 2003-01-04 (ASB 212-02-116 Rev A); FAA AD 90-26-11 (ASB 212-90-59); ASB 212-02-117; ASB 212-94-94; ASB 212-94-92 Rev. A complied with. TB 212-99-170 previously complied with.	WS OH 13944-R	OH 07
11Jun09	Insp	16074.17	ADA	6 mth insp. c/out.	WS 080209B097	M 011
19Dec09	Insp	16086.42	ADA	6 mth insp c/out.	WS 181209B051	M 048
03Jan10	Rep	16086.67	ADA	Pitch horn REFS-2625 replaced by REFS-2190	WS 221209B052	M 073
14Jan10	Repl	16087.83	ADA	Pitch horn S/N REFS-2190 replaced by REFS-2625.	WS 140110B053	M 067
25 JAN 12	INSPECTION	16712.67	ADA	1200 Hrs/24 Mths Inspection carried out IAW BHT 212 CR&O Rev 9. TT Straps LPFS-22562, LPFS-22854 replaced by LPFS-28005, LPFS-27424. FAA AD 2003-01-04 (ASB 212-02-116 Rev A); FAA AD 90-26-11 (ASB 212-90-59); ASB 212-02-117; ASB 212-94-94; ASB 212-94-92 Rev. A; FAA AD 2011-08-01, EASA AD 2010-0246 R1, ASB 212-10-142 Rev.B Part II and TB 212-90-128 Rev B. (P/N changed to 204-012-101-153 GFM) complied with. ASB 212-10-142 Rev.B Part I & TB 212-99-170 previously complied with.	WS OH 15928-R	OH01
5/2/13	AD.			FAA AD-2012-17-08, N/A BY YOKE P/N J/N HFT-11513	DAVID COOPER H.E.L. AUTH #H1	H1
14/2/13	AD			FAA AD 2013-03-16, PCW MPI ON ADA J/N WS OH15928-R, INB FIT S/N A-8983 AND A-9108. HELIFIX JN TL-6954	DAVID COOPER H.E. AUTH #H1	H1.

COMPONENT NAME MAIN ROTOR HUB ASSY
PART NUMBER 204-012-101-029GFM
SERIAL NUMBER ADA-01237
PAGE 6A OF

HISTORICAL SERVICE RECORD - CONTINUATION SHEET

OVERHAUL AND SIGNIFICANT REPAIR					
DATE	OVERHAUL OR REPAIR (Specify)	TSN	REPAIR STATION	REMARKS AND MAJOR PART REPLACED	
				THIS SIDE NOT USED	

COMPONENT NAME / PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	TOTAL AIRCRAFT TIME (HRS)	REMOVAL DATA	
			ACCUMULATED TIME ON ASSEMBLY OR PART				ACCUMULATED TIME ON ASSEMBLY OR PART	
		DATE / AIRCRAFT HRS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	DATE / AIRCRAFT HRS		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: STRAP ASSY	BNFS-47696 ✓	180795	NEW	NEW		12642.42	1196.25	-
NO.: 204-012-122-005	BNFS-47754 ✓	11446.17	NEW	NEW		12642.42	1196.25	-
NAME: PIN ASSY	DIFS-7550 ✓	180795	NEW	NEW		13834.25	2388.08	-
	DIFS-7832 ✓		NEW	NEW		13834.25	2388.08	-
	DIFS-7862 ✓		NEW	NEW		13834.25	2388.08	-
NO.: 204-012-104-005	DIFS-7464 ✓	11446.17	NEW	NEW		13834.25	2388.08	-
NAME: BUSHING	BT-4441 ✓	180795	NEW	NEW		TRANSFERED	TO CARD 6	
	BT-4547 ✓		NEW	NEW				
	BT-3685 ✓		NEW	NEW				
NO.: 204-011-135-105	BT-4558 ✓	11446.17	NEW	NEW				
NAME: FITTING IB	A-4467 ✓	180795	NEW	NEW		13834.25	2388.08	-
NO.: 212-010-103-007	A-4119 ✓	11446.17	NEW	NEW		13834.25	2388.08	-
NAME: RETENTION STRAP	BNFS-48426	090597	NIL	-	1200/2 Years	13834.25	1191.83	-
NO.: 204-012-122-005	BNFS-48433	12642.42	NIL	-	1200/2 Years	13834.25	1191.83	-
NAME: Pitch Horn	REFS-432	13558.17	2685.08	0.0	3000 HR	13834.25	2961.17	-
NO.: 204-011-120-005	REFS-2625	13558.17	New	New	3000 HR	TRANSFERED	TO CARD 6	
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								

COMPONENT NAME MR HUB ASSY
PART NUMBER 204-012-101-029G
SERIAL NUMBER ADA-01237
PAGE 5 OF

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT. R/N 72160 130299

INSTALLATION DATA						A/C HOURS SCH. FOR [X] O/H [X] RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	HRS. / DATE	DATE	REMOVED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
27.7.95	A6-BBW	ADA	9260.50	11446.17	00.00	2400/1200	29.2.96	9554.50	11740.17	294.00	M/R BLADES TX
11Mar96	A6-BBL	ADA.	16742.42	11740.17	294.00		110996	17488.83	12486.58	1040.42	Bolt Sheared Plate Assy Grip
40ct96	A6-BBE	ADA	22094.08	12486.58	1040.42		310397	22249.92	12642.42	1196.25	Timex T/T Straps
16May97	A6-BBU	ADA	10109.42	12642.42	1196.25		2.8.97	10364.25	12897.25	1451.08	GRIP PAD DEBONDED
12Aug97	A6-BBP	ADA	12356.58	12897.25	1451.08		200698	12866.25	13406.92	1960.75	A/C on 3000 Hrs
220798	A6-BBS	ADA	15741.33	13406.92	1960.75		011198	15965.33	13630.92	2184.75	A/C on 3000 Hrs
10Dec98	A6-BBS	ADA	15965.33	13630.92	2184.75		130299	16168.67	13834.25	2388.08	O/Haul

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
ASB212-94-94		CONDITIONAL INSPECTION & OVERHAUL CARRIED OUT IN ACCORDANCE WITH COMPONENT	ABU DHABI AVIATION	180795
		REPAIR & OVERHAUL MANUAL BHT-212-CR&O @ T.S.N.11446.17(JOB NO.OH 121)		
		300/600 hr inspectinn carried out. TSN 11740.17, TSO 294.00	ADA WS 645	07Mar96
		Sheared AN 5H10A on grip plate asy replaced. TSN 12486.58, TSO 1040.42	ADA OH-3485R	20Sep96
W/S OH 3876R		T/T Straps Replaced. Drag Brace & Grip Insp. Carried Out Assy TSN 12642.42	ADA	090597
WS OH-4014R		MR Grip pad rebonded, TSN 12897.25, TSO 1451.08	ADA/Manochao	07Aug97
W/S 300/9BP97		600 Hr/6 Mth Inspection Carried Out. TSN 13183.25	ADA	291097
W/S 0706BP01		600 Hr/6 Mth Inspection Carried Out. TSN 13406.92	ADA	100698

SEE PAGE 6

COMPONENT NAME / PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	REMOVAL DATA		
			ACCUMULATED TIME ON ASSEMBLY OR PART				ACCUMULATED TIME ON ASSEMBLY OR PART	
		DATE / COMPONENT HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	DATE / COMPONENT HOURS	DATE / AIRCRAFT HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: OB fitting	A-012475 ✓	10561:45	NEW	NEW		~~13834.25~~	3272.50	-
NO.: 204-012-103-005	~~A-12589~~ ✓	10561:45	NEW	NEW		~~13834.25~~	3272.50	-
NAME: Yoke						140544	884.42	R.T.S. 884.42
NO.: 212-011-102-105	~~A-243~~ ✓	10561:45	NEW	NEW		11446.17		
NAME: Horn	~~REFS-1321~~ ✓	10561:45	NEW	NEW	~~13558.17~~		4996.42	FX
NO.: 204-011-120-005	~~REFS-1365~~ ✓	10561:45	NEW	NEW	13558.17			
NAME: ~~Bushing~~	BT-237 ✓ BT-480 ✓ ~~BT-1367~~ ✓ ~~BT-1383~~ ✓	10561:45	NEW	NEW		14.5.94		CALLED NDT
NO.: 204-011-135-105						11446.17	884.42	884.42
NAME: Strap	BNFS-46565 ✓	10561:45	NEW	NEW		14.5.94	884.42	R.T.S.
NO.: 204-012-122-005	BNFS-46420 ✓	10561:45	NEW	NEW		11446.17		
NAME: Grip	LL-0848	10561:45	NK	0:0		14.5.94	NK	2080.34
NO.: ~~204-011-121-009G~~	JI-I-38985 ✓	10561:45	NK	0:0		11446.17	NK	2080.34
NAME: Drag Brace	AI-10835 ✓	10561:45	NK	0:0	DEFER TO LOG CARDS FOR O/H INSP ETC		TRANSFERRED TO	
NO.: 204-011-140-005	AI-11252 ✓	10561:45	NK	0:0				
NAME: YOKE ASSY		180795					CARD 6	
NO.: 212-011-102-105	A-1145M	11446.17	NEW	NEW				
NAME: 204-011-105-001		180795						ADA TRS
NO.: TRUNNION ASSY	AFS-1860	11446.17	NEW	NEW				
NAME: GRIP ASSY	LL-0437	180795	8878.42	00.00	DEFER TO LOG CARDS FOR O/H INSP ETC	~~13834.25~~	~~11266.50~~	1191.83
~~204-011-121-009G~~	JI-I-38847	11446.17	"	00.00		13834.25	~~NK~~	1191.83

COMPONENT NAME M/R HUB ASSEMBLY

PART NUMBER 204-012-101-029G

SERIAL NUMBER ADA-01237

PAGE 4 OF 4

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

17108:35	Overhaul (2400)
5.07-95	T.T. Straps (Date)
17104:30	T.T. Straps (hours)

INSTALLATION DATA

DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H
221290	30822 (BL)	ADA	9332:05	8208:10	1200:10
10.1.92	31183 (80)	ADA	4400:15	9365:50	00:00
25.11.92	21441:05 (BH)	ADA	21441:05	9851:35	485:45
5.7.93	30942 (BQ)	ADA	15904:30	10561:45	1195:55

REMOVAL DATA

DATE	REMOVED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
080991	10489:45	9365:50	2357:50	High time - ohl
7.11.92	4886:00	9851:35	485:45	UNABLE TO TRACK & BAL.
28.5.93	22151:15	10561:45	1195:55	TT STRAPS TIMEX
140594	16788.92	11446.17	2080.33	M/R GRIP CRACKED

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
		Overhauled in accordance with Bell 212 Component Repair and Overhaul Manual	D.A.A.S.	17.12.91
		(J/No. 212442-2101). T.S.N. 9365:50 ; T.S.O. 00:00.	Pte. Ltd.	
		A.S.B. 212-89-55'A', A.S.B. 212-90-59, A.S.B. 212-90-62'A',	Singapore.	DON'TY 30
		A.S.B. 212-90-64'A', A.S.B. 212-90-68, T.B. 212-86-94 and ADHM/212/85/36		
		complied with.		
		Note: Assy. serviced with Aeroshell Grease 22C.		
Q.A. INSP. 93/5		A.D. 93-05-01 SATISFIED BY INST'N OF 'NEW' YOKE dd 17.12.91, (W/O 212442-2101)	ADA	12.04.93
ADA WS 0H508		Disassy/reassy (comp change & ASB complinace). TSN 10561:45, TSO 1195:55	ADA	170693
		ASB 212-90-59, ASB 212-92-80, ASB 212-90-62A & ASB 212-92-80 c/o.		

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL ASSEMBLY TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL ASSEMBLY TIME (HRS)	ACCUMULATED TIME ON ASSEMBLY OR PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: Inboard Fitting	A-2371	7008:00	00:00	-	9365:50	2357:50		2400 HRS.
NO: 212-010-103-7	A-2451	7008:00	00:00	-	9365:50	2357:50		2400 HRS.
NAME: Outboard Fitting	A-8575	7008:00	00:00	-	10561:45	3553:45		3600 HRS.
NO: 204-012-103-5	A-10294	7008:00	00:00	-	10561:45	3553:45		3600 HRS.
NAME: Strap Pin Inboard	EA-794	7008:00	00:00	-	9365:50	2357:50		2400 HRS.
NO: 204-012-104-5	EA-993	7008:00	00:00	-	9365:50	2357:50		2400 HRS.
NAME: Strap Pin Outboard	EA-1002	7008:00	00:00	-	9365:50	2357:50		2400 HRS.
NO: 204-012-104-5	EA-1320	7008:00	00:00	-	9365:50	2357:50		2400 HRS.
NAME: Trunnion								
NO: 204-011-105-1	A1-11225 ✓	00:00	00:00	-	11446.17	13922.45	RTS.	15000 HRS.
NAME: TT Straps	BNFS-44466	8208:10	00:00	-	9365:50	1157:40		1200 HRS/24 MTH
NO: 204-310-101-101	BNFS-44468	8208:10	00:00	-	9365:50	1157:40		1200 HRS/24 MTH
NAME: Yoke	EM83033-3	8208:10	1309:35	-	9365:50	3299:48	SPINDLE WORN	3600 HRS.
NO: 204-011-102-125								
NAME: Drag Brace	A-273	9365:50	COND	00:00	10561:45	1195:55		Cond.
NO: 204-011-140-005	A-274	9365:50.	COND	00:00	10561:45	1195:55		Cond.
NAME: Pitch Horn	REFS-452	8265:15	NEW	-	10561:45	2296:30		3000 Hrs.
NO: 204-011-120-5	REFS-464	8265:15	NEW	-	10561:45	2296:30		3000 Hrs.
NAME: Retention Strap	LKFS 3716	9365:50	00:00	-	10561:45	1195:55		1200 HRS/24 MTH
NO: 204-310-101-101	LKFS 3729	9365:50	00:00	-	10561:45	1195:55		1200 HRS/24 MTH
NAME: Inboard Fitting	A-3503 ✓	9365:50	00:00	-	11446.17	2080.34	RTS	2400 HRS.
NO: 212-010-103-007	A-3507 ✓	9365:50	00:00	-	11446.17	2080.34	RTS	2400 HRS.
NAME: Inboard Strap Pin	VT11779 ✓	9365:50	00:00	-	11446.17	2080.34	RTS	2400 HRS.
NO: 204-012-104-005	VT12464 ✓	9365:50	00:00	-	11446.17	2080.34	RTS	2400 HRS.
NAME: Outboard Strap Pin	VT12471 ✓	9365:50	00:00	-	11446.17	2080.34	RTS	2400 HRS.
NO: 204-012-104-005	VT12499 ✓	9365:50	00:00	-	11446.17	2080.34	RTS	2400 HRS.
NAME: Yoke	A-379	9365:50	00:00	-	10561:45	2029:40		3600 HRS.
NO: 204-011-102-125								

COMPONENT NAME M/R Hub Assy
PART NUMBER 204-012-101-029G
SERIAL NUMBER ADA-01237
PAGE 3 OF 4

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc
POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

INSTALLATION DATA						SCH. FOR ☐ O/H ☐ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	HRS. / DATE	DATE	REMOVED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
221290	80322(BL)	ADA	9332:05	8208:10	1200:10	/	080991	10489:45	9365:50	2357:50	High time overhaul
					XFER TO	CARD NO. 4					
						/					
						/					
						/					
						/					
						/					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE

COMPONENT NAME / PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA — ACCUMULATED TIME ON ASSEMBLY OR PART		SCHEDULED REMOVAL	TOTAL AIRCRAFT TIME (HRS)	REMOVAL DATA — ACCUMULATED TIME ON ASSEMBLY OR PART	
		DATE / AIRCRAFT HRS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	DATE / AIRCRAFT HRS		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: O/B Fittings	A-406	3469.30	0.0	-		7008:00	3538:30	
NO.: 204-012-103-5	A1-34881	26.4.86	0.0	-				
NAME: TT Straps	27249	3469.30	0.0	-		7281:30	1147:50	-
NO.: 204-012-122-5	27258	26.4.86	0.0	-	4617:20			
NAME: T.T. Strap	26969 (R)				30.7.88	5898.30	1195.10	
NO.: 204-012-122-005	28941 (W)	4617:20	00:00	-	5812.30			
NAME: Inboard Fitting	A1079 (R)					7008:00	2390:40	
NO.: 212-010-103-007	A1106 (W)	4617:20	00:00	-				
NAME: Strap Pin Inboard	VT9448 (R)					7008:00	2390:40	
NO.: 204-012-104-005	VT9504 (W)	4617:20	00:00	-				
NAME: Strap Pin Outboard	VT9932 (R)					7008:00	2390:40	
NO.: 204-012-104-005	VT10166 (W)	4617:20	00:00	-				
NAME: PITCH HORN	RE3953	5271:00	NEW	NEW	8271:00	8265:15	2994:15	TIMEX
NO.: 204-011-120-005	RE4267	5271:00			8271:00	8265:15	2994:15	TIMEX
NAME: YOKE ASSY		30.7.88				8208:10	2758:40 (inc 363 lift	
NO.: 204-011-102-125	EM-82784--3	5812.30	NIL	-	3600.00			
NAME: Retention Straps	33182 33281	30.7.88	NIL	-		7008:00	1195:30	
NO.: 204-012-122-5		5812.30			1200			
NAME: Retention Strap	LKFS-0880	5.9.89				8208:10	1200:10	
NO.: 204-310-101-101	LKFS-1301	7008:00	00:00	-				

SEE CARD NO. 4

COMPONENT NAME M/R HUB ASSEMBLY
PART NUMBER 204-012-101-029G
SERIAL NUMBER ADA-01237
PAGE 2 OF 4

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED BELOW IS RETURNED TO BHT. FOR ANY REASON IT IS MANDATORY THAT THIS SERVICE RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	DATE	REMOVED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
13.6.87	32123	ADA	7866.50	4617.20	0.0	20-12-87	8520:30	5271:00	653:40	Sus grips binding
2.3.88	30777	ADA	16524.00	5271:00	653:40	1-7-88	17065:30	5812:30	1195:10	TT straps & yoke tx
23-8-88	30651	ADA	6143:55	5812:30	1195:10	31-8-88	6147:30	5816:05	1198:45	Ops requirement
31-8-88	30793	ADA	16990:30	5816:05	1198:45	12-2-89	17701:40	6527:15	1909:55	At 1200 hr insp
15-2-89	30917	ADA	6288:45	6527:15	1909:55	070689	6769.30	7008.00	2390.40	Timex T/T Straps Due Overhaul
21-11-89	30942	ADA	12956:40	7008:00	00:00	080990	14156:50	8208:10	1200:10	TT straps timex.
				SEE LOG	CARD NO.	3				

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
W/S 552/87		ASB.212-87-43 PT.II Complied With. Assy TT 4617.20 TSO 0.0	ADA	5.5.87
		ASB.212-87-44 REV.'A' Assignment of 15000 Hours Retirement to M/R		
		Trunnion Assy P/N 204-011-105-1	ADA	31.10.87
	-	Overhauled in accordance with Bell Component Repair and Overhaul Manual	Dowty Avia.	5 Sept'89
		T.T. - 7008:00, T.S.O. - 00:00 (Job No. 211665-2101).	Svcs Pte Ltd.,	
		T.B. 212-78-11, T.B. 212-86-94, ASB 212-80-17, ASB 212-81-23, ASB 212-85-37'A',	Singapore	DOWTY 28
		ASB 212-87-43'A', ASB 212-87-44 and ADHM/212/85/36 complied with.		
		ASB 212-89-55 observed.		
ASB 212-90-60		MR YOKE INSPECTION	ADA/13KBQ90	120490

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: RETENTION STRAP								
NO: 204-012-122-005	20388	1192.50	0.0	-	2357:00	1164:10		1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-005	20674	1192.50	0.0	-	2357:00	1164:10		1200/2 Years
NAME: PITCH HORN								
NO: 204-011-120-5	RE-3787	2357:00	00:00		5271:00	2914:00		3000
NAME: PITCH HRON								
NO: 204-011-120-5	RE-3828	2357:00	00:00		5271:00	2914:00		3000
NAME: RENTENTION STRAP								
NO: 204-012-122-5	23010	2357:00	00:00		3469.30	1112.30	-	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	23514	2357:00	00:00		3469.30	1112.30	-	1200/2 Years
NAME: INBD STRAP FITTING								
NO: 212-010-103-7	A-513	2357:00	00:00		4617:20	2260:20	-	2400
NAME: INBD STRAP FITTING								
NO: 212-010-137-7	A-529	2357:00	00:00		4617:20	2260:20	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	PB-6414	2357:00	00:00		4617:20	2260:20	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	PB-6445	2357:00	00:00		4617:20	2260:20	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	PB-6531	2357:00	00:00		4617:20	2260:20	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	PB-6617	2357:00	00:00		4617:20	2260:20	-	2400
NAME: YOKE								
NO: 204-011-102-125	EM81742-1	2357:00	00:00		5812.30	3545.30	-	3600
NAME:					Time includes 80 Lift Event Hours as per ASB 212-87-44			

COMPONENT NAME M/R HUB ASSEMBLY
PART NUMBER 204-012-101-029G
SERIAL NUMBER ADA-01237
PAGE 1 OF 2

Bell Helicopter TEXTRON
Division of Textron Inc
POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED BELOW IS RETURNED TO BHT. FOR ANY REASON IT IS MANDATORY THAT THIS SERVICE RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	DATE	REMOVED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
1-20-83	31231	BHT	0.0	0.0	NEW	10.10.83	1192.50	1192.50	-	TT Straps Time-X
14.10.83	30783	ADH	6004.30	1192.50	-	2.12.83	6126.35	1314.55	-	Grip Seal Leaking
5.12.83	30794	ADH	10,711.50	1314.55	-	8.2.84	10970.10	1573.15	-	Grip Seal Leaking
10.2.84	30942	ADH	4821.30	1573.15	-	26.2.84	4868.25	1620.10	-	Grip Seal Leaking
8.3.84	30773	ADH	5241.40	1620.10	-	23.1.85	5978.30	2357.00	-	Due Overhaul
21.6.85	30776	ADH	13537.50	2357:00	00:00	4.12.85	14154.10	2973.50	616.50	2:1 Vib.
11.12.85	30786	ADH	13587.15	2973.50	616.50	1.1.86	13686.40	3073.15	716.15	To service 32125
2.1.86	32125	ADH	5737.25	3073.15	716.15	26.4.86	6133.40	3469.30	1112.30	TT Straps Time-X
28.4.86	32125	ADH	6133.40	3469.30	1112.30	8.2.87	7281.30	4617.20	2260.20	TT Straps Timex. Sent for Overhaul
10.6.87	30794	ADA	15932.25	4617:20	00:00	11.6.87	15932.25	4617.20	0.0	Unable to Track & Balance M/R Blades

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
		Overhauled in accordance with Bell Component Repair and Overhaul Manual	Fas Orient	13/3/85
		T.T. 2357:00 T.S.O - 00:00 (Job No. 10968).	(Pte.) Ltd.,	FAS 10
		T.B. 212-78-11, ASB. 212-80-17, ASB.212-81-23 and F.A.A. AD.79-20-05	Singapore.	
		Amendment 39-3662 and T.B. 212-81-56 Rev. 'A' found complied with.		
		NOTE: Hub Assembly serviced with Aeroshell Grease 22C.		
		Overhauled in accordance with Bell 212 Component Repair & Overhaul Manual	Fas Orient	23 Mar'87
		T.T. 4617:20, T.S.O. - 00:00 (Job No. 210533-2101).	(Pte) Ltd.,	
		T.B. 212-78-81, ASB 212-80-17, ASB 212-81-23, OSN 212-85-13, A.D.	Singapore.	
		79-20-05, T.B. 212-86-94 complied with.		FAS 10
		NOTE: Hub Assembly serviced with Aeroshell Grease 22C.		

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL AIRCRAFT TIME (HRS)	ACCUMULATED TIME ON ASSEMBLY OR PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: INBD STRAP FITTING								
NO: 212-010-103-007	A1-07411	0.0	0.0	NEW	2357:00	2357:00		2400
NAME: INBD STRAP FITTING								
NO: 212-010-103-007	A1-07383	0.0	0.0	NEW	2357:00	2357:00		2400
NAME: OUTBD STRAP FITTING								
NO: 204-012-103-005	A1-33358	0.0	0.0	NEW	3469.30	3469.30	-	3600
NAME: OUTBD STRAP FITTING								
NO: 204-012-103-005	A1-33404	0.0	0.0	NEW	3469.30	3469.30	-	3600
NAME: STRAP ASSY.								
NO: 204-012-122-005	16001	0.0	0.0	NEW	1192.50	1192.50	-	1200 HRS. OR 2 YRS.
NAME: STRAP ASSY.								
NO: 204-012-122-005	16003	0.0	0.0	NEW	1192.50	1192.50	-	1200 HRS. OR 2 YRS.
NAME: STRAP PIN								
NO: 204-012-104-005	VT-1416	0.0	0.0	NEW	2357:00	2357:00	-	2400
NAME: STRAP PIN								
NO: 204-012-104-005	PB-7649	0.0	0.0	NEW	2357:00	2357:00	-	2400
NAME: STRAP PIN								
NO: 204-012-104-005	PB-7679	0.0	0.0	NEW	2357:00	2357:00	-	2400
NAME: STRAP PIN								
NO: 204-012-104-005	VT-1108	0.0	0.0	NEW	2357:00	2357:00	-	2400
NAME: PITCH HORN								
NO: 204-011-120-005	RE-2975	0.0	0.0	NEW	2357:00	2357:00	-	3000
NAME: PITCH HORN								
NO: 204-011 120-005	RE-2980	0.0	0.0	NEW	2357:00	2357:00	-	3000
NAME: YOKE ASSY.								
NO: 204-011-102-125	EM-81704-4	0.0	0.0	NEW	2357:00	2357:00	-	3600
NAME:								
NO:								

COMPONENT NAME YOKE ASSY
PART NUMBER 212-011-102-105
SERIAL NUMBER A-1145 M
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc
POST OFFICE BOX 482 • FORT WORTH TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

INSTALLATION DATA						A/C HOURS SCH. FOR ☐ O/H ☑ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO. XXX MRH	BY (ACTIVITY)	INSTALLED AT A/C HRS. XXXX MRH	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	HRS. / DATE	DATE	REMOVED AT A/C HRS. MRH	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
180795	ADA-01237	ADA OH121	11446.17	NEW	NEW	10000HR RET					
~~09-04-12~~	~~PQ-HFT 3125~~	~~HELIFIX~~	~~18393.0~~	~~5266.5~~	~~5266.5~~	23126.5	~~09-11-12~~	~~17354.80~~	~~5908.6~~	~~5908.6~~	~~DUE 1200HR/24MTH~~

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
	4450.75	Overhauled. ASB 212-94-94 complied with.	WS OH 11649-0	27FEB07
2012-17-08		M/R YOKE P/N: 204-011-102-XXX. M/A by P/N. S/N: HFT-11513	MH	5/3/13
	5908.6	1200 HR/24 MTH INSP C/O IAW BHT 212-MM-5-40. HELIFIX S/N-HFT-22573		09/1/13
	6038.36	1200 HR/24 MTH INSP. C/OUT.	OH 19740-R	14 AUG 16
	6849.26	OVERHAULED WITH M/R HUB ASSY IAW BHT-212-CR&O REV. 12.	OH 22834-0	07DEC20
		ASB 212-94-94 -1200 HR YOKE INSP - C/W ITH.		

COMPONENT: TRUNNION
PART NUMBER: 204-011-105-001

SERIAL NUMBER: AFS-1860
PAGE: 4 of

HISTORICAL SERVICE RECORD

INSTALLED M/R HUB ASSY S/N: ADA-01237

Rin Factor = (Flights x 5) + (Lifts x 5)

INSTALLATION DATA					LIFE LIMITS	REMOVAL DATA			
DATE	FITTED ON A/C REG	BY (ACTIVITY)	INSTALLED AT A/C T.A.T. FLIGHTS / LIFTS	COMPONENT TSN / RIN COMP' TSN COMP' RIN	SCHEDULED RETIREMENT COMP' TSN COMP' RIN	DATE	REMOVED AT A/C T.A.T. FLIGHTS / LIFTS	COMPONENT TSN / RIN COMP' TSN COMP' RIN	REASON FOR REMOVAL
6-Mar-07	A6-BBE	ADA	24236.92 26725 4128	4450.75 155188	15000 300000	14-Feb-08	24369.58 27194 4282	4583.42 158303	Removed with M/R Hub
22-Feb-08	A6-BBA	ADA	25802.25 33065 5966	2448.00 158303	" "	25-Feb-09	25846.83 33186 6032	4628.00 159238	Removed with M/R Hub
19-Jun-09	A6-BBO 30903	ADA	21673.42 31811 13191	4628.00 159238	" "	28-Apr-11	22311.90 33511 13765	5266.50 170608	Removed with M/R Hub
8-Apr-12	P2 HFT 32125	HELIFIX	18393.00 24181 8585	5266.50 170608	" "	28-Feb-16	19165.10 28526 8908	6038.60 193948	Removed with M/R Hub
14-Apr-18	N-21225	BDS	16977.33 39031 4569	6038.60 193948	" "	2-Mar-20	17788.17 42042 4569	6849.44 209003	Removed with M/R Hub
				6849.44 209003	" "				
					" "				
					" "				
					" "				
					" "				
					" "				

HISTORY OF INSPECTION, OVERHAUL, REPAIR, AND COMPLIANCE WITH SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS ETC

DATE	COMP' TSN / RIN		DESCRIPTION OF WORK CARRIED OUT	SIGNATURE	AUTH.

COMPONENT: TRUNNION
PART NUMBER: 204-011-105-001
SERIAL NUMBER: AFS-1860
PAGE: 3 of

HISTORICAL SERVICE RECORD

INSTALLED M/R HUB ASSY S/N: ADA-01237

Rin Factor = (Flights x 5) + (Lifts x 5)

INSTALLATION DATA						LIFE LIMITS	REMOVAL DATA			
DATE	FITTED ON A/C REG	BY (ACTIVITY)	INSTALLED AT A/C T.A.T. FLIGHTS	LIFTS	COMPONENT TSN / RIN COMP' TSN COMP' RIN	SCHEDULED RETIREMENT COMP' TSN COMP' RIN	DATE	REMOVED AT A/C T.A.T. FLIGHTS	LIFTS	COMPONENT TSN / RIN COMP' TSN COMP' RIN	REASON FOR REMOVAL
20-May-99	A6-BBL	ADA	19654.67		2338.08	15000	10-May-00	19714.58		2448.00	NOT REMOVED: Introduction of AD 2000-08-52
			24497 Events		72998	300000		24885 Events		74993	
10-May-00	A6-BBL	Introduction of AD 2000-08-52	19714.58		2448.00	"	23-Mar-02	19894.75		2628.17	Removed with M/R Hub
			33977	0	74993	"		34872	401	81473	
12-Apr-02	A6-BAC	ADA	9618.83		2628.17	"	25-Jul-02	10181.08		3190.42	Removed with M/R Hub
			6536	469	81473	"		9963	2806	110293	
25-Jul-02	A6-BBS	ADA	18729.00		3190.42	"	27-Jul-02	18729.00		3190.42	Removed with M/R Hub
			17798	381	110293	"		17798	381	110293	
20-Aug-02	A6-BBY	ADA	14869.08		3190.42	"	24-Jan-03	15048.42		3369.75	Removed with M/R Hub
			11927	557	110293	"		12314	557	112228	
24-Jan-03	A6-BBK	ADA	23350.17		3369.75	"	27-Jan-03	23353.83		3373.42	Removed with M/R Hub
			22072	3	112228	"		22095	3	112343	
27-Jan-03	A6-BBY	ADA	15054.00		3373.42	"	16-Feb-03	15065.17		3384.58	Removed with M/R Hub
			12323	557	112343	"		12335	557	112403	
4-Jun-03	A6-BBW	ADA	13820.17		3384.58	"	12-Aug-03	14072.25		3636.67	Removed with M/R Hub
			22121	741	112403	"		23734	768	120603	
12-Aug-03	A6-BBQ	ADA	17356.42		3636.67	"	18-Jan-05	17836.67		4116.92	Removed with M/R Hub
			485	960	120603	"		2819	2409	139518	
10-Feb-05	A6-BBP	ADA	13525.17		4116.92	"	26-Nov-05	13766.58		4358.33	Removed with M/R Hub
			23658	2202	139518	"		24644	3635	151613	
21-Jan-06	A6-BBE	ADA	24144.50		4358.33	"	25-Jan-07	24236.92		4450.75	Removed with M/R Hub
			26571	3567	151613	"		26725	4128	155188	

HISTORY OF INSPECTION, OVERHAUL, REPAIR, AND COMPLIANCE WITH SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS ETC

DATE	COMP' TSN	RIN	DESCRIPTION OF WORK CARRIED OUT	SIGNATURE	AUTH.
10-May-00	2448.00	74993	AD 2000-08-52 complied with.	QA 01	ADA
31-Jul-00	2477.25	76673	AD 2000-15-52 complied with.	QA 01	ADA
19-May-99	0.00	0	Installed on M/R Hub A-01237 @ Hub TSN: 11446.17	WS OH 121	ADA

COMPONENT NAME TRUNNION
PART NUMBER 204-011-105-001
SERIAL NUMBER AFS-1860
PAGE 2 OF

COMMERCIAL HISTORICAL SERVICE RECORD

R.I.N. FACTOR =X5

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP. ☐ O/H ☐ RET.	REMOVAL DATA				
DATE	INSTALLED ON AIRCRAFT SERIAL NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS. / EVENTS	COMP. HRS./RIN SINCE NEW COMP. HRS. / RIN	COMP. HRS./RIN SINCE O/H COMP. HRS. / RIN	COMP. HRS. RIN	DATE	REMOVED AT A/C HRS. / EVENTS	COMP. HRS./RIN SINCE NEW COMP. HRS. / RIN	COMP. HRS./RIN SINCE O/H COMP. HRS. / RIN	REASON FOR REMOVAL
15-10-95	RIN Intro' A6-BBW		9345.75 0.0	85.25 ~~1705~~	2558 *	24-	11-95	9554.50 693	294.00 5170		Blades T/EX
11-06-96	A6-BBL		16742.42 2990	294.00 5170		11-09-96		17488.83 8805	1040.42 34245		Grip plate bolt u/s
04-10-96	A6-BBE		22094.08 8559	1040,42 34245		31-03-97		22249.92 9280	1196.25 37850		Grip & T.T Straps
16-05-97	A6-BBU		10109.42 13247	1196.25 37850		02-08-97		10364.25 15085	1451.08 47040		Grip De-bond.
12-08-97	A6-BBP		12356.58 18538	1451.08 47040			200698	12866.25 22319	1960.75 65945		A/C ON 3000 HR INSP.
220798	AG-BBS		15741.33 8475	1960.75 65945			151198	15965.33 9054	2184.75 68840		A/C on 3000 HR Insp
10Dec98	A6-BBS	ADA	15965.33 9054	2184.75 68840			130299	16168.67 9718	2388.08 ~~72160~~ 72998 *		M/R Hub Due O/H

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY Signature affirms work performed IAW FAR Part 43. SIGNATURE	CERT. NO.	DATE
	CORRECTION TO RIN CALCULATION IAW AD 2000-15-52, REF' TO ATTACHED HISTORY SHEET. EM/ADA/89 QA 01			

7861 61838 REV 1294

COMPONENT NAME Trunnion
PART NUMBER 204-011-105-001
SERIAL NUMBER AFS-1860
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc
POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

INSTALLATION DATA						A/C HOURS SCH. FOR ☐ O/H ☐ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT A/C HRS. MRH	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	HRS. / DATE	DATE	REMOVED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
180795	ADA-01237	ADA OH121	11446.17	NEW	NEW						

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE

NOMENCLATURE FITTING ASSY
PART NUMBER 212-010-103-007 FM
SERIAL NUMBER A- 008994
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 76101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☑ RET	REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS / RIN	SINCE O/H HRS COMP. HRS / RIN	COMP. HRS / RIN	DATE	REMOVED AT A/C HOURS A/C RIN	COMP. HRS/RIN SINCE NEW HRS / RIN	SINCE O/H HRS / RIN	REASON FOR REMOVAL
10DEC 2020	ADA -9237	OH 22843-0	18295:38	0.0	NEW	2400HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1.)

NOMENCLATURE FITTING ASSY
PART NUMBER 212-010-103-007 FM
SERIAL NUMBER A- 9156
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482. Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN			DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL
	MRH		MRH	SINCE NEW	SINCE O/H	COMP. HRS.		MRH	SINCE NEW	SINCE O/H	
			A/C HOURS	HRS COMP. HRS	HRS COMP. HRS			A/C HOURS	HRS	HRS	
			A/C RIN	RIN	RIN	RIN		A/C RIN	RIN	RIN	
10DEC 2020	ADA -01237	OH 22843-0	18295:38	0.0	NEW	2400HRRET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1)

Component Name FITTING OUTBD

Part Number 204-012-103-005

Serial Number CQ-73

Page 1 Of 1

Bell Helicopter

A Textron Company

Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA

Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN		Next Scheduled ☐ Insp ☐ O/H ☑ RET
				Since New	Since O/H	
			A/C Hours	Comp. Hrs	Comp. Hrs	Comp. Hrs
			RIN	RIN	RIN	RIN
09/11/13	32125	HELIFIX	19035.1	0.0	NEW	22635.1
				0.0	NEW	

REMOVAL DATA

Date	Removed At	Component Hours / RIN		Reason For Removal
		Since New	Since O/H	
	A/C Hours	Comp. Hrs	Comp. Hrs	
	RIN	RIN	RIN	

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Compiled With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date
940:38	OVERHAULED WITH M/R HUB ASSY IAW BHT-212-CR&O REV. 12	OH-06	OH22834-O	07DEC20

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

7861 5671REV994

Component Name FITTING OUTBD

Part Number 204-012-103-005

Serial Number CQ-150

Bell Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA

Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN		Next Scheduled ☐ Insp ☐ O/H ☑ RET
				Since New	Since O/H	
			A/C Hours	Comp. Hrs	Comp. Hrs	Comp. Hrs
			RIN	RIN	RIN	RIN
09/11/13	33125	Heli-Fix	14035:1	0.0	NEW	22635:1
				0.0	NEW	

REMOVAL DATA

Date	Removed At	Component Hours / RIN		Reason For Removal
		Since New	Since O/H	
	A/C Hours	Comp. Hrs	Comp. Hrs	
	RIN	RIN	RIN	

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Compiled With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date
9410:380	OVERHAULED WITH M/R HUB ASSY IAW BHT-212-CR&O REV. 12.	OH-06	OH22834-0	07DEC20

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

GRN: 999560

Component Name STRAP ASSY

Part Number 204-310-101-101

Serial Number LPFS38503

Page 1 **Of** 1

Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA

Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN		Next Scheduled
				Since New	Since O/H	☐ Insp ☐ O/H ☑ RET
			A/C Hours	Comp. Hrs	Comp. Hrs	Comp. Hrs
			RIN	RIN	RIN	RIN
10NOV 2020	ADA -01237	OH 220430	MRH 18295:38	0.0	NEW	1200 HRS
				0.0	NEW	24 MTH

REMOVAL DATA

Date	Removed At	Component Hours / RIN		Reason For Removal
		Since New	Since O/H	
	A/C Hours	Comp. Hrs	Comp. Hrs	
	RIN	RIN	RIN	

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Compiled With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

GRN: 099560

Component Name STRAP ASSY

Part Number 204-310-101-101

Serial Number LPFS38507

Page 1 Of 1

Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA

Date	Installed on Aircraft Serial No.	By (Activity)	Installed At	Component Hours / RIN	
			MRH	Since New	Since O/H
			A/C Hours	Comp. Hrs	Comp. Hrs
	MRH		RIN	RIN	RIN
10DEC 2020	ADA -01237	OH 228430	18295:38	0.0	NEW
				0.0	NEW

Next Scheduled
- ☐ Insp
- ☐ O/H
- ☑ RET

Comp. Hrs
RIN
1200 HRS
24 MTHS

REMOVAL DATA

Date	Removed At	Component Hours / RIN		Reason For Removal
		Since New	Since O/H	
	A/C Hours	Comp. Hrs	Comp. Hrs	
	RIN	RIN	RIN	

History of Inspection, Overhaul, Repair and Application of Technical Bulletin, Service Bulletin, Airworthiness Directives, Etc.

Component Total Time / RIN	Description of Work Accomplished	Compiled With By - Signature affirms work performed IAW FAR Part 43		
		Signature	Cert. No.	Date

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

NOMENCLATURE PIN ASSY
PART NUMBER 204-012-104-005
SERIAL NUMBER DIFS-20685
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA

NEXT SCHEDULED: ☐ INSP ☐ O/H ☒ RET

DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS / A/C RIN	COMPONENT HOURS/RIN: SINCE NEW HRS COMP. HRS / RIN	COMPONENT HOURS/RIN: SINCE O/H HRS COMP. HRS / RIN	NEXT SCHEDULED: COMP. HRS / RIN
10DEC 2020	MRH ADA -01237	OH 22843-0	18295:38	0.0	NEW	24000HR RET
				0.0	NEW	

REMOVAL DATA

DATE	REMOVED AT MRH A/C HOURS / A/C RIN	COMP. HRS/RIN: SINCE NEW HRS / RIN	COMP. HRS/RIN: SINCE O/H HRS / RIN	REASON FOR REMOVAL

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD: SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions. (Model 204 refer to Section 1.)

NOMENCLATURE PIN ASSY
PART NUMBER 204-012-104-005
SERIAL NUMBER DIFS-20814
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 76101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☒ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS / A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP HRS / RIN	COMPONENT HOURS/RIN SINCE O/H HRS COMP HRS / RIN	COMP HRS / RIN	DATE	REMOVED AT MRH A/C HOURS / A/C RIN	COMP HRS/RIN SINCE NEW HRS / RIN	COMP HRS/RIN SINCE O/H HRS / RIN	REASON FOR REMOVAL
10DEC 2020	ADA -01237	OH 22843-0	18295:38	0.0	NEW	2400HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions. (Model 204 refer to Section 1.)

NOMENCLATURE PIN ASSY
PART NUMBER 204-012-104-005
SERIAL NUMBER DIFS-20899
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☒ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS RIN	COMPONENT HOURS/RIN SINCE O/H HRS COMP. HRS RIN	COMP. HRS RIN	DATE	REMOVED AT MRH A/C HOURS A/C RIN	COMP. HRS/RIN SINCE NEW HRS RIN	COMP. HRS/RIN SINCE O/H HRS RIN	REASON FOR REMOVAL
10DEC 2020	ADA -01237	OH 22843-0	18295:38	0.0	NEW	2400HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD: SIGNATURE	NO. CERT. NO	DATE

7861 56717REV 994

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions

NOMENCLATURE PIN ASSY
PART NUMBER 204-012-104-005
SERIAL NUMBER DIFS-20956
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 76101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA

NEXT SCHEDULED: ☐ INSP ☐ O/H ☒ RET

DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS / A/C RIN	COMPONENT HOURS/RIN: SINCE NEW HRS COMP HRS / RIN	COMPONENT HOURS/RIN: SINCE O/H HRS COMP HRS / RIN	NEXT SCHEDULED: COMP HRS / RIN
10DEC 2020	MRH ADA -01237	OH 22843-0	18295:38	0.0 /	NEW	2400HR RET
				0.0 /	NEW	

REMOVAL DATA

DATE	REMOVED AT MRH A/C HOURS / A/C RIN	COMP. HRS/RIN: SINCE NEW HRS / RIN	COMP. HRS/RIN: SINCE O/H HRS / RIN	REASON FOR REMOVAL

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD: SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1.)

NOMENCLATURE PITCH HORN ASSY
PART NUMBER 204-011-120-005
SERIAL NUMBER REFS 3558
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET 3000	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS RIN	COMPONENT HOURS/RIN SINCE O/H HRS COMP. HRS RIN	COMP. HRS. RIN	DATE	REMOVED AT MRH A/C HOURS A/C RIN	COMP. HRS/RIN SINCE NEW HRS RIN	COMP. HRS/RIN SINCE O/H HRS RIN	REASON FOR REMOVAL
	MRH		22149.4	0.0	NEW	3000HR RET	23.07.11	22399.7	250.3		
19.12.10	P2-HFT	Helifax	MRH 16580.15	0.0	NEW	25149.4					
05.04.12	P2 HFT	HALIFAX	18393.0	250.3	N/A	21142.70 ~~21393.00~~					

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD SIGNATURE	NO. CERT. NO	DATE
1745:26	OVERHAULED WITH M/R HUB ASSY IAW BHT-212-CR&O REV. 12.	OH 22834-0	OH-06	07DEC20

7861 56717REV 994

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1.)

NOMENCLATURE PITCH HORN ASSY
PART NUMBER 204-011-120-005
SERIAL NUMBER REFS 3560
PAGE 1 OF 1

Bell Helicopter
A Textron Company
Post Office Box 482. Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS RIN	 SINCE O/H HRS COMP. HRS RIN	COMP. HRS. RIN	DATE	REMOVED AT MRH A/C HOURS A/C RIN	COMP. HRS/RIN SINCE NEW HRS RIN	 SINCE O/H HRS RIN	REASON FOR REMOVAL
07JUN12	ADA-01227	HALIFX	16829:42	0.0	NEW	3000HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE
1465:56	OVERHAULED WITH M/R HUB ASSY IAW BHT-212-CR&O REV. 12.	OH 22034-0	OH-06	07DEC20

RNY

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1).

NOMENCLATURE BUSHING
PART NUMBER 204-011-135-105
SERIAL NUMBER D I-21883
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
Post Office Box 482. Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS RIN	COMPONENT HOURS/RIN SINCE O/H HRS COMP. HRS RIN	COMP. HRS. RIN	DATE	REMOVED AT MRH A/C HOURS A/C RIN	COMP. HRS/RIN SINCE NEW HRS RIN	COMP. HRS/RIN SINCE O/H HRS RIN	REASON FOR REMOVAL
10 DEC 2020	AOA -01237	OH 22843-0	18295:38	0.0	NEW	3600HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1)

NOMENCLATURE BUSHING
PART NUMBER 204-011-135-105
SERIAL NUMBER DI-21975
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
Post Office Box 482. Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS / A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS / RIN	COMPONENT HOURS/RIN SINCE O/H HRS COMP. HRS / RIN	COMP. HRS. RIN	DATE	REMOVED AT MRH A/C HOURS / A/C RIN	COMP. HRS/RIN SINCE NEW HRS / RIN	COMP. HRS/RIN SINCE O/H HRS / RIN	REASON FOR REMOVAL
10DEC 2020	ADA -01237	OH 22843-0	18295:38	0.0	NEW	3600HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1)

NOMENCLATURE BUSHING
PART NUMBER 204-011-135-105
SERIAL NUMBER DI-22250
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
Post Office Box 482. Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS RIN	COMPONENT HOURS/RIN SINCE O/H HRS COMP. HRS RIN	COMP. HRS. RIN	DATE	REMOVED AT MRH A/C HOURS A/C RIN	COMP. HRS/RIN SINCE NEW HRS RIN	COMP. HRS/RIN SINCE O/H HRS RIN	REASON FOR REMOVAL
10DEC 2020	ADA -01237	OH 228430	18295:38	0.0	NEW	3600HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1)

NOMENCLATURE BUSHING
PART NUMBER 204-011-135-105
SERIAL NUMBER DI-22073
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
Post Office Box 482. Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT MRH A/C HOURS / A/C RIN	COMPONENT HOURS/RIN SINCE NEW HRS COMP. HRS / RIN	COMPONENT HOURS/RIN SINCE O/H HRS COMP. HRS / RIN	COMP. HRS. / RIN	DATE	REMOVED AT MRH A/C HOURS / A/C RIN	COMP. HRS/RIN SINCE NEW HRS / RIN	COMP. HRS/RIN SINCE O/H HRS / RIN	REASON FOR REMOVAL
10DEC 2020	ADA -01237	OH 22843-C	18295:38	0.0	NEW	3600HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1)

ABU DHABI AVIATION
ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES

WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L No.	

NOMENCLATURE	DRAG BRACE	PART NO.	204-011-140-005	SERIAL NO.	A-3884
MANUFACTURER		RETIREMENT TIME (If Applicable)		OVERHAUL INTERVAL	

INSTALLATION DATA							REMOVAL DATA				
DATE	INSTALLED ON MRH S/N		BY	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS SINCE NEW	COMP. HOURS/LDGS SINCE O/H	DATE	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS SINCE NEW	COMP. HOURS/LDGS SINCE O/H	REASON FOR REMOVAL
9-Nov-13	ADA-01237		HELIFIX	17354:50	0:00	NEW					

TECHNICAL DIRECTIVES

TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DATE	WORKSHEET/GRN

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (SPECIFY)	TSN	REPAIR STATION & WORK ORDER	REMARKS AND MAJOR PART REPLACED	DONE BY/GRN
14AUG16	INSP.	129.48	OH19740-R	1200 HR / 24 MTH INSP. C/OUT	OH-11
07DEC20	O/H	940:48	OH22834-O	OVERHAULED WITH M/R HUB IAW BHT-212-CR&O REV. 12	OH-06

ABU DHABI AVIATION

ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES

WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L No.	

NOMENCLATURE	DRAG BRACE	PART NO.	204-011-140-005	SERIAL NO.	A-3904
MANUFACTURER		RETIREMENT TIME (If Applicable)		OVERHAUL INTERVAL	

INSTALLATION DATA

DATE	INSTALLED ON MRH S/N		BY	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS SINCE NEW	COMP. HOURS/LDGS SINCE O/H
9-Nov-13	ADA-01237		HELIFIX	17354:50	0:00	NEW

REMOVAL DATA

DATE	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS SINCE NEW	COMP. HOURS/LDGS SINCE O/H	REASON FOR REMOVAL

TECHNICAL DIRECTIVES

TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DATE	WORKSHEET/GRN

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (SPECIFY)	TSN	REPAIR STATION & WORK ORDER	REMARKS AND MAJOR PART REPLACED	DONE BY/GRN
14AUG16	INSP.	129:48	OH19740-R	1200 HR/24 MTH INSP. C/OUT.	OH-11
07DEC20	O/H	940:48	OH22834-O	OVERHAULED WITH M/R HUB ASSY IAW BHT-212-CR&O REV.12	OH-06

DESCRIPTION	M/R GRIP ASSY
PART NUMBER	204-011-121-121G
SERIAL NUMBER	A-6063
2 OF	2

Helifix Engineering Ltd
Portion 1536, Jacksons Parade,
Jacksons International Airport,
Port Moresby 121, NCD, PNG

NOTICE: When returning any limited life components to BHTC/BHTI for any reason, it is mandatory that a valid historical service record accompany the component.

DOM: _____

HISTORICAL SERVICE RECORD.

INSTALLATION DATA						OH INSPV RETIRE.	REMOVAL DATA				
DATE	INSTALLED ON A/C #	BY (Activity)	INSTALLED AT A/C Hrs A/C RIN	COMPONENT HOURS/RIN SINCE NEW COMP HRS RIN	SINCE OH COMP HRS RIN	Due OFF @ A/C TTIS Other	DATE	REMOVED AT A/C Hrs A/C RIN	COMPONENT HOURS/RIN SINCE NEW COMP HRS RIN	SINCE OH COMP HRS RIN	REASON
9/4/2012	P2-HFT	HELIFIX	18,393.00	2,724.30	815.80	O/C	09-11-13	19035.1	3366.4	1457.9	DVE INSP FOR 1200HR/24MO
09-11-13	P2-HFT	HELIFIX	19035.1	3366.4	1457.9	O/C					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL.

DIRECTIVE # IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
ASB 212-02-116	3031.8	ULTRASONIC INSPECTION C/W ON M/R GRIP S/N: A-6063 & A-6062 ,@ 18700.5 TAT IAW ASB 212-02-116 REV A & B212 MM 5-34	Helifix 145/026	12/4/2013
	3366.4	1200 HR/24 MONTH INSP C/O IAW BHT 212 MM 5-40	Helifix 145/026	09-11-13
	3496:24	FAA AD 2014-12-04 Para 2, Para 3, Para 4 c/w. 1200 HRS/24 MTH INSP. C/O UT.	OH19740-R	14 AUG 16
	4307:14	FAA AD 2014-12-04 PARA 2, PARA 3, PARA 4, PARA 5 C/W ITH.	OH22043-O	07 DEC 20

COMPONENT NAME M/R GRIP ASSY

PART NUMBER 204-011-121-121G

SERIAL NUMBER A-6063

PAGE 1 OF

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

	GRN 15113

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON M/R Serial No.	BY (ACTIVITY)	INSTALLED AT Assy Hours	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	HRS. / DATE	DATE	REMOVED AT Assy Hours	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	REASON FOR REMOVAL
140301	ADA-01237	ADA	13988.42	NIL	NEW						
09.04.12	R2-HFT 32125	HELIFIX	18393.00	2724.3	815.80	O/C					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
ASB 212-02-116	648.17	Ultrasonic Inspection of lower tangs. (Initial Inspection)	WS OH 7205R	18Aug02
AD 2003-01-04		(M/R GRIP) COMPLIED WITH.	TS 212/014	190103
ASB 212-02-116 Rev A AD 2003-01-04	842.33	Ultrasonic and Grip Pads Inspections carried out.	ADA WS OH 7466R	19Mar03
ASB 212-02-116 REV A	986.42	Ultronsonic inspection of the lower tang carried out.	W/s 01073BW01	01-07-03
ASB 212-02-116RA	1094.42	Ultrasonic inspection of Lower Tang C/out.	WS 12083BW01	12Aug03
ASB212-02-116 REV.A	1574.67	ULTRASONIC INSPECTION AND NDT INSPECTION CARRIED OUT.	ADA WS OH-9465-R	24JAN05
ASB212-02-116 R.A	1816.08	Ultrasonic inspection and NDT inspection carried out.	ADA OH10472-R	08DEC05
	1908.50	Overhauled AD 2003-01-04 (ASB 212-02-116 R.A) and ASB 212-94-92 R.A complied with	ADA OH 11649-O	23FEB07
	2951.9	Ultrasonic Inspection C/W @ 18620.6 A/F I.AW B212MM-5-34 ULTRA SONIC TEST	Helifix Job# HK-0593	02/09/12
		KIT P/N: USM22G, S/N Y001C3A NEXT CAL DUE: 13/04/13		
ASB212-02-116 (IN)	3031.8	Ultrasonic Inspection C/W ON M/R GRIPS P/N: 204-011-121-121G, S/N: A-6063 &	HELIFIX JOB# HET-4213	12/04/13

REFER PG 2

DESCRIPTION: M/R GRIP ASSY
PART NUMBER: 204-011-121-121G
SERIAL NUMBER: A-6062
2 OF 2

Helifix Engineering Ltd
Portion 1536, Jacksons Parade,
Jacksons International Airport,
Port Moresby 121, NCD, PNG

NOTICE: When returning any limited life components to BHTC/BHTI for any reason, it is mandatory that a valid historical service record accompany the component.

DOM: _____

HISTORICAL SERVICE RECORD.

INSTALLATION DATA						OH INSPV RETIRE.	REMOVAL DATA				
			INSTALLED AT	COMPONENT HOURS/RIN				REMOVED AT	COMPONENT HOURS/RIN		
DATE	INSTALLED ON A/C #	BY (Activity)	A/C Hrs A/C RIN	SINCE NEW COMP HRS RIN	SINCE OH COMP HRS RIN	Due OFF @ A/C TTIS Other	DATE	A/C Hrs A/C RIN	SINCE NEW COMP HRS RIN	SINCE OH COMP HRS RIN	REASON
9/4/2012	P2-HFT	HELIFIX	18,393.00	2,724.30	815.80	O/C	09-11-13	19035.1	3366.4	1457.9	1200HR/24MTH INSP
09-11-13	P2-HFT	HELIFIX	19035.1	3366.4	1457.9	O/C					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL.

DIRECTIVE # IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
ASB 212-02-116	3031.8	ULTRASONIC INSPECTION C/W ON M/R GRIP S/N: A-6063 & A-6062 ,@ 18700.5 TAT IAW ASB 212-02-116 REV A & B212 MM 5-34	Helifix 145/026	12/4/2013
	3366.4	1200 HR/24 MTH INSP C/O IAW B212 MM 5-40	HELIFIX 145/026	09-11-13
	3496.24	FAA AD 2014-12-04 Para 2, Para 3, Para 4 4w. 1200 HRS/24 MTH INSP. C/OUT	OH 19740-R	14 AUG 16
	4307:14	FAA AD 2014-12-04 PARA2, PARA3, PARA4, PARA 5 C/W ITH.	OH 22843-O	07 DEC 20

COMPONENT NAME M/R GRIP ASSY
PART NUMBER 204-011-121-121G
SERIAL NUMBER A-6062
PAGE 1 OF

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

	GRN 15113

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON. M/R Serial No.	BY (ACTIVITY)	INSTALLED AT. Assy Hours	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	HRS. / DATE	DATE	REMOVED AT Assy Hours	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O / H	REASON FOR REMOVAL
140301	ADA-01237	ADA	13988.42	NIL	NEW						
09.04.12	P2-HFT 32125	HELIFIX	18393.00	2724.30	815.8	O/C					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
TB.212-81-56		Modification to Grease Lubrication.	ADA WS OH 6176R	140301
ASB 212-02-116	648.17	Ultrasonic Inspection of lower Tangs. (Initial Inspection)	ADA WS OH 7205R	18Aug02
AD 2003-01-04		(M/R GRIP) COMPLIED WITH.	TS 212/014	190103
ASB 212-02-116 Rev A AD 2003-01-04	842.33 HAW	Ultrasonic inspection and Grip Buffer Pads inspection carried out.	ADA WS OH 7466R	19Mar03
ASB212-02-116 REV.A	986.42	Ultronsonic inspection of lower tang carried out.	WS 01073BW01	01-07-03
ASB 212-02-116RevA	1094.42	Ultrasonic inspection of Lower Tang C/out.	WS 12083BW01	12Aug03
ASB 212-02-116REV A	1574.67	ULTRASONIC INSPECTION AND NDT INSP. CARRIED OUT.	ADA WS OH-9465-R	24JAN05
	1816.08	Ultrasonic inspection and NDT inspection carried out.	ADA OH10472-R	08DEC05
	1908.50	Overhauled AD 2003-01-04 (ASB 212-02-116 R.A) and ASB 212-94-92 R.A complied with	ADA OH 11649-O	23FEB07
	2951.9	Ultrason Insp C/W I.A.W BHT212-MM.5-34 @ 18620.6 HRS, ULTRA SONIC TEST KIT P/N USM22B, S/N Y001C3A. NXT CAL 13/04/13	HELIFIX JB HL-0593	02/09/12

NOMENCLATURE PILLOW BLOCK
PART NUMBER 204-011-108-119
SERIAL NUMBER TI-44
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc.
Post Office Box 482. Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	– REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN			DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
	MRH		MRH	HRS COMP. HRS	HRS COMP. HRS	COMP. HRS.		MRH			
			A/C HOURS					A/C HOURS	HRS	HRS	
			A/C RIN	RIN	RIN	RIN		A/C RIN	RIN	RIN	
10DEC 2020	ADA -01237	OH 22843-0	18295:38	0.0		~~2400 ROL~~ 4					
				0.0							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN (Retirement Index Number) Accumulation Instructions (Model 204 refer to Section 1.).

COMPONENT NAME PILLOW BLOCK
PART NUMBER 204-011-108-119
SERIAL NUMBER TI-4
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc
POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: When returning any limited life component to BHTI for any reason, it is mandatory that a valid HISTORICAL SERVICE RECORD accompany component.

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	REMOVAL DATA				
DATE	INSTALLED ON AIRCRAFT SERIAL NO. MRH	BY (ACTIVITY)	INSTALLED AT A/C HRS. MRH RIN	COMP. HRS./RIN SINCE NEW COMP. HRS. RIN	COMP. HRS./RIN SINCE O/H COMP. HRS. RIN	COMP. HRS. RIN	DATE	REMOVED AT A/C HRS. MRH RIN	COMP. HRS./RIN SINCE NEW COMP. HRS. RIN	COMP. HRS./RIN SINCE O/H COMP. HRS. RIN	REASON FOR REMOVAL
10DEC 2020	ADA -01237	OH 22843-0	18295:38	0.0	NEW	~~OH 2400 HRS~~ 4th					

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY Signature affirms work performed IAW FAR Part 43. SIGNATURE	CERT. NO.	DATE

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to Section 1.).