

ABU DHABI AVIATION ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES
WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L NO.	

NOMENCLATURE							PART NO.			SERIAL NO.		
M/R HUB ASSY							204-012-101-153GFM			ADA-01007		
MANUFACTURER							RETIREMENT TIME (If Applicable)			OVERHAUL INTERVAL		
CARD No10										2400 HOURS		
INSTALLATION DATA							REMOVAL DATA					
DATE	INSTALLED ON ACFT/EQUIP		BY	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS		DATE	TOTAL HRS/LDS ACFT/EQUIP	COMP. HOURS/LDGS		REASON FOR REMOVAL	
	TYPE	ACFT/EQUIP			SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H		
15-Mar-15	212	A6-BAC	ADA	15228:35	18862:24	1840:00	05 APR 2018	15713:40	19347:29	2325:05	DUE OVERHAUL	
22 JAN 19	212	A6-BBV	ADA	19590:45	19347:29	0:00	22 JAN 21	19621:10	19377:54	30:25	TT STRAP REPLACEMENT	
					19377:54	751 0:00						

TECHNICAL DIRECTIVES				
TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DATE	JOB No.
FAA AD 2014-12-04 Para 3 & 4	11-Mar-15	M/R grip Ultrasonic inspection c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-02-116 Rev A	11-Mar-15	M/R grip Ultrasonic inspection c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-02-59 & FAA AD 90-26-11	11-Mar-15	Drag Brace MPI c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-02-117	11-Mar-15	1200 hour of Hub pins c/out.	11-Mar-15	ADA -OH18406-R
TB-212-99-170	11-Mar-15	Previously complied with.	11-Mar-15	ADA -OH18406-R
ASB 212-94-94	11-Mar-15	1200 hour inspection of M/R yoke carried out.	11-Mar-15	ADA -OH18406-R
ASB 212-94-92 Rev A	11-Mar-15	M/R grip conditional inspection c/out.	11-Mar-15	ADA -OH18406-R
ASB 212-10-142 Rev B	11-Mar-15	Inboard strap fitting MPI c/with.	11-Mar-15	ADA -OH18406-R
ASB 212-12-144	11-Mar-15	M/R Grip inspection and rework C/out.	11-Mar-15	ADA -OH18406-R
FAA AD 2013-03-16	11-Mar-15	Inboard strap fitting MPI c/with.		
FAA AD 2014-12-04 PARA 4	03 APR 17	M/R GRIP ULTRASONIC INSP. C/OUT.	03 APR 17	BAC-000228

CARD NO. **U/PARA 3**

PERMANENT F

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (SPECIFY)	TSN	REPAIR STATION	REMARKS AND MAJOR PART REPLACED	W/O #
11-Mar-15	REPAIR	18862:24	ADA OH18406R	1200 hour/24 month inspection c/out IAW BHT-212-CR&O Rev.9-- TT Straps LPFS-27985/27602 replaced by LPFS-33723/33745. Drag Brace A-599/A-603 replaced by A-350/A1-07403.	OH18406-R
20 MAR 15 18 MAY 16	INSP INSP	18862:24 18998:10	BAC-000044/0016 BAC-000169/79	6 MTH INSP. C/OUT. 6 MTH INSP. C/OUT.	MOOH FAASA
03 APR 17	REPLACE	19113:24	BAC-000228	TT STRAPS LPFS 33745 & LPFS 33723 REPLACED BY S/N: LPFS 36061 & LPFS 36063	FAASA
10 APR 17 27 SEP 17	INSP INSP	19113:24 19265:24	BAC-000228 BAC-000233	6 MTH INSP C/OUT. 6 MTH INSP. C/OUT	FAASA. MO75
03 OCT 18	O/H	19347.29	OH 21464-0	Overhauled IAW BHT 212 CR&O R10. M/R Strap Pins S/N DIFS17958, DIFS17971, DIFS18004, DIFS18089 replaced by S/N DIFS20711, DIFS20969, DIFS20900, DIFS20552. Bushings S/N BT10363, BT10437, BT10438, BT10505 replaced by S/N DI22279, DI22182, DI21833, DI22185. TT Strap S/N LPFS36061, LPFS36063 replaced by S/N LPFS36305, LPFS36307. Pitch Horn S/N MWFS632, MWFS809 replaced by S/N REFS3542, REFS3526.	OH-06
				ASB 212-02-116 Rev A, FAA AD 2014-12-04, ASB 212-90-59 (FAA AD 90-26-11), TB 212-99-170, ASB 212-10-142 Rev B Part 1 and Part 2, FAA AD 2013-03-16 Complied With. ASB 212-94-94, ASB 212-94-92 Rev. A, ASB 212-15-152 Previously Complied With.	
22 JAN 19	INSP.	19347.29	BBV-000211/0110	6 MTH INSP. C/OUT.	M-011
10 JUN 2021	INSP	19377:54	OH 23439-R	1200 HR / 24 MTH INSP C/O IAW BHT-212-CR&O, REV.13. TT STRAPS S/N LPFS 36305 & LPFS 36307 REPLACED BY S/N LPFS 38633 & LPFS 38616.	ADA TRM OH 06.

ABU DHABI AVIATION

ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES
WHEN THE ITEM IS INSTALLED. THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

CARD NO. 9

P/L No. GRN No.

NOMENCLATURE MAIN ROTOR HUB ASSY

PART NO. 204-012-101-~~029~~¹⁵³ GFM

SERIAL NO. ADA-01007

MANUFACTURER

RETIREMENT TIME (If Applicable)

OVERHAUL INTERVAL 2400 HRS.

INSTALLATION DATA

REMOVAL DATA

DATE	INSTALLED ON AIRCRAFT		BY	HRS / LDS TOTAL ACFT./EQUIP	COMP. HOURS / LDGS		DATE	TOTAL ACFT./EQUIP HRS / LDGS	COMP. HOURS / LDGS		REASON FOR REMOVAL
	TYPE	REG. NO.			SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
31JAN05	212	EP-NAG	ADA	15254.50	16378.67	1391.00	30Oct05	15850.67	16974.83	1987.17	Grip NDT insp & buffe
02Nov05	212	A6-BBC	ADA	30149.92	16974.83	1987.17	18FEB06	30197.50	17022.42	2034.75	A/C UNDERGOING MAJOR INSP
29Mar06	212	A6-BBC	ADA	30200.67	17022.42	0.00	24Jun07	30720.42	17542.17	519.75	TT straps due retire
10Jul07	212	A6-BBC	ADA	30720.42	17542.17	519.75	21Mar08	31212.25	18034.00	1011.58	Sub-Assy RT.
23May08	212	A6-BBL	ADA	24326.17	18034.00	1011.58	30Jun09	24833.17	18541.00	1518.58	TT Strap due RT
29 AUG 2009	212	A6-BBC	ADA	31759.83	18541.00	1518.58	12Apr11	31930.00	18701.17	1678.75	ASB 212-10-142 Rev A comp
27Jul11	212	A6-BBS	ADA	24362.67	18701.17	1678.75	31Jul11	24364.58	18703.08	1680.67	vibration.
15.4.12	212 RAC	P2-HFV	Helifix	15224.0	18703.08	1680.67	19/09/12	15224.0	18860.78	1839.45	Removed for ops
19/09/12	212 BRW	P2-HFP	Helifix	18028.9	18860.78	1839.45	22/01/13	18030.0	18861.88	1839.47	Removed for ops
18 JAN 13	212 RAC	P2-HFV	Helifix	15224.0	18861.98	1839.59	11 FEB 14	15224.25	18862.24	1839.78	

TECHNICAL DIRECTIVES

TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DONE BY
ASB 212-02-116 Rev. A	17022.42	ASB 212-02-116 Rev.A complied with. (Ultrasonic insp. of MYR Grips).	OH-10697-O OH-12
ASB 212-02-117	17022.42	ASB 212-02-117 complied with. (1200 Hrs Special Insp. for Pin)	
FAA AD2003-01-04 Pt C	17542.17	Ultrasonic inspection of grips complied with.	WS OH 11995R
	18034.00	AD 2003-01-04 (ASB 212-02-116 Rev.A), AD 90-26-11 (ASB 212-90-59), AD 79-20-05, ASB 212-02-117, ASB 212-94-94, ASB 212-94-92 Rev.A and TB 212-99-170 PCW.	WS OH 12818R
	18701.17	FAA AD 2003-01-04 (ASB 212-02-116 REV.A), FAA AD 90-26-11 (ASB 212-90-59), ASB 212-02-117, ASB 212-94-94, ASB 212-94-92 Rev.A., ASB 212-10-142 Rev.B (FASAAD 2010-0246R1, FAA AD 2011-08-01) Complied With. TB 212-99-170 Previously complied with.	WS OH 15643-R

OVERHAUL AND SIGNIFICANT REPAIR

DATE	OVERHAUL OR REPAIR (Specify)	TSN	REPAIR STATION	REMARKS AND MAJOR PART REPLACED	SIGNATURE AUTHORISATION
15JAN05	REPAIR	16378.67	ADA WS OH-9441-R	REPAIRED C/O IAW BHT-212-CR&O. M/R GRIP ULTRASONIC INSP. C/OUT. PITCH HORN S/N REFS-2201, REFS-2214 REPLACED BY S/N MWS-809, MWS-632. INB. STRAP FITTING S/N A-5709, A-5715 REPLACED BY S/N A-7841, A-7816. FISHINGS S/N DI-21016, DI-21262, DI-21852, DI-21936 REPLACED BY S/N BT-10363, BT-10438, BT-10505, BT-10437.	OH 04 / OH
03FEB05 03AUG05 31Oct05	INSP. INSP. Insp	16378.67 16776.58 16974.83	ADA WS 600/2NAG05 ADA WS03085NAG01 ADA OH 10352R	6 MONTHLY INSPECTION CARRIED OUT. 6 MONTHLY INSPECTION CARRIED OUT. Grip NDT inspection and ADB 212-02-116 Rev A carried out.	6330802 5880317 M 004
01Nov05 05DEC05 28Mar06	Insp. INSP Overhaul	16974.83 16996.83 17022.42	WS 26105BC01 WS 03125BC01 WS OH-10697-O	6Mth insp. c/out. 6 month inspection carried out. Overhauled iaw BHT-212-CR&O Revision No. 5.	M 004. M 021 OH 12
06May06	Insp.	17024.17	WS 06056BC46	TT Strap S/N LPFS-18033, LPFS-18034 replaced by S/N LPFS-19559, LPFS-20186. Strap Pin S/N DIFS-14804, DIFS-14884, DIFS-14934, DIFS-14965 replaced by S/N DIFS-17958, DIFS-17971, DIFS-18004, DIFS-18089.	M 025
29Oct06 27Jun07	insp. Repair	17210.33 17542.17	WS 18104BC98 WS CH 11995R	6 monthly inspection carried out. TT straps S/N LPFS-19559/LPFS-20186 replaced by LPFS-20624/20610. Ultrasonic current insp c/out on M/R grips.	M 012 OH -01
10Jul07 08Feb08 13Apr08	Insp. Insp Insp.	17542.17 17979.33 18034.00	WS 28057BC03 WS 080208BC26 WS OH-12818R	6 Mth insp. c/out. 6 mth inspection c/out. 1200 Hrs/24 Mths Inspection carried out IAW BHT 212 MM Ch. 5 Rev 8 & 212 CR&O Rev 6. Outboard Fittings A-15657, A-16020 replaced by A-17700, A-17749. AD 2003-01-04 (ASB 212-02-116 Rev A); AD 90-26-11 (ASB 212-90-59); ASB 212-94-94; ASB 212-94-92 Rev. A; ASB 212-02-117; AD 79-20-05 complied with and TB 212-99-170 previously complied with.	M 011 M 022 OH 11
20Jul08 21Jan09	Inspect Insp.	18153.17 18446.08	WS 010708BL23 WS 190109BL69	6 month inspection c/out. 6 Mth insp. c/out.	M 027 M 022
20Jul09	Insp	18541.00	WS OH 14258R	1200hr/24mth insp C/out iaw BHT 212-MM Chap 5 Rev 9 and 212 CR&O Rev. 7. TT strap LPFS-20610/20624 replaced by LPFS-22970/22781. Inbd fittings S/N A-7841/7816 replaced by A-3960/8995.	OH 11
23Aug09 23Feb10 29Aug10	Insp. Insp. Insp.	18541.00 18610.33 18621.50	WS 070309BC29 WS 270210BC96 WS 280810BC50	6 mth insp. c/out. 6 mth insp. c/out. 6 mth insp. c-out.	M 047 M 010 M 048
27Jul11 27Jul11	Insp Insp	18701.17 18701.17	WS OH-15643-R WS 270711BS29	1200hr/24Mth insp c/out IAW BHT-212-CR&O Rev.9 & ASB 212-10-142 Rev.B C/with TT Strap S/N LPFS-22781, LPFS-22970 replaced by S/N LPFS-27985, LPFS-27602. 6 Mth insp c/out.	OH 11 M 083

COMPONENT NAME M/R HUB ASSY.
PART NUMBER 204-012-101-029G
SERIAL NUMBER ADA-01007
PAGE 9A OF

HISTORICAL SERVICE RECORD - CONTINUATION SHEET

[illegible]

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	TOTAL TIME (HRS)	REMOVAL DATA	
		DATE Assy HRS	ACCUMULATED TIME ON ASSEMBLY OR PART		DATE Assy HRS		ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: STRAP PIN ASSY	DIFS-5102	11277.17	568.58	-	2400	18973.42	4264.83	TIMEX
	DIFS-5306	11277.17	568.58	-	2400			
NO.: 204-012-104-005	DIFS-5346	11277.17	568.58	-	2400			
	DIFS-5380	11277.17	568.58	-	2400			
NAME: OUTBOARD FITTING	A-437	11277.17	655.33	-	3600	11775.75	3552.58	HI TIME
NO.: 204-012-103-005	A-448	11277.17	655.33	-	3600	11775.75	3552.58	HI TIME
NAME: PITCH HORN	RE-4378	11277.17	1886.83	-	3000	12381.58	2991.25	TIMEX
NO.: 204-011-120-005	RE-4447	11277.17	1886.83	-	3000	12381.58	2991.25	TIMEX
NAME: T/T STRAPS	LKFS-3806	11277.17	648.33	-	1200/2 Years	11775.75	1146.92	HI TIME
NO.: 204-310-101-101	LKFS-3832	11277.17	648.33	-	1200/2 Years	11775.75	1146.92	HI TIME
NAME: pitch horn	REFS-1093	15.11.97	2792.67	403.67	3000	13472.25	2994.17	TIMEX
NO.: 204-011-120-005	REFS-1121	13270.75			3000	13472.25	2994.17	TIMEX
NAME: PITCH HORN	TKFS-29	13472.25	2381.50	-	3000	14081.17	2990.42	TIMEX
NO.: 204-011-120-005	TKFS-214	030198	2381.50	-	3000	14081.17	2990.42	TIMEX
NAME: PITCH HORN	REFS-2201	191198	570.75	-	3000	16378.67	2868.25	TIMEX
NO.: 204-011-120-005	REFS-2214	14081.17	570.75	-	3000	16378.67	2868.25	TIMEX
NAME: T/T STRAPS	LPFS-9869	14143.50	NIL	-	1200/2 years	14371.08	227.58	Cal Timex
NO.: 204-310-101-101	LPFS_9877	14143.50	NIL	-	1200/2 years	14371.08	227.58	Cal Timex
NAME: I/B FITTINGS	A-5709	14143.50	NIL	-	2400	16378.67	2235.17	HIGH TIME
NO.: 2120010-103-007	A-5715	14143.50	NIL	-	2400	16378.67	2235.17	HIGH TIME
NAME: M/R GRIP ASSY	* LL-0198	14143.50	15151.67	0.0	1200/2 years	14370.58	15378.75	227.08
204-011-121-009G *								
204-011-121-121G	A-5347	14370.58	3019.25	651.50		14370.58	3019.25	651.50

COMPONENT NAME MAIN ROTOR HUB
PART NUMBER 204-012-101-294
SERIAL NUMBER ADA - 01007
PAGE 7A+8A OF

HISTORICAL SERVICE RECORD - CONTINUATION SHEET

[illegible]

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	TOTAL Assembly TIME (HRS)	REMOVAL DATA	
		DATE AIRCRAFT HRS	ACCUMULATED TIME ON ASSEMBLY OR PART		DATE AIRCRAFT HRS		ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: DRAG BRACE.	A.599 ✓	10103:40	NK	00:00	RETURN TO ASSEMBLY LOG			
NO.: 204-011-140-005	A.603 ✓	10103:40	NK	00:00	CARDS FOR O/H DETAILS			
NAME: MR GRIP.	511-36078	9419:15	NK	00:00		11043.92	NK	1624.67
NO.: 204-011-121-009.								
NAME: BUSHING.	BT-591 ✓	10103:40	NEW	00:00		12973.42	2869.75	TIME
NO.: 204-011-135-105	BT-413 ✓	10103:40	NEW	00:00				
NAME: BUSHING	BT-59 ✓	10103:40	NEW	00:00				
NO.: 204-011-135-105	BT-82. ✓	10103:40	NEW	00:00				
NAME: PITCH HORN ASSY	CH-163	11043.92	2536.00	0.0	3000	11277.17	2905.08	-
NO.: 204-011-120-005	REFS-135	11043.92	2671.83	-	3000	11277.17	2769.25	-
NAME: INBOARD FITTING	A-3503	11043.92	2080.33	-	2400	11277.17	2313.58	-
NO.: 212-010-103-007	A-3507	11043.92	2080.33	-	2400	11277.17	2313.58	-
NAME: STRAP PIN ASSY	VT-11779	11043.92	2080.33	-	2400	11277.17	2313.58	-
	VT-12464	11043.92	2080.33	-	2400	11277.17	2313.58	-
NO.: 204-012-104-005	VT-12471	11043.92	2080.33	-	2400	11277.17	2313.58	-
	VT-12499	11043.92	2080.33	-	2400	11277.17	2313.58	-
NAME: T.T. STRAP ASSY	BNFS-46420	11043.92	884.42	-	1200/2 Yrs	11277.17	1117.67	-
NO.: 204-012-122-005	BNFS-46565	11043.92	884.42	-	1200/2 Yrs	11277.17	1117.67	-
NAME: M/R GRIP ASSY	LL-0860	11043.92	NK	0.0		11775.75	-	731.83
NO.: 204-011-121-009 RRG	5278-9	11043.92	13863.67	0.0		11775.75	-	731.83
NAME: I/B FITTING	A-2950	11277.17	1745.42	-	2400	11775.50	2244.00	NI TIME
212-010-103-007	A-3608	11277.17	1745.42	-	2400	11775.50	2244.00	NI TIME

REFER TO INDIVIDUAL LOG CARDS FOR SUBASSEMBLIES
COMPONENT NAME **MAIN ROTOR HUB ASSY**

PART NUMBER **204-012-101-029GFM**

SERIAL NUMBER **ADA-01007**

PAGE **8** OF

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

INSTALLATION DATA						A / C HOURS SCH. FOR ☒ O / H ☐ RETIRE X HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A / C NO.	BY (ACTIVITY)	INSTALLED AT A / C HRS.	COMP. HRS.			DATE	REMOVED AT A / C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O / H				SINCE NEW	SINCE O / H	
16-11-00	A6-BBS	ADA	17351.92	14311.00	167.50		2400 1200	131200	17411.50	14370.58	227.08
290301	A6-BBK	ADA	22100.08	14370.58	227.08		280301	22100.58	14371.08	227.58	I/T Str x Cal.
090401	A6-BBY	ADA	14252.50	14371.08	227.58		20Aug02	14869.08	14987.67	844.17	Trunnion Timex
28Mar03	A6-BBA	ADA	24343.67	14987.67	0.0		14Nov03	24562.17	15206.17	218.50	RTS BAB
14Nov03	A6-BAB	ADA	15949.75	15206.17	218.50		03Mar04	16523.33	15779.75	792.08	Ops Rec
10Apr04	A6-BBS	ADA	20140.75	15779.75	792.08		05 AUG.04	20420.67	16059.67	1072.00	1200HR/24 INSP.
08 AUG.04	A6-BBS	ADA	20420.67	16059.67	1072.00		31DEC04	20739.67	16378.67	1391.00	IB STRAP & TNG PL-TTN

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
	14371.08	Replaced I/T Straps. Drag Braces & Yoke 1200 Hr/24 Mth Insp C/O IAW		
		ASB 212-90-59 & ASB 212-94-94.	ADA WS OH 6231R	29Mar01
AD 2003-01-04		(M/R GRIP) COMPLIED WITH.	TS 212/014	190103
	14987.67	Overhauled iaw Bell 212 CR & O manual/Form ADA/OH/212/01 REV 1 Nov 02		
		Tech. Dir. c/o : ASB 212-02-116, ASB 212-02-117 and AD 2003-01-04.	OH 006	23FEB03
ADA WS 600/3AB03	15206.17	6 Monthly Inspection Carried Out. ASB 212-02-116 Rev A Complied With.	M 085 & M 004	15Nov03
WS OH 8935-R	16059.67	6 MONTH INSP. C/O. - ASB 212-02-116 REVA C/O. - TT STRAP SNOS. LPFS-15376 & LPFS15590	OH 12 & OH 04	07 AUG.04
		REPLACED BY SNOS.:LPFS 18031 & LPFS 18033/ STRAP PIN SNOS. DIFS-14934,DIFS-14965,DIFS-14804, DIFS-14884 .(1200 HR. INSP. C/O.) - DRAGBRACES SN. A-599 & A-603 NDT C/O._ GRIP ASSY SN.*		
		A-6014 & A-6015 1200 HR INSP. C/O. - ASB212-02-117 C/W.		
		1200 hr./24 mths. insp. carried out		

[illegible]

COMPONENT NAME MR HUB ASSY
 PART NUMBER 204-012-101-029G FM
 SERIAL NUMBER ADA-01007
 PAGE 7 OF

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

	T.T. STRAPS (CAL.)

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A / C NO.	BY (ACTIVITY)	INSTALLED AT A / C HRS.	COMP. HRS.			DATE	REMOVED AT A / C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O / H				SINCE NEW	SINCE O / H	
12-2-96	A6- BBK	ADA	20768.08	11775.75	0.0		3.7.96	20872.00	11879.67	103.92	INSP & EVALUATION
11.9.96	A6- BBL	ADA	17488.83	11879.67	103.92		31.7.97	18582.58	12973.42	1197.67	TT STRAPS
30.8.97	A6- BBU	ADA	10468.75	12973.42	1197.67		13.4.98	11332.17	13836.83	2061.08	7MAY98
240998	A6- BBC	ADA	26635.25	13836.83	2061.08		081298	26941.92	14143.50	2367.75	Overhaul
060599	A6- BBW	ADA	11345.42	14143.50	0.0		27Mar2000	11427.25	14225.33	81.83	10MAY99
1MAY00	A6- BBA	ADA	23967.75	14225.33	81.83		10Aug2000	24053.23	14312.39	168.89	TRUNNION EXCEEDS RIN PER AD 2000-15-52
1MAY00	A6- BBA	ADA	23967.75	14225.33	81.83		10AUG00	24053.42	14311.00	167.50	AD/ASB

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		Overhauled iaw BHT CR&O manual. TSN 11775.75, TSO 0.0	ADA OH-224	110ct95
ASB 212-94-94	EQ 192A	MR Hub pitch change bearings - inner race replacement. (E-10-192 "B")	ADA OH-224	110ct95
W/S OH 285		Conditional inspection of M/R Hub Assy carried out IAW BHT 212 CR & O Manual chapter 62-20. (Overtorque above 112%) Sub Assy Items MPI & FPI Carried out. TSN 11879.67 TSO 103.92	ADA	080996
W/S 300/4BL97		600 Hr/6 Mth inspection carried out. TSN 12338.17	ADA	180197
W/S 2701BL02		Pitch Horns Replaced @ 12381.58 Assy TT see over for details	ADA	270197
WS OH-4021R		Midlife insp/replacement carried out. TSN 12973.42, TSO 1197.67	ADA	280897
W/S 0301BU02		Pitch Horns Replaced @ 13472.25 Assy TT. see cont sheet 2 for details	ADA	030198
W/S 300/9BU98		600 Hr inspection carried out. TSN 13576.17	ADA	300198
W/S 953		600 HR INSPECTION CARRIED OUT. TSN: 13836.83 TSO: 2061.08	ADA	290498

COMPONENT NAME	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL	REMOVAL DATA		
		DATE	ACCUMULATED TIME ON ASSEMBLY OR PART			DATE	ACCUMULATED TIME ON ASSEMBLY OR PART	
PART NUMBER		COMPONENT HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	COMPONENT HOURS	ASSEMBLY HOURS	SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: Trunnion	A-84		NEW	NEW				
NO.: 204-011-105-001		4625.17						
NAME: Yoke Assy	A-1156M		NEW	NEW				
NO.: 212-011-102-105		11775.75						
NAME: TT strap	BNFS-48188	11775.75	NEW	NEW	—	12973.42	1197.67	TIMEX
NO.: 204-012-122-005	BNFS-48192	11775.75	NEW	NEW	—	12973.42	1197.67	TIMEX
NAME: OB Fitting	A-13695	11775.75	NEW	NEW		23.2.03	3212.92	HI TIME
NO.: 204-012-103-005	A-13717	11775.75	NEW	NEW		14987.67		
NAME: IB Fitting	A-4110	11775.75	NEW	NEW		14143.50	2367.75	TIMEX
NO.: 212-010-103-007	A-4114	11775.75	NEW	NEW		14143.50	2367.75	TIMEX
NAME: Grip Assy	A-5347	11775.75	NEW	NEW		14143.50	2367.75	At O/H
NO.: 204-011-121-121G	A-5357	11775.75	NEW	NEW		14370.58	2594.83	227.08 RTS
NAME: Pillow Block	307770400493A	11775.75	NK	0.0				
NO.: 204-011-108-113	307770400493B	11775.75	NK	0.0				
NAME: PITCH HORN	REFS-798	12381.58	2080.83	—	3000 Hrs	15.11.97	2970.00	TIMEX
NO.: 204-011-120-005	REFS-844	12381.58	2080.83		3000 Hrs	13270.75		
NAME: Bushing	DI-21016	28 Aug 97	New	New		15JAN05	3405.25	HIGH TIME
NO.: 204-011-135-105	DI-21262	12973.42				16378.67		
NAME: TT strap	LPFS-8383	12973.42	New	New		14143.50	1170.08	TIMEX
NO.: 204-910-101-101	LPFS-8439	12973.42	New	New		14143.50	1170.08	TIMEX
NAME: PIN	DIFS-10358	28 Aug 97	New	New		23.2.03	2016.33	HI TIME
NO.: 204-012-104-005	DIFS-8797	12973.42				14987.67		

COMPONENT NAME MAIN ROTOR HUB ASY
 PART NUMBER 204-012-101-29G
 SERIAL NUMBER ADA-01007
 PAGE 6 OF

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

Overhaul (2400)	
NOTICE: WHEN RETURNING ANY LIMITED	
LIFE COMPONENT TO BHT FOR ANY	
16-04-95	T.T. Straps (Date)
THE COMPONENT	T.T. Straps (hours)

INSTALLATION DATA						A/C HOURS SCH. FOR ☒ O/H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.			DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H				SINCE NEW	SINCE O/H	
3-11-92	30777 (BC)	ADA	23326:40	9419:15	00:00	2400	25-3-92	24011:05	10103:40	684:25	Yoke Tires.
13-05-93	31227 (AB)	ADA	7287:55	10103:40	684:25		220594	8228.17	11043.92	1624.67	Op. Req.
12-6-94	30822 (BL)	ADA	14342.5	11043.92	1624.67		280794	14575.75	11277.17	1857.92	O/B Strap Fittings Time
201094	A6-BAB	ADA	8605.00	11277.17	1857.92		30-4-95	9103.58	11775.75	2356.50	T.T. STRAPS & DUE OVAL
				CONT'D ON PAGE NO. 7							

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
ASB 212-92-80		PILLOW BLOCK INSPECTION	ADA	5.4.93.
AD 93-05-01				
ADA WS 6764		Yoke, T.T. STRAPS, DAG BRACES REPLACED HUB INSPECTED, NO ASSEMBLY	ADA.	5.4.93
		BALANCED T.T. 10103:40 TSO 684:25		
ADA WS OH622		Rebond pillow block buffer pads. TSN 10241:05, TSO 821:50.	ADA/043	090793
ADA W/S OH1463		DISASSEMBLED, INSPECTED. GRIPS, PITCH HORNS, T.T. STRAPS, PINS (x4),	ADA/021	4.06.94
		I/B FITTINGS & BLADE BOLTS ALL REPLACED. RE-ASSEMBLED. @ 11043.92 HUB T.T.		
ASB 212-94-91		MAIN BLADE BOLTS RECALL - N/A BY S/N	WS 1406BL02	140694
EQ-159		Improved Inspectability-Detection of Cracks being masked by Sealant/		
		Paint. W/S OH 1656 TSN 11277.17	ADA	110894
W/S OH 1656		T/T Straps, O/B & I/B Fittings Strap Pins & Pitch Horns Replaced		
		TSN 11277.17 TSO 1857.92	ADA	110894

COMPONENT NAME PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE	INSTALLATION DATA		SCHEDULED REMOVAL DATE COMPONENT HOURS	REMOVAL DATA		
		DATE COMPONENT HOURS	ACCUMULATED TIME ON ASSEMBLY OR PART			DATE AIRCRAFT HOURS	ACCUMULATED TIME ON ASSEMBLY OR PART	
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)
NAME: 212-011-102-105 YOKE	A142 ✓	10103:40	00:00	—	11775.75	11775.75	1672.08	WARRANTY WORK SAMPLES
NO.: 204-011-102-125	A. 256	8765:15	NEW	—		10103:40	2400:30	INCLUDING FACTOR
NAME: TRUNNION	A. 84 ✓							
NO.: 204-011-105-1		4625:10	NEW	—	XFER TO CARD NO. 7			
NAME: PITCH HORN	REFS. 860	8336:55	NEW	—		11043.92	2707.00	
NO.: 204-011-120-5	REFS. 650	8336:55	NEW	—		11043.92	2707.00	
NAME: TT STRAPS	BNFS. 46065	9419:15	NEW	—		10103:40	684:25	
NO.: 204-012-122-005	BNFS. 46182	9419:15	NEW	—		10103:40	684:25	
NAME: INBD FITTING	A. 3970	9419:15	NEW	—		11043.92	1624.67	
NO.: 212-010-103-7	A. 3951	9419:15	NEW	—		11043.92	1624.67	
NAME: 1/B SNAP PIN	EA. 1063	9419:15	NEW	—		11043.92	1624.67	
NO.: 204-012-104-005	EA. 5	9419:15	NEW	—		11043.92	1624.67	
NAME: 0/B SNAP PIN	EA. 1895	9419:15	NEW	—		11043.92	1624.67	
NO.: 204-012-104-005	EA. 614	9419:15	NEW	—		11043.92	1624.67	
NAME: DRAG BRACE	A1. 01836	9419:15	NK.	00:00		10103:40	NK	684:25
NO.: 204-011-140-005	A1. 09932	9419:15	NK	00:00		10103:40	NK	684:25
NAME: 0/B FITTING	A. 11209	7679:10	NEW	—		11277.17	3598.00	—
NO.: 204-012-103-005	A. 11814	7679:10	NEW	—		11277.17	3598.00	
NAME: TT STRAPS	BNFS-46179	10103:40	NEW	—		11043.92	940.25	—
204-012-122-005	BNFS-46184	10103:40	NEW	—		11043.92	940.25	—

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

COMPONENT NAME MAIN ROTOR HUB ASSY.
PART NUMBER 204-012-101-29G
SERIAL NUMBER ADA-01007
PAGE 4 OF

6169-00	Overhaul (2400)
REASON IT IS MANDATORY THAT THIS SERVICE	
18-10-93	T.T. Straps (Date)
	T.T. Straps (hours)

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
200690	31189 (BV)	ADA	5293:55	7023:50	00:00	230790	5293:55	7023:50	0:0	RTS
230790	30794 (BH)	ADA	18047:15	7023:50	0:0	5.12.90	18702:35	7679:10	655:20	Yoke Time Ex / TTS H
080191	31180 (BT)	ADA	12061:45	7679:10	655:20	3.10.91	13145:25	8762:50	1739:00	YOKE HIGH TIME
181091	30773 (BA)	ADA	15600:45	8762:50	1739:00	031191	15603:10	8765:15	1741:25	Vibration
17.12.91	30783 (BE)	ADA	15693:25	8765:15	1741:25	290392	16135:25	9207:15	2183:25	RTS
070592	31189 (BV)	ADA	5952:25	9207:15	2183:25	21/6/92	6164:25	9419:15	2395:25	DUE OVERHAUL

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		Overhauled in accordance with Bell Component Repair and Overhaul Manual	D.A.A.S.	15 May 90
		T.T. 7023:50, T.S.O. 00:00 (Job No. 211938-2101)		
		T.B. 212-78-11, T.B. 212-86-94, AD 79-20-05, ASB 212-80-17, ASB 212-81-23,		
		ASB 212-87-43'A', ASB 212-87-44, ASB 212-87-48, ASB 212-89-55'A',		
		ASB 212-90-59, ADHM/212/85/36 compiled with.		
ADA WS NO. 911285		YOKE S/N EN-83047-6 REPLACED BY A-100. TT STRAPS LFWS 3005/3035	ADA	16.10.91
		REPLACED BY LFWS 3775/2852. ASB 212-90-59 CARRIED OUT. DNG BULBETS		
		AI-07624/07942 REPLACED BY AI-01836/09932		
ADA WS NO. Q.A. 91/29/9/10/91		T.T. STRAP PINS VERIFICATION ASB 212-91-68 SATISFIED	ADA	9.10.91
W/S NO: 911489		ASSY. DISASSEMBLED, YOKE S/N A-100 REPLACED BY S/N A-256 (TS.N. "NEW") ALONG	ADA	11.11.91
		WITH BEARINGS. HUB T.T. 8765:15, T.S.O. 1741:25 ASSY. REASSEMBLED.		
ADA WS No. 920444		MRH disassy/reassy (pillow block removal to repl seals & buffers. TSN 9207:15	ADA/EBP	06.0.92

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: Outbrd Strap Pin								
NO: 204-012-104-5	VT-8991 (R)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Outbrd Strap Pin								
NO: 204-012-104-5	VT-8983 (W)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Yoke								
NO: 204-011-102-125	EM-82812-5	4625:10	00:00	-	7679:10	3619:15	(Lifts inc)	3600
NAME: Pitch Horn								
NO: 204-011-120-5	RE-4133	5349.00	0.0	-	8336:55	2987:55	-	3000
NAME: Pitch Horn	REFS 860	8336:55	0:00	-				3000
NO: 204-011-120-5	RE-4346	5349.00	0.0	-	8336:55	2987:55	-	3000
NAME: Trunnion	REFS 650	8336:55	0:00	-				3000
NO: 204-011-105-1	A.84	4625.10	0.0	-				15000
NAME: TT Strap								
NO: 204-012-122-5	26560	5824.25	0.0	-	6604:50	780:25	(Cal tx)	1200 / 2 Yrs
NAME: TT Strap								
NO: 204-012-122-5	26562	5824.25	0.0	-	6604:50	780:25	(Cal tx)	1200 / 2 Yrs
NAME: TT STRAP	LKFS0842	6604:50	NEW	NEW	7679:10	1074:20	-	1200hr/2yrs
NO: 204-310-101-101	LKFS1167	6604:50	NEW	NEW	7679:10	1074:20	-	1200hr/2yrs
NAME: Inboard Strap Fitting	A-2800	7023:50	00:00	-	9419:15	2395:25		2400
NO: 212-010-103-7	A-2854	7023:50	00:00	-	9419:15	2395:25		2400
NAME: Inboard Strap Pin	EA-690	7023:50	00:00	-	9419:15	2395:25		2400
NO: 204-012-104-5	EA-960	7023:50	00:00	-	9419:15	2395:25		2400
NAME: Outboard Strap Pin	EA-1036	7023:50	00:00	-	9419:15	2395:25		2400
NO: 204-012-104-5	EA-1102	7023:50	00:00	-	9419:15	2395:25		2400
NAME: FITTING OUTBOARD	A-437	4625:10	00:00	-	7679:10	3054:00	(RTS)	2400 3600
NO: 204-012-103-5	A-448	4625:10	00:00	-	7679:10	3054:00	(RTS)	2400 3600
NAME: DRAG BRACE	A1-09390	NK	NK	NK	7679:10	NK		COND
NO: 204-011-140-5	A1-09405	NK	NK	NK	"	NK		COND

A Subsidiary of Textron Inc

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
BELOW IS RETURNED TO BHT. FOR ANY
REASON IT IS MANDATORY THAT THIS SERVICE
RECORD ACCOMPANY THE COMPONENT

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

[illegible]

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: PITCH HORN								
NO: 204-011-120-5	RE-2977	2358:30	00:00	-	5349.00	2990.30	(Timex)	3000
NAME: Yoke Assy.								
NO: 204-011-102-125	EM-82748-2	3475.05	0.0	-	4625:10	1150:05	-	3600
NAME: Outboard Fitting								
NO: 204-012-103-5	A1-28349	3475.05	2327.55	0.0	4625:10	3478:00	-	3600
NAME: Outboard Fitting								
NO: 204-012-103-5	A1-29574	3475.05	2327.55	0.0	4625:10	3478:00	-	3600
NAME: Retention Strap								
NO: 204-012-122-5	23447	3475.05	0.0	-	4625:10	1150:05	-	1200/2 Years
NAME: Retention Strap								
NO: 204-012-122-5	23454	3475.05	0.0	-	4625:10	1150:05	-	1200/2 Years.
NAME: T.T. Strap								
NO: 204-012-122-5	27244 (R)	4625:10	00:00	-	5824.25	1199.15	-	
NAME: T.T. Strap								
NO: 204-012-122-5	27254 (W)	4625:10	00:00	-	5824.25	1199.15	-	2400
NAME: Inboard Fitting								
NO: 212-010-103-7	A1475 (R)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Inboard Fitting								
NO: 212-010-103-7	A1486 (W)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Outboard Fitting								
NO: 204-012-103-5	A437 (R)	4625:10	00:00	-	} XFERED TO CARD NO. 2		-	
NAME: Outboard Fitting							-	
NO: 204-012-103-5	A448 (W)	4625:10	00:00	-			-	
NAME: Inbrd Strap Pin								
NO: 204-012-104-5	VT-8888 (R)	4625:10	00:00	-	7023:50	2398:40	-	2400
NAME: Inbrd Strap Pin	VT-9046							
NO: 204-012-104-5	VT-8983 (W)	4625:10	00:00	-	7023:50	2398:40	-	2400

PAGE 2 OF

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: RETENTION STRAP								
NO: 204-012-122-5	11583	47.55	0.0	-	1172.05	1124.10	-	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	11684	47.55	0.0	-	1172.05	1124.10	-	1200/2 Years
NAME: TRUNNION								
NO: 204-011-105-1	A1-10634	47.55	0.0	-	4625.10	3577.15		
NAME: RETENTION STRAP								
NO: 204-012-122-005	20731	1172.05	0.0	-	2358:30	1186:25	-	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-005	20752	1172.05	0.0	-	2358:30	1186:25	-	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	21064	2358:30	00:00	-	3475.05	1116.35 (Timex)		1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	21075	2358:30	00:00	-	3475.05	1116.35 (Timex)		1200/2 Years
NAME: INBOARD STRAP FITTING								
NO: 212-010-103-7	A-244	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: INBOARD STRAP FITTING								
NO: 212-010-103-7	A1-05294	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: INBOARD STRAP PIN								
NO: 204-012-104-5	DI-2589	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: INBOARD STRAP PIN								
NO: 204-012-104-5	PB-7793	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: OUTBOARD STRAP PIN								
NO: 204-012-104-5	PB-6881	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: OUTBOARD STRAP PIN								
NO: 204-012-104-5	DI-3786	2358:30	00:00	-	4625:10	2266:40	-	2400
NAME: PITCH HORN								
NO: 204-011-120-5	RE-2378	2358:30	00:00	-	5349.00	2990.30 (Timex)		3000

HISTORICAL SERVICE RECORD

COMPONENT NAME M/R HUB ASSEMBLY
 PART NUMBER 204-012-101-29 G
 SERIAL NUMBER ADA-01007
 PAGE 1 OF

NOTICE: WHEN COMPONENT IDENTIFIED
 BELOW IS RETURNED TO BHT. FOR ANY
 REASON IT IS MANDATORY THAT THIS SERVICE
 RECORD ACCOMPANY THE COMPONENT

SERIAL NUMBER

PAGE 1 OF

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS.		DATE	REMOVED AT A/C HRS.	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
2-21-80	32123	BHT	0.0	0.0	0.0	30/1/82	47.55	47.55	-	Tension/Torsion Straps Time Ex.-Cal.
2.5.82	30651	ADH	3272.20	47.55	-	15.6.83	4174.45	950.20	-	With U/S Blade
3.7.83	30783	ADH	5782.45	950.20	-	14.10.83	6004.30	1172.05	-	Grip Seals Leaking
23.10.83	30777	ADH	9862.05	1172.05	-	23.7.84	11048.30	2358.30	-	Retention Straps Timex & Overhaul
19.9.84	30777	ADH	11341.30	2358:30	00:00	20.9.84	11342.20	2359.20	0.50	Unable to track
21.9.84	30776	ADH	12422.05	2359.20	0.50	21.6.85	13537.50	3475.05	1116.35	Yoke + others Time-
14.7.85	32123	ADH	5260.10	3475.05	1116.35	18.11.85	5748.50	3963.45	1605.15	Lateral Vibration.
18.11.85	30903	ADH	10552.15	3963.45	1605.15	6.4.86	11133.45	4545.15	2186.45	To Service 30822
6.4.86	30822	ADH	6645.45	4545.15	2186.45	1.5.86	6725.40	4625.10	2266.40	Due Overhaul.
25.10.86	30779	ADH	12312.55	4625:10	00:00	10.8.87	13512.10	5824.25	1199.15	T/T Straps Timex

UNION DIRECTIVES AND HISTORY OF OVERHAUL

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
W/S No.89/82		Static Balance check carried out after trunnion change. TT 47.55	ADH	2.22.82
		Overhauled in accordance with Bell Component Repair and Overhaul Manual	Fas Orient	28 Aug 84
		T.T. 2358:30 , T.S.O. 00:00 (Job No. S68078).	(Pte.) Ltd.	
		T.B. 212-78-11, T.B. 212-81-56'A', ASB 212-80-17, ASB 212-81-23 and F.A.A.	Singapore.	
		A.D. 79-20-05 Amendment 39-3662 complied with.		
W/S 265/85		NOTE : Assembly serviced with Aeroshell Grease 22C.		
		ASB.212-85-37 "A" Complied with. Grip S/Ns. GD.9456-11/GD.9449-3 TT 29	1.50 ADH	13.2.85
		Overhauled in accordance with Bell Component Repair and Overhaul Manual	Fas Orient	3 Oct '86
		T.T. - 4625:10, T.S.O. - 00:00 (Job No. 210046-2101).	(Pte) Ltd.,	
		T.B. 212-78-11, ASB 212-80-17, ASB 212-85-37'A', ADHM/212/85/36, OSN 212-85-13	Singapore Fas	
		and T.B. 212-86-94 complied with.		
		Hub Assembly serviced with Aeroshell Grease 22C.		

COMPONENT ASSY. OR PART	SERIAL NUMBERS	INSTALLATION DATA			REMOVAL DATA			SCHEDULED REMOVAL AIRCRAFT (HRS)
		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		TOTAL Assembly TIME (HRS)	ACCUMULATED TIME ON PART		
			SINCE NEW (HRS)	SINCE OVERHAUL (HRS)		SINCE NEW (HRS)	SINCE OVERHAUL (HRS)	
NAME: INBD STRAP FITTING								
NO: 212-010-103-7	A1-05973	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: INBD STRAP FITTING								
NO: 212-010-103-7	A1-05926	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: OUTBD STRAP FITTING								
NO: 204-012-103-5	A1-27855	0.0	0.0	0.0	3475.05	3475.05	(Timex)	3600
NAME: OUTBD STRAP FITTING								
NO: 204-012-103-5	A1-29004	0.0	0.0	0.0	3475.05	3475.05	(Timex)	3600
NAME: RETENTION STRAP								
NO: 204-012-122-5	2452	0.0	0.0	0.0	47.55	47.55	Time Ex Calendar	1200/2 Years
NAME: RETENTION STRAP								
NO: 204-012-122-5	2558	0.0	0.0	0.0	47.55	47.55	Time Ex Calendar	1200/2 Years
NAME: STRAP PIN								
NO: 204-012-104-5	VT2171	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	VT1970	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	VT2118	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: STRAP PIN								
NO: 204-012-104-5	VT1130	0.0	0.0	0.0	2358:30	2358:30	-	2400
NAME: PITCH HORN								
NO: 204-011-120-5	RE1329	0.0	0.0	0.0	2358:30	2358:30	-	3000
NAME: PITCH HORN								
NO: 204-011-120-5	RE0720	0.0	0.0	0.0	2358:30	2358:30	-	3000
NAME: YOKE								
NO: 204-011-102-125	GD 9020-5	0.0	0.0	0.0	3475.05	3475.05	(Timex)	3600
NAME: Trunnion								
NO: 204-011-105-1	A1-09691	0.0	0.0	0.0	47.55	47.55	Eccentric	

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
W/S OH 419		Overhauled to zero time. TSN 2367.75	ADA	270499
ASB 212-94-94	2596.33	1200 Hr/24 Month Inspection Carried Out.	ADA WS OH 6231R	29Mar01
	3212.92	Overhauled with MR Hub S/N ADA-01007.	WS OH-722/O	23FEB03
	4284.92	1200 HRS./24 MTHS. INSP. C/O.	WS OH8935-R	06 AUG.04
	5247.67	Overhauled with MR Hub S/N ADA-01007 @ TSN 17022.42	WS OH-10697-O	26Mar06
	6259.25	1200Hrs/24Mth insp. c/out.	WS OH-12818R	13Apr03
	6766.25	1200hr/24mth inspection c/out.	WS OH 14258R	20jul09
	6926.42	1200Hr/24Mth insp c/out.	WS OH-15643-R	27jul11
AD 2012-17-08		MR Yoke 204-011-102-XXX. N/A by P/N installed. J/N. MRY-11713 refers.	ADA WS OH 18406R	5-3-13
ASB 212-94-94	7087.40	1200 HR INSPECTION C/OUT.	ADA WS OH 18406R	REMARKS
	7572.45	OVERHAULED IAW BHT-212-CR 80 REV.10.	OH 21464-O	03 OCT 18

HISTORICAL SERVICE RECORD

INSTALLED M/R HUB ASSY S/N: ADA-01007

$$\text{Rin Factor} = (\text{Flights} \times 5) + (\text{Lifts} \times 5)$$

INSTALLATION DATA						LIFE LIMITS	REMOVAL DATA				
DATE	FITTED ON A/C REG	BY (ACTIVITY)	INSTALLED AT		COMPONENT TSN / RIN	SCHEDULED RETIREMENT	DATE	REMOVED AT		COMPONENT TSN / RIN	REASON FOR REMOVAL
			A/C T.A.T.		COMP' TSN	COMP' TSN		A/C T.A.T.		COMP' TSN	
			FLIGHTS	LIFTS	COMP' RIN	COMP' RIN		FLIGHTS	LIFTS	COMP' RIN	
15-Apr-12	P2-HFV (A6-BAC)	HELIFIX	15066.20 26631 4108		3715.42 123305	15000 300000	19-Sep-12	15224.00 27095 4131		3873.22 125740	With M/R Hub Assy
19-Sep-12	P2-HFP (A6-BBW)	HELIFIX	18028.90 37573 2315		3873.22 125740	" "	22-Jan-13	18030.00 37582 2315		3874.32 125785	With M/R Hub Assy
22-Jan-13	P2-HFV (A6-BAC)	HELIFIX	15224.00 27095 4131		3874.32 125785	" "	11-Feb-15	15224.42 27100 4131		3874.74 125810	With M/R Hub Assy
16-Mar-15	A6-BAC	ADA	15228.58 27120 4131		3874.74 125810	" "	5-Apr-18	15713.67 28280 6727		4359.83 144590	With M/R Hub Assy
22-Jan-19	A6-BBV	ADA	19590.75 47212 15321		4359.83 144590	" "	22-Jan-21	19621.17 47371 15321		4390.25 145385	With M/R Hub Assy

HISTORY OF INSPECTION, OVERHAUL, REPAIR, AND COMPLIANCE WITH SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS ETC

DATE	COMP' TSN / RIN	DESCRIPTION OF WORK CARRIED OUT	SIGNATURE	AUTH.

COMPONENT: TRUNNION
 PART NUMBER: 204-011-105-001
 SERIAL NUMBER: AFS-2695
 PAGE: 1 of

HISTORICAL SERVICE RECORD

INSTALLED M/R HUB ASSY S/N: ADA-01007

Rin Factor = (Flights x 5) + (Lifts x 5)

INSTALLATION DATA						LIFE LIMITS	REMOVAL DATA				
DATE	FITTED ON A/C REG	BY (ACTIVITY)	INSTALLED AT		COMPONENT TSN / RIN	SCHEDULED RETIREMENT	DATE	REMOVED AT		COMPONENT TSN / RIN	REASON FOR REMOVAL
			A/C T.A.T.		COMP' TSN	COMP' TSN		A/C T.A.T.		COMP' TSN	
			FLIGHTS	LIFTS	COMP' RIN	COMP' RIN		FLIGHTS	LIFTS	COMP' RIN	
28-Mar-03	A6-BBA	ADA	24343.67		0.00	15000	14-Nov-03	24562.17		218.50	With M/R Hub Assy
			28747	1676	0	300000		29081	3273	9655	
14-Nov-03	A6-BAB	ADA	15949.75		218.50	"	03-Mar-04	16523.33		792.08	With M/R Hub Assy
			29052	1850	9655	"		32111	6889	50145	
10-Apr-04	A6-BBS	ADA	20140.75		792.08	"	05-Aug-04	20420.67		1072.00	With M/R Hub Assy
			21693	509	50145	"		22394	521	53710	
07-Aug-04	A6-BBS	ADA	20420.67		1072.00	"	31-Dec-04	20739.67		1391.00	With M/R Hub Assy
			22394	521	53710	"		23241	589	58285	
31-Jan-05	EP-NAG	ADA	15254.50		1391.00	"	30-Oct-05	15850.67		1987.17	With M/R Hub Assy
			29401	836	58285	"		30816	836	65360	
02-Nov-05	A6-BBC	ADA	30149.92		1987.17	"	18-Feb-06	30197.50		2034.75	With M/R Hub Assy
			25865	6149	65360	"		26098	6245	67005	
29-Mar-06	A6-BBC	ADA	30200.67		2034.75	"	24-Jun-07	30720.42		2554.50	With M/R Hub Assy
			26121	6245	67005	"		28044	9865	94720	
10-Jul-07	A6-BBC	ADA	30720.42		2554.50	"	21-Mar-08	31212.25		3046.33	With M/R Hub Assy
			28044	9865	94720	"		30148	10032	106075	
23-May-08	A6-BBL	ADA	24326.17		3046.33	"	30-Jun-09	24833.17		3553.33	With M/R Hub Assy
			57448	3470	106075	"		59482	3911	118450	
29-Aug-09	A6-BBC	ADA	31769.83		3553.33	"	12-Apr-11	31930.00		3713.50	With M/R Hub Assy
			33234	12104	118450	"		33988	12295	123175	
27-Jul-11	Ag-BBS	ADA	24362.67		3713.50	"	31-Jul-11	24364.58		3715.41	With M/R Hub Assy
			34874	2214	123175	"		34900	2214	123305	
HISTORY OF INSPECTION, OVERHAUL, REPAIR, AND COMPLIANCE WITH SERVICE BULLETINS, AIRWORTHINESS DIRECTIVES, TECHNICAL BULLETINS ETC											
DATE	COMP' TSN / RIN		DESCRIPTION OF WORK CARRIED OUT							SIGNATURE	AUTH.
23-Feb-03	0.00	0	Installed on MRH ADA-01007 @ 14987.67 MRH TSN.							OH 722/0	OH 01

NOMENCLATURE FITTING ASSY
 PART NUMBER 212-010-103-007 FM
 SERIAL NUMBER A-008995
 PAGE 1 OF 1

Bell Helicopter
 A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

ANW 30990

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		- REMOVAL DATA					
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN		COMP. HRS.	☐ INSP ☐ O / H ☒ RET 2400	DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL		
				SINCE NEW	SINCE O/H					SINCE NEW	SINCE O/H			
			A/C HOURS	HRS COMP. HRS	HRS COMP. HRS	HRS				HRS				
			A/C RIN	RIN	RIN	RIN				RIN				
20Jul09	ADA-01007	OH 14258R	18541.00	0.0	NEW	RT 2400 NR	31/07/11	24364.6	18703.1	162.1	Vibration Removed with the head.			
15/04/12	R-HFV	HELIFIX	15066.3	162.1	NEW	17304.2								

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	NO. CERT. NO	DATE
160.17	ASB 212-10-142 Rev.B (FASA AD 2010-0246R1 and FAA AD 2011-08-01) C/with.	WS CH 15643-R	CH 11	27Jul11
	AD-2013-03-16 ONE TIME INSB FIT MPI, MPI PCW ON ADA JIN	DAVID COOPER		
	WS-CH 15643-R 27-JUL-2011. HELIFIX JOBS TL-6953	HEL AUTH#H1	H1	14/2/13
321:25	ASB 212-10-142 REB PT.1 COMPLIED WITH; FAA AD 2013-03-16 C/with	WS CH 18406R	CH-11	05MAR15
806:30	ASB 212-10-142 Rev.B Part 1 & 2 C/W, FAA AD 2013-03-16 C/W	CH 21464-0	CH-06	03 OCT 18

NOMENCLATURE FITTING ASSY
 PART NUMBER 212-010-103-007 FM
 SERIAL NUMBER A-008960
 PAGE 1 OF 1

Bell Helicopter
 A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

CRW 30190

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		-- REMOVAL DATA					
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN		COMP. HRS.	☐ INSP ☐ O/H ☒ RET	DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL		
				SINCE NEW HRS COMP. HRS	SINCE O/H HRS COMP. HRS					SINCE NEW HRS	SINCE O/H HRS			
			A/C HOURS											
			A/C RIN	RIN	RIN	RIN				RIN	RIN		RIN	RIN
20jul09	ADA-01007	OH 14258R	18541.00	0.0	NEW	RT 2400 HR		30/07/11	24364.6	18703.1	162.1	(Vibration)		
				0.0	NEW									
15/04/12	P2-HEV	HELIFIX	15066.3	162.1	NEW	17804.2								

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	NO. CERT. NO	DATE
160.17	ASB 212-10-142 Rev B (EASA AD 2010-0246R1 and FAA AD 2011-08-11) C/w/with.	WS OH 15643-R	OH 11	27Jul11
	AD-2013-03-16, ONE TIME MPI, MPI PCW ON ADA JIN WS OH 15643-R	DAVID COOPER		
	27 JULY 2011. HELIFIX JIN TL-6953 NFAAR	HEL AUTH #H1 H1		14/2/13
321.25	ASB 212-10-142 REV B PART. 1 C/W/with, FAA AD 2013-03-16 C/W/with	WS OH 18406 R	OH-11	05 MAR 15
806.30	ASB 212-10-142 REV. B Part 1 & 2 C/w, FAA AD 2013-03-16 C/w	OH 21464-0	OH-06	03 OCT 18

Page 1 Of 1

Bell *helicopter*

A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

31577

OUT B.

NOMENCLATURE FITTING
 PART NUMBER 204-012-103-005
 SERIAL NUMBER A-017749
 PAGE 1 OF 1



A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		- REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT	COMPONENT HOURS/RIN		COMP. HRS	☐ INSP ☐ O/H ☒ RET	DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL	
				SINCE NEW	SINCE O/H					SINCE NEW	SINCE O/H		
				HRS COMP. HRS	HRS COMP. HRS					HRS	HRS		
				A/C HOURS	RIN	RIN			A/C HOURS	RIN	RIN		
13Apr08	MRH ADA-01007	OH-12818R	18034.00	0.0	NEW	3600 HRS		27.07.11	18703.1	669.1	NEW	Removed with N/A Head	
15.04.12	B-HFV ADA-01007	Helifix	15066.3	669.1	NEW	17797.2							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE



Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

CARN: 100999

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

7861 5671REV994

Page 1 Of 1



Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

[illegible]

Refer to applicable regulatory agency directives and Section 4 of the Maintenance Manual for RIN Accumulation Instructions (Model 204 refer to section 1)

7861 5671REV994

NOMENCLATURE PIN ASSY
 PART NUMBER 204-012-104-005
 SERIAL NUMBER DIFS 20552
 PAGE 1 OF 1



NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		- REMOVAL DATA			
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH	COMPONENT HOURS/RIN		COMP. HRS.	☐ INSP ☐ O/H ☒ RET	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL
				SINCE NEW HRS COMP. HRS	SINCE O/H HRS COMP. HRS					SINCE NEW	SINCE O/H	
				A/C HOURS	A/C RIN					HRS	HRS	
				A/C RIN	RIN					RIN	RIN	
03 OCT 18	A04-01007	OH-21464-0	19347.29	0.0	NEW	2400H RET						
				0.0	NEW							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

NOMENCLATURE PIN ASSY
 PART NUMBER 204-012-104-005
 SERIAL NUMBER DIFS 20711
 PAGE 1 OF 1

Bell Helicopter
 A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		- REMOVAL DATA			
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY) MRH	INSTALLED AT MRH	COMPONENT HOURS/RIN			COMP. HRS. RIN	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL
				SINCE NEW HRS COMP. HRS	SINCE O/H HRS COMP. HRS	SINCE NEW HRS				SINCE O/H HRS		
				A/C HOURS A/C RIN	RIN	RIN				RIN		
03 Oct 18	ADA-01007	OH-21464-0	19347.29	0.0	NEW	2400H RET						
				0.0	NEW							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

NOMENCLATURE PIN ASSY
 PART NUMBER 204-012-104-005
 SERIAL NUMBER DIFS 20900
 PAGE 1 OF 1

Bell Helicopter
 A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED		- REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY) MRH	INSTALLED AT MRH	COMPONENT HOURS/RIN		COMP HRS	RIN	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL
				SINCE NEW HRS HRS RIN	SINCE O/H HRS HRS RIN					SINCE NEW HRS RIN	SINCE O/H HRS RIN	
03 OCT 18	ADA-01007	UH-21464-0	19347.29	0.0	NEW	2400HRS	RET					
				0.0	NEW							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	NO. CERT. NO	DATE

Boeing Helicopter
A Textron Company
Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

[illegible]

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

[illegible]

NOMENCLATURE PITCH HORN ASSY
 PART NUMBER 204-011-120-005
 SERIAL NUMBER REFS 3542
 PAGE 1 OF 1



NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		- REMOVAL DATA			
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH	COMPONENT HOURS/RIN		COMP. HRS. RIN	☐ INSP ☐ O/H ☐ RET	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL
			A/C HOURS A/C RIN	SINCE NEW HRS COMP. HRS	SINCE O/H HRS COMP. HRS				A/C HOURS A/C RIN	SINCE NEW HRS	SINCE O/H HRS	
				RIN	RIN					RIN	RIN	
03 OCT 18	ADA-01007	OH-21464-0	19347-29	0.0	NEW	3000HR RET						
				0.0	NEW							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

NOMENCLATURE PITCH HORN ASSY
 PART NUMBER 204-011-120-005
 SERIAL NUMBER REFS 3546
 PAGE 1 OF 1

Bell Helicopter

A Textron Company
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	- REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH	COMPONENT HOURS/RIN		COMP. HRS. RIN	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL
			A/C HOURS A/C RIN	SINCE NEW HRS COMP. HRS	SINCE O/H HRS COMP. HRS			SINCE NEW HRS	SINCE O/H HRS		
				RIN	RIN				RIN	RIN	
03 OCT 18	ADA- 01007	04- 21464-0	19347.29	0.0	NEW	3000H RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE AFFIRMS WORK PERFORMED IN ACCORDANCE WITH APPLICABLE AIRWORTHINESS STANDARD		
		SIGNATURE	NO. CERT. NO	DATE

NOMENCLATURE BUSHING
 PART NUMBER 204-011-135-105
 SERIAL NUMBER DI 22182
 PAGE 1 OF 1

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc.
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA							- REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY) MRH	INSTALLED AT	COMPONENT HOURS/RIN		COMP. HRS.	DATE	REMOVED AT	COMP. HRS/RIN		REASON FOR REMOVAL
			MRH	SINCE NEW	SINCE O/H			MRH	SINCE NEW	SINCE O/H	
				HRS COMP.	HRS COMP.				HRS	HRS	
				HRS	HRS				RIN	RIN	
03 Oct 18	ADA-01007	OH-21464-0	19247.29	0.0	NEW	3600HR RET					
				0.0	NEW						

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	NO. CERT. NO	DATE

NOMENCLATURE BUSHING
 PART NUMBER 204-011-135-105
 SERIAL NUMBER D 7 21833
 PAGE 1 OF 1

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc.
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA						NEXT SCHEDULED ☐ INSP ☐ O/H ☐ RET	- REMOVAL DATA					
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY) OH	INSTALLED AT MRH	COMPONENT HOURS/RIN			COMP. HRS.	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL
			A/C HOURS A/C RIN	SINCE NEW HRS COMP. HRS	SINCE O/H HRS COMP. HRS				SINCE NEW HRS	SINCE O/H HRS		
				RIN	RIN					RIN	RIN	
03 OCT 18	ADA-01007	21464-0	19347.29	0.0	NEW	3600H RET						
				0.0	NEW							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	NO. CERT. NO	DATE

NOMENCLATURE BUSHING
 PART NUMBER 204-011-135-105
 SERIAL NUMBER D I 22185
 PAGE 1 OF 1

Bell Helicopter TEXTRON
 A Subsidiary of Textron Inc.
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTC/BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		- REMOVAL DATA			
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY)	INSTALLED AT MRH	COMPONENT HOURS/RIN		COMP. HRS.	☐ INSP ☐ O/H ☐ RET	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H					SINCE NEW	SINCE O/H	
				HRS COMP.	HRS COMP.					HRS	HRS	
				A/C HOURS	A/C RIN					A/C HOURS	A/C RIN	
03 OCT 18	ADA-01007	OH-21464-D	19347.29	0.0	NEW	3600H RET						
				0.0	NEW							

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	NO. CERT. NO	DATE

NOMENCLATURE BUSHING
 PART NUMBER 204-011-135-105
 SERIAL NUMBER DI 22279
 PAGE 1 OF 1

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc.
 Post Office Box 482, Fort Worth Texas 78101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO
 BHTC/BHTI FOR ANY REASON IT
 IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD
 ACCOMPANY THE COMPONENT

HISTORICAL SERVICE RECORD

INSTALLATION DATA							NEXT SCHEDULED		- REMOVAL DATA				
DATE	INSTALLED ON A/C NO. MRH	BY (ACTIVITY) MRH	INSTALLED AT MRH	COMPONENT HOURS/RIN		COMP. HRS. RIN	☐ INSP ☐ O/H ☐ RET	DATE	REMOVED AT MRH	COMP. HRS/RIN		REASON FOR REMOVAL	
				SINCE NEW	SINCE O/H					SINCE NEW	SINCE O/H		
				HRS COMP.	HRS COMP.								
				HRS	HRS								
A/C HOURS		A/C HOURS		A/C HOURS		A/C HOURS		A/C HOURS		A/C HOURS			
A/C RIN		A/C RIN		A/C RIN		A/C RIN		A/C RIN		A/C RIN			
03 Oct 18	ADA-01007	OH-21464-0	19347-29	0.0	NEW	360CHR RET							
				0.0	NEW								

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ECT.

COMPONENT TOTAL TIME / RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY		
		SIGNATURE	NO. CERT. NO	DATE

COMPONENT NAME DRAG BRACE ASSY
 PART NUMBER 204-011-140-005
 SERIAL NUMBER A-350
 PAGE 2 OF

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A / C NO. MR HUB	BY (ACTIVITY)	INSTALLED AT A / C HRS. MR HUB	COMP. HRS.			DATE	REMOVED AT A / C HRS. MR HUB	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O / H				SINCE NEW	SINCE O / H	
16JUN01	ADA-01072	ADA	15005.00	7004.08	0.00	ON COND	07JUL14	20539:55	12539:00	2108:45	ROBBERY 0417900-0
11MAR15	ADA-01007	OH- 18406 R	18862:24	12539:00	0.0						

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
	10430.25	Overhauled iaw BHT 212 CR&O Chapter 62, Rev. No. 6	ADA OH1065-0	27JUN06
AD 90-26-11	11017.17	1200hr/24 mth inspection c/out. AD 90-26-11 complied with.	WS OH12871-R	16Apr08
	11215.00	1200 Hrs/24 Mths Inspection c/out. AD 90-26-11 (ASB 212-90-59) complied with. MPI Inspection c/out.	OH 14198-R	17Nov09
	11402.83	1200Hrs/24Mth insp c/out. FAA AD 90-26-11 (ASB 212-90-59) c/with.	WS OH 16148-R	20Mar12
	12539:00	OVERHAULED IAW BHT 212 CR&O REV.10	WS OH-17900-0	05MAR15
AD 90-26-11			WS- OH	
(ASB 212-90-59)	12539:00	COMPLIED WITH.	18406 R	05MAR15
	13024:05	OVERHAULED IAW BHT-212 CR&O REV.10, ASB 212-90-59 (AD 90-26-11) c/w	OH 21464-0	03OCT18

COMPONENT NAME BRACE ASSY
 PART NUMBER 204-011-140-5
 SERIAL NUMBER A.350
 PAGE 1 OF 1

HISTORICAL SERVICE RECORD

NOTICE: WHEN COMPONENT IDENTIFIED
 BELOW IS RETURNED TO BHT. FOR ANY
 REASON IT IS MANDATORY THAT THIS SERVICE
 RECORD ACCOMPANY THE COMPONENT

INSTALLATION DATA						REMOVAL DATA				
DATE	INSTALLED ON THE NO. <i>ASSY</i>	BY (ACTIVITY)	INSTALLED AT THE HRS. <i>ASSY</i>	COMP. HRS.		DATE	REMOVED AT THE HRS. <i>ASSY</i>	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O/H			SINCE NEW	SINCE O/H	
19.11.85	ADA 08543	FAS Singapore	8115:15	NEW	NEW	24.10.89	10338:05	2222:50	2222:50	AT OVERHAUL.
24.10.89	ADA 08543	Dowty Singapore	10338:05	2222:50	00:00		12720:55	4605:40	2382:50	@ OVERHAUL.
19.8.95	ADA-01072	ADA	12606.58	4605.67	0.0	110796	13802.17	5801.25	1195.58	Hub overhaul
111196	ADA-01072	ADA	13802.17	5801.25	0.0	120297	13836.17	5835.25	34.00	Overtorque
310397	ADA-01072	ADA	13836.17	5835.25	0.0	050499	14144.08	6143.17	307.92	TT Straps Timex
150499	ADA-01072	ADA	14144.08	6143.17	0.0	130601	15005.00	7004.08	860.92	Hub T/T Straps Timex
160601	ADA-01072	ADA	15005.00	7004.08	0.0	CLOSED - TRANSFERRED TO CARD NO. 2				

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
		Fitted <u>new</u> to Main Rotor Hub Assembly S/N ADA-08543 at Hub T.T. 8115:15, T.S.O. - 00:00 (Job No. 10/15129).	Fas Orient (Pte) Ltd. Singapore.	19/11/85
		Overhauled and <u>re-fitted</u> to Main Rotor Hub Assembly S/N ADA-08543 at Hub T.T. 10338:05 T.S.O. 00:00 (Job No. 211685-2101)	Dowty Avia. Svcs Pte Ltd. Singapore.	24 Oct'89
ASB-212-90-59		Overhauled to zero time IAW BHT 212 CR & O Manual TSN 5801.25 w/s OH 295	ADA	111196
		Overhauled with MRH ADA-01072 @ MRH TT 13836.17	ADA OH-3749	11Mar97
		Overhauled with MRH ADA-07072 @ MRH TT 14144.08	ADA OH-5022R	15Apr99
WS OH 6418R		1200 Hr Insp C/O IAW ASB 212-90-59 TSN 7004.08	ADA	160601

WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L No.	GRN No.

[illegible][illegible]

COMPONENT NAME DRAG BRACE ASSY
 PART NUMBER 204-011-140-005
 SERIAL NUMBER A1-07403
 PAGE 1 OF

Bell Helicopter **TEXTRON**
 A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

LOG CARD RAISED 21-1-91

INSTALLATION DATA						A/C HOURS SCH. FOR ☒ O/H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO. <i>AS4</i>	BY (ACTIVITY)	INSTALLED AT A/C HRS. <i>AS4</i>	COMP. HRS.			DATE	REMOVED AT A/C HRS. <i>AS4</i>	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE OH <i>AS4</i>				SINCE NEW	SINCE OH <i>AS4</i>	
21-1-91	ADA 53533	DONTY SINGAPORE	10349:20	NK	NIL		22-2-91	11941:00	NK	1591:40	AD 99/26/11 REMOVED
13-10-91	ADA 08524	ADA	12364:35	NK	00:00			13559.41	NK	1194.83	DUE INSP/OH
19-8-95	ADA-01072	ADA	12606:58	NK	00:00		060796	13802.17	NK	1195.58	Hub O/Haul
111196	ADA-01072	ADA	13802.17	NK	0.0		120297	13836.17	NK	34.00	Overtorque
310397	ADA-01072	ADA	13836.17	NK	0.0		050499	14144.08	NK	307.92	TT Straps Timex
150499	ADA-01072	ADA	14144.08	NK	0.0		130601	15005.00	NK	860.92	Hub T/T Straps Timex
160601	ADA-01072	ADA	15005.00	NK	0.0	ONCD	CONT... CARD 2				

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
ASB 212-90-59		Drag brace inspection.	ADA/WS 910191	91092
ADA WS 911335		Fitted to MRH S/N ADA-08524 at assy TT 12364:35.		
		Drag brace TSN NK, TSO 0:0	ADA/EBP	131091
ASB 212-90-59		OVERHAULED I.A.W. COMPONENT REPAIR & OVERHAUL MANUAL BHT-212-CR&O @ T.S.N.	ABU DHABI	240494/89
		NK, T.S.O. 00.00 (JOB NO. OH 1024)	AVIATION	OH 001
W/S OH 295		Overhauled to zero time IAW BHT 212 CR & O Manual TSN NK	ADA	111196
		Overhauled with MRH ADA-01072 @ MRH TT 13836.17	ADA OH-3749	11Mar97
		Overhauled with MRH ADA-01072 @ MRH TT 14144.08	ADA OH-5022R	15Apr99
WS OH 6418R		1200 Hr Insp. C/O IAW ASB.212-90-59 TSN NK	ADA	160601
WS OH-9625-R	TSN NK	1200 HR/ 24 MTH INSPECTION CARRIED OUT.	ADA	17MAR05
	TSN NK	Overhauled IAW BHT 212 CR & O, Chapter 62, Rev. No. 6	ADA OH11065-0	27JUN06
AD 9026-11	TSO 586.92	1200hr/ 24 mth inspection c/out. AD 90-26-11 complied with.	WS OH 12871-R	16Apr08

COMPONENT NAME

PILLOW BLOCK

PART NUMBER 204-011-108-113 FM

SERIAL NUMBER 30777040493B

PAGE 1 OF 1

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

[illegible]

[illegible]

ABU DHABI AVIATION **ACCESSORY AND COMPONENT SERVICE RECORD**

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES

WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L NO.	

NOMENCLATURE	M/R GRIP ASSY	PART NO.	204-011-121-121G	SERIAL NO.	A-6014
MANUFACTURER	CARD # 2	RETIREMENT TIME (If Applicable)	25,000 HOURS	OVERHAUL INTERVAL	2400 HOURS

INSTALLATION DATA							REMOVAL DATA				
DATE	INSTALLED ON ACFT/EQUIP		BY	TOTAL HRS/LDS	COMP. HOURS/LDGS		DATE	TOTAL HRS/LDS	COMP. HOURS/LDGS		REASON FOR REMOVAL
	TYPE	ACFT/EQUIP		ACFT/EQUIP	SINCE NEW	SINCE O/H		ACFT/EQUIP	SINCE NEW	SINCE O/H	

TECHNICAL DIRECTIVES				
TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DATE	DONE BY
FAA AD 2014-12-04 PARA 2		Complied with	5-Mar-15	WS OH18406-R
FAA AD 2014-12-04 PARA 3		Complied with	5-Mar-15	WS OH18406-R
FAA AD 2014-12-04 PARA 4		Complied with	5-Mar-15	WS OH18406-R
ASB 212-02-116 REV A		Complied with	5-Mar-15	WS OH18406-R
ASB 212-12-144		Complied with	5-Mar-15	WS OH18406-R
ASB 212-94-92 REV A		Complied with	5-Mar-15	WS OH18406-R
ASB 212-12-144		Complied with	5-Mar-15	WS OH18406-R
FAA AD 2014-12-04 PARA 4 & PARA 3		COMPLIED WITH	03 APR 17	BAC-000228/0016
	4917:55	FAA 2014-12-04 PARA 2, 3, 4 & 5 COMPLIED WITH.	03 OCT 18	OH 21464-0

COMPONENT NAME M/R GRIP ASSY
 PART NUMBER 204-011-121-121G
 SERIAL NUMBER A-006014
 PAGE 1 OF

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

	GRN 14830

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON M/R HUB Serial No.	BY (ACTIVITY)	INSTALLED AT Assy Hours	COMP. HRS.			DATE	REMOVED AT Assy Hours	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O / H				SINCE NEW	SINCE O / H	
230101	ADA-01007	ADA	14370.58	NIL	NEW	25000 HA RT					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
AD 2003-01-04		(M/R GRIP) COMPLIED WITH .	TS 212/014	190103
	618.08	1200hr/24mth inspection c/o @MRH TSN 14987.67. ASB 212-02-116 AND AD 2003-01-04 c/o.	WS OH 722/O	23FEB03
ASB 212-02-116 Rev A	835.58	ASB 212-02-116 Rev A Complied With Prior to Installation to A6-BAB. M 004	WS 600/3AB03	13Nov03
	1689.08	ASB 212-02-116 C/W. - 1200 HRS/24 MTHS. INSP. CARRIED OUT.	WS OH 8935-R	06AUG.04
	2008.08	ULTRASONIC INSP. C/OUT (ASB212-02-116 REV.A).	ADA WS OH9441-R	15JAN05
ASB 212-02-116 Rev.A	2652.83	Ultrasonic insp.c/out (ASB212-02-116 Rev.A) and NDT Insp c/out. 1200hr/24Mth Insp. c/out.	WS OH 10697-O	28Mar06
AD 2003-01-04PtC	3171.58	Ultrasonic insp. c/out. (ASB 212-02-116RevA.)	WS CH 11995-R	27Jun07
AD 2003-01-04 Pt D	3664.42	1200Hrs/24Mth insp. c/out. AD 2003-01-04 (ASB 212-02-116 Rev.A) c/out.	WS OH-12818R	13Apr08
AD 2003-01-04 &	4171.42	1200hr/24mth insp.c/out. AD 2003-01-04 Pt.C c/with.	WS OH 14258R	20Jul09
ASB 212-94-92 Rev A		ASB 212-94-92 Rev A complied with.	WS OH 14258-R	20Jul09
ASB 212-94-92 Rev A	4331.58	FAA AD 2003-01-04 (ASB 212-02-116 Rev.A) C/W. 1200Hr/24Mth Insp c/out.	WS OH15643-R	27Jul11

ABU DHABI AVIATION ACCESSORY AND COMPONENT SERVICE RECORD

THIS RECORD MUST ACCOMPANY THE ITEM AT ALL TIMES
WHEN THE ITEM IS INSTALLED, THE RECORD THEN BECOMES PART OF THE COMPONENT LOG BOOK

	OVERHAUL/TIMEX
P/L NO.	

NOMENCLATURE							M/R GRIP ASSY		PART NO.		204-011-121-121G		SERIAL NO.		A-6015	
MANUFACTURER							CARD # 2		RETIREMENT TIME (If Applicable)		25,000 HOURS		OVERHAUL INTERVAL		2400 HOURS	
INSTALLATION DATA							REMOVAL DATA									
DATE	INSTALLED ON ACFT/EQUIP		BY	TOTAL HRS/LDS	COMP. HOURS/LDGS		DATE	TOTAL HRS/LDS	COMP. HOURS/LDGS		REASON FOR REMOVAL					
	TYPE	ACFT/EQUIP		ACFT/EQUIP	SINCE NEW	SINCE O/H		ACFT/EQUIP	SINCE NEW	SINCE O/H						

TECHNICAL DIRECTIVES				
TYPE DIRECTIVE AND NUMBER	DATE	DESCRIPTION	DATE	DONE BY
FAA AD 2014-12-04 PARA 2		Complied with	5-Mar-15	WS OH18406-R
FAA AD 2014-12-04 PARA 3		Complied with	5-Mar-15	WS OH18406-R
FAA AD 2014-12-04 PARA 4		Complied with	5-Mar-15	WS OH18406-R
ASB 212-02-116 REV A		Complied with	5-Mar-15	WS OH18406-R
ASB 212-12-144		Complied with	5-Mar-15	WS OH18406-R
ASB 212-94-92 REV A		Complied with	5-Mar-15	WS OH18406-R
ASB 212-12-144		Complied with	5-Mar-15	WS OH18406-R
FAA AD 2014-12-04 PARA 4 & PARA 3		COMPLIED WITH	03 APR 17	BAC-000228
	4977-55	FAA AD 2014-12-04 PARA 2, 3, 4 & 5 COMPLIED WITH	03 OCT 18	OH 21464-0

COMPONENT NAME M/R GRIP ASSY
 PART NUMBER 204-011-121-121G
 SERIAL NUMBER A-006015
 PAGE 1 OF

Bell Helicopter **TEXTRON**

A Subsidiary of Textron Inc.

POST OFFICE BOX 482 • FORT WORTH • TEXAS 76101

HISTORICAL SERVICE RECORD

	GRN 14830

INSTALLATION DATA						A / C HOURS SCH. FOR ☐ O / H ☐ RETIRE HRS. / DATE	REMOVAL DATA				
DATE	INSTALLED ON. M/R HUB Serial No.	BY (ACTIVITY)	INSTALLED AT Assy Hours	COMP. HRS.			DATE	REMOVED AT Assy ² Hours	COMP. HRS.		REASON FOR REMOVAL
				SINCE NEW	SINCE O / H				SINCE NEW	SINCE O / H	
230101	ADA-01007	ADA	14370.58	NIL	NEW	25000 HR. RT					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME / DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE	
			BY (ACTIVITY)	DATE
AD 2003-01-04		(M/R GRIP) COMPLIED WITH	TSN 212/014	190103
	618.08	1200hr/24mth inspection c/o @MRH TSN 14987.67. ASB 212-02-116 AND AD 2003-01-04 C/O.	WS OH 722/O	23FEB03
ASB 212-02-116 Rev A	835.58	ASB 212-02-116 Rev A Complied With Prior to Installation on A6-BAB. M 004	WS 600/3AB03	13Nov03
	1689.08	ASB 212-02-116 C/W. - 1200 HRS/24 MIHS. INSP. CARRIED OUT. -	WS OH 8935-R	06 AUG.04
	2008.08	ULTRASONIC INSPECTION C/OUT (ASB212-02-116 REV.A).	ADA WS OH9441-R	15JAN05
ASB212-02-116 Rev.A	2652.83	Ultrasonic insp. c/out (ASB 212-02-116 Rev.A) and NDT Insp. c/out. 1200hr/24Mth Insp. c/out.	WS OH-10697-O	24Mar06
AD 2003-01-04 Pt C	3171.58	Ultrasonic insp. c/out. (ASB 212-02-116 Rev.A.)	WS OH 11995-R	27Jun07
AD 2003-01-04 Pt D	3664.42	1200Hrs/24Mth insp. c/out. AD 2003-01-04 (ASB 212-02-116 Rev.A) c/out.	WS OH-12818R	13Apr08
AD 2003-01-04 &	4171.42	1200hr/24mth insp c/out. AD 2003-01-04 Pt. C c/with.	WS OH 14258R	20Jul09
ASB 212-94-92 Rev.A.		ASB 212-94-92 Rev A c/with.	WS OH 14258-R	20Jul09
ASB 212-94-92 Rev.A	4331.58	FAA AD 2003-01-04 (ASB 212-02-116 Rev.A) C/w. 1200hr/24Mth insp c/out.	WS OH-15643-R	27Jul11