Rotor Brake.

COMPONENT NAME QUILL
PART NUMBER ~~412-040-123-101~~ 412-540-014-101
SERIAL NUMBER A-98
PAGE 1 OF 1

Bell Helicopter TEXTRON
A Subsidiary of Textron Inc
POST OFFICE BOX 482 • FORT WORTH, TEXAS 76101

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT TO BHTI FOR ANY REASON IT IS MANDATORY THAT A VALID HISTORICAL SERVICE RECORD ACCOMPANY THE COMPONENT.

HISTORICAL SERVICE RECORD

2400H

INSTALLATION DATA						SCH. FOR ☑ O/H ☐ RETIRE	REMOVAL DATA				
DATE	INSTALLED ON A/C NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	HRS. / DATE	DATE	REMOVED AT A/C HRS.	COMP. HRS. SINCE NEW	COMP. HRS. SINCE O/H	REASON FOR REMOVAL
22/9/92	VH-NSP	LLOYD	3486.0	NIL	—	/	18May97	5934.6	2448.6	2448.6	Overhaul
14 Jul 98	30849 VT-NSY	LLOYD	10050.2	2448.6	0.0	/					
	33034 VH-VAH	CHC (AUST)				/	06/9/06	9962.3	2480.9	2480.9	O/H.
26.4.07	33091 VH-NSP	CHC (AUST)	10807.5	2480.9	0.0	/	~~18.02.14~~	~~14881.06~~ ~~16703:25~~ 11860.4	3533.8 ~~5356:07~~	~~4073:36~~ ~~1822:19~~ 1052.9	O/H-Leaks WP059/14 WPS 1106/14
24.09.11	VH-NSC	CHC AUST	14881:06	~~4073~~ 3533.8 ~~6982:30~~	0.0	/	18.02.14	16703:25	5356:07	1822:19	OPS CONVENIENCE
						/					
						/					

TECHNICAL DIRECTIVES AND HISTORY OF OVERHAUL

DIRECTIVE NUMBER IF APPLICABLE	TIME/DATE EFFECTIVITY	DESCRIPTION	COMPLIANCE BY (ACTIVITY)	COMPLIANCE DATE
	T.T.	Overhauled IAW Bell 412 CR+O TB 412-93-117 C/O BY LLOYD HELICOPTERS OH422	4107	24/2/98
	TT UNK	OVERHAULED IAW BELL 412 CR&O BY OVERHAUL INTERNATIONAL REF W/O OH3398	CHC 4460 4107	12/10/00
	T.T. 3533.8	OVERHAULED IAW BELL 412 CR+O BY OVERHAUL INTERNATIONAL, W/O OH4387 REFERS	CHC 4445 4107	09/08/10
	T.T 5356:07	Overhauled IAW BHT-412-CR&O Rev 8 30 Aug 13, W/O 19382. TB412-03-191 C/O: Quill Upgraded To P/N 412-540-014-101.	SH 1280	31 OCT 14
	5356:07	VISUALLY INSPECTED UNDER ALPINE AEROTECH W/O# KC055120	AAL M138 93-00	JUN 03 2024

7861 56717 REV 483